

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20003105/BRA3Q2

**Date:** 29/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

#### Claimant

**Vehicle No :** SME7570U

**Insured Vehicle No :** SMP8955D

**Date of Loss:** 13/02/2020

**Nature of Claim:** TP

**Claim No:** 7000613866SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SME7570U

**Make & Model:** TOYOTA PRIUS PLUS, 1.8 (A)

**Engine No:** 2ZR0C56893

**Reg. Date:** 16/10/2018 (Man. Year: 2018)

**Chassis No:** JTDZS3EU00J034027

**Colour:** Silver

**Odometer:** 150225 km

**Engine Capacity:** 1798 cc

**Market Value/New Car**

**Price:** N/A

**Sum Insured (\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable):

Yes

**Footbrake (Serviceable):**

Yes

**Handbrake (Serviceable):**

Yes

**Engine Modification:**

No

**Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 205/60 R16

**Rear Tyre Size:** 205/60 R16

**Front Left Side:** Goodride 6 mm

**Rear Left Side:** West Lake 6 mm

**Front Right Side:** Goodride 6 mm

**Rear Right Side:** West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,203.15	2,166.25	2,036.90	48.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	1,730.00	930.00	34.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>6,863.15</b>	<b>3,896.25</b>	<b>2,966.90</b>	<b>43.23</b>
<b>Approved Total (Overridden) (\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	6,863.15	3,100.00	3,763.15	54.83
<b>+ GST 7.00/7.00% (\$)</b>	480.42	217.00	263.42	54.83
<b>Nett Amount (\$)</b>	<b>7,343.57</b>	<b>3,317.00</b>	<b>4,026.57</b>	<b>54.83</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (\$)</b>		400.00		
<b>+ Car Rental (3.0 x S\$120.00/day) (\$)</b>		360.00		
<b>+ Doc/Search Fee (\$)</b>		29.00		
<b>Nett Liability (\$)</b>		<b>4,106.00</b>		
<b>Global Sum Settlement (\$)</b>		<b>4,100.00</b>		

### INSPECTION

**Date of Assignment:** 24/02/2020

**Date Inspected:** 24/02/2020 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)  
160 SIN MING DRIVE, #01-14 SIN  
MING AUTOCITY  
Singapore 575722

Estimated Period of Repair: 6.0 days

---

**Adjuster:** Lim Teow Guan

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	725.00 FL	*523.90 FL
2	2		*REAR BUMPER RETAINER	Necessary	189.60 FL	*189.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	423.50 FL	*350.50 FL
4	1		*REAR BUMPER REFLECTOR	Broken	201.00 FL	*81.70 FL
5	1		*REAR BUMPER LOWER	Dented	248.90 FL	*248.90 FL
6	1		*REAR BUMPER LOWER COVER	No such part	138.10 FL	*- FL
7	1		*REAR END PANEL	Not Damaged	602.10 FL	*- FL
8	1		*REAR FENDER LH	Dented	620.00 FL	*620.00 FL
9	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	523.00 FL	*- FL
10	1		*REAR FENDER INNER COWLING LH	Not Damaged	286.30 FL	*- FL
11	1		*REAR AIR VENTS	Broken	185.60 FL	*76.00 FL
12	1		*TAIL LAMP LH	Cut	624.40 FL	*624.40 FL
13	1		*TAIL LAMP LOWER BRACKET LH	No such part	36.70 FL	*- FL
14	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*REAR BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*REAR BUMPER LOWER COVER CLIPS	No such part	50.00 FS	*- FS
17	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
18	1		*FENDER SEALANT	Necessary	100.00 FS	*50.00 FS
19	1		*FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
20	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS
22	1		*TAILLAMP CLIPS	Necessary	50.00 FS	*20.00 FS
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,404.20</b>	<b>2,845.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,201.05	678.75
<b>Total Parts (\$\$)</b>	<b>4,203.15</b>	<b>2,166.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REVERSE SENSOR AN CHECK	New	80.00	60.00
2	PANEL BEAT	New	1,200.00	800.00
3	RUST PROOFING	New	80.00	40.00
4	SPRAY PAINTING	New	1,200.00	800.00
5	CHECK WIRING	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,660.00</b>	<b>1,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >