

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20003111/EPA3Q2

Date: 28/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M497634

Claimant
Vehicle No : SBV6636L

Insured Vehicle No : PC4068Z

Date of Loss: 12/02/2020

Nature of Claim: TP

Claim No: MC20202021

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBV6636L**

Make & Model: BMW 318I, 1.5 LED (A)

Engine No: 39855462B38B15A

Reg. Date: 23/11/2018 (Man. Year: 2018)

Chassis No: WBA8E32040A553373

Colour: Silver

Odometer: 27830 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R16

Rear Tyre Size: 225/55 R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,129.40	1,550.80	578.60	27.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,765.00	1,934.00	1,831.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,894.40	3,484.80	2,409.60	40.88
+ GST 7.00/7.00% (\$\$)	412.61	243.94	168.67	40.88
Nett Amount (\$\$)	6,307.01	3,728.74	2,578.27	40.88
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,916.19		

INSPECTION

Date of Assignment: 09/03/2020

Date Inspected: 09/03/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2020)
Parts:	143	BMW 318i 1.5 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBV6636L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
3	1		*FRT BUMPER TOWING LUG COVER PRIMED	Cut	43.50 FS	*43.50 FS
4	1		*FRT SHOCK ABSORBER ECE	Not Necessary	54.55 FS	*- FS
5	1		*FRT BUMPER PANEL PRIMED (BASIS)	Dented	987.65 FS	*987.65 FS
6	1		*FRT RH GRILLE (BASIS)	Cut	107.15 FS	*107.15 FS
7	1		*FRT RH GRILLE (BASIS)	Repeated	107.15 FS	*- FS
8	1		*SUPPORT NUMBER PLATE ECE	Not Necessary	69.60 FS	*- FS
9	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
10	1		*AIR DUCT RADIATOR	Not Necessary	105.35 FS	*- FS
11	1		*AIR DUCT FRT BOTTOM	Not Necessary	100.35 FS	*- FS
12	1		*PLAQUE 82MM	Not Necessary	71.60 FS	*- FS
13	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.40 FS	*20.40 FS
14	1		*SET MOUNTING PDC/PMA SENSOR FRT	Necessary	67.30 FS	*67.30 FS
15	1		*FRT LH GRILLE (BASIS)	Cut	107.15 FS	*107.15 FS
16	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **2,129.40** **1,550.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING FRONT BUMPER PANEL AND ATTACHMENT AND AIRDUCT	New	2,550.00	850.00
2	SPRAY FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			3,765.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >