

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20003112/EBA3Q2

**Date:** 23/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100087723

**Claimant**  
**Vehicle No :** SMD5529J **Insured Vehicle No :** GBB9888L

Date of Loss: 22/02/2020 Nature of Claim: TP Claim No: 3379656803SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMD5529J</b>		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ850665
Reg. Date:	24/08/2018 (Man. Year: 2018)	Chassis No:	WAUZZZGA7JA080891
Colour:	Yellow	Odometer:	18668 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,025.00	5,893.28	5,131.72	46.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,112.00	6,482.00	5,630.00	46.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>23,137.00</b>	<b>12,375.28</b>	<b>10,761.72</b>	<b>46.51</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,619.59	866.27	753.32	46.51
<b>Nett Amount (\$\$)</b>	<b>24,756.59</b>	<b>13,241.55</b>	<b>11,515.04</b>	<b>46.51</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (\$\$)</b>		700.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>13,943.55</b>		

### INSPECTION

Date of Assignment: 28/02/2020

Date Inspected: 28/02/2020 Inspected At: 281 ALEXANDRA ROAD  
Repairer: Premium Automobiles Pte Ltd (HQ)

Estimated Period of Repair: 7.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,108.00 FS	*886.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	73.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Broken	268.00 FS	*214.00 FS
4	1		*REAR LIGHT REFLECTOR -LH	Not Necessary	28.00 FS	*- FS
5	1		*TAIL LIGHT -LH	Cut	1,245.00 FS	*996.00 FS
6	1		*TAIL LIGHT TRIM -LH	Necessary	28.00 FS	*22.16 FS
7	1		*REAR BUMPER CARRIER	Not Necessary	517.00 FS	*- FS
8	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	24.00 FS	*- FS
9	2		*REAR BUMPER GUIDE SRCTION -LH/RH	Not Necessary	102.00 FS	*- FS
10	2		*REAR PARKING AIR SENSOR -OUTER /INNER (NPA)	Not Necessary	0.00 FS	*- FS
11	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
12	2		*REAR WHEEL COVER -LH/RH	Necessary	320.00 FS	*256.00 FS
13	1		*REAR LID	Dented	2,221.00 FS	*1,776.80 FS
14	2		*REAR LID HINGE	Not Necessary	280.00 FS	*- FS
15	1		*REAR LID ATTACHMENT PARTS	Not Necessary	113.00 FS	*- FS
16	1		*REAR LID LOCK STRIKER	Not Necessary	274.00 FS	*- FS
17	1		*REAR LID FLAP GASKET	Not Necessary	112.00 FS	*- FS
18	1		*REAR LID LOCK STRIKER	Not Necessary	232.00 FS	*- FS
19	1		*BONNET LOCK COVER	Not Necessary	12.00 FS	*- FS
20	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.24 FS
21	1		*AUDI EMBLEM	Necessary	117.00 FS	*93.20 FS
22	1		*Q2 INSCRIPTION	Necessary	90.00 FS	*71.76 FS
23	1		*TFSI INSCRIPTION	Necessary	90.00 FS	*71.76 FS
24	1		*SPOILER FIXING PARTS	Not Necessary	125.00 FS	*- FS
25	1		*REAR WINDSCREEN	Necessary	734.00 FS	*586.80 FS
26	1		*PRIMER	Necessary	19.00 FS	*14.80 FS
27	1		*CROSS PANEL REINFORCEMENT	Not Necessary	691.00 FS	*- FS
28	1		*REAR CROSS PANEL	Bent	231.00 FS	*184.40 FS
29	1		*REAR SILENCER	Not Necessary	667.00 FS	*- FS
30	1		*REAR SILENCER DUAL CLIP	Not Necessary	55.00 FS	*- FS
31	2		*EXHAUST SYSTEM RETAINER	Not Necessary	77.00 FS	*- FS
32	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
33	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
34	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
35	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
37	1		*SUNDRIES	Necessary	400.00 FS	*4.96 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 11,025.00 5,893.28**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM WIRE HARNESS AND TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN FOR REAR LID RENEWAL	New	480.00	480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	420.00	420.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT	New	480.00	480.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID .TO CUT OUT AND WELD END PANELLING .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	4,800.00	2,500.00
7	TO RESPRAY REAR BUMPER ,REAR LID ,HINGES ,END PANELLING AND SPARE WHEEL HOUSING	New	4,500.00	1,650.00
8	TO RENEW LHS REAR EXHAUST SILENCER TO ALIGN TO POSITON	New	480.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,112.00</b>	<b>6,482.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >