

CC6/AIG20003113/Uka3

LKK
IBAC

ASSIGNMENT
2020

Date / Time : 24/02/2020

Registered in Merimen: 24/02/2020

SG

Merimen e-Claims

汽車貿易服務

HUP MOTOR TRADING & SERVICE

9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@

Our Ref: TF 2984/02/20

Your Ref:

Date: 2

MR SOH CHIK KHON
30, Upper Serangoon View,
#07-39, Singapore 534208

o/p \$ 520 =

*not Allowed
26/2/20
o/p \$ 520. 2 days.*

Estimate cost of repair to MERCEDES BENZ CLA 180 (A) 1.6 Saloon - SLA 8606 C

1 pc front bumper		\$ 1,410.00	Nett	X
20 pcs front bumper clips	9.00 N	180.00	"	X
1 pc front bumper o/s side retainer		35.00	"	X
8 pcs front bumper rivets	9.00 N	72.00	"	X
1 pc front bumper o/s damper		34.00	"	X
1 pc o/s head lamp assy		2,610.00	"	X
		\$ 4,341.00	Nett	
		Less 10%	\$ 434.10	
		\$ 3,906.90		

To wiring check up & diagnose & re-set headlight sensor. 150.00 20

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front bumper reinforcement & necessary parts, to weld, renew & align above parts. 750.00 250

To putty & respray painting on all affected accident parts. 900.00 250
\$ 5,706.90

Dollars : Five Thousand Seven Hundred Six Dollars And Cents Ninety Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLA 8606 C
INSRS:
WSP HUP M
Tel:
Liability:
RMKS:
Date/Time:

2/3/20

16/3/20

3/1/31
OK

PRELIM

FINAL

Repair

FINAL

Final

Repair

Loss

Low

Low

LI

C