8/28/2020 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003130/KES3Q2

28/08/2020 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SHD5813Y Insured Vehicle No:

SKM162S No:

Date of Loss: 19/02/2020 Nature of Claim: ΤP 523444441SG Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD5813Y Reg No:

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR2B75418

Reg. Date: 22/11/2018 (Man. Year: 2018) Chassis No: JTDKB3FU303076860

Colour: Metallic Pearl White/Red Odometer: 150778 km

1798 cc **Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Sailun 8 mm Rear Left Side: Giti 9 mm Front Right Side: Sailun 8 mm Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
9,403.28	432.23	8,971.05	95.40
0.00	0.00	0.00	
14,170.00	320.00	13,850.00	97.74
0.00	0.00	0.00	
0.00	0.00	0.00	
23,573.28	752.23	22,821.05	96.81
1,650.13	52.66	1,597.47	96.81
25,223.41	804.89	24,418.52	96.81
x S\$50.00/day) (S\$)	100.00		
1 x S\$2.00/day) (S\$)	224.70		
oc/Search Fee (S\$)	7.49		
Nett Liability (S\$)	1,137.08		
	9,403.28 0.00 14,170.00 0.00 0.00 23,573.28 1,650.13 25,223.41 x \$\$50.00/day) (\$\$) 4 x \$\$2.00/day) (\$\$) 10c/Search Fee (\$\$)	9,403.28 432.23 0.00 0.00 14,170.00 320.00 0.00 0.00 0.00 0.00 23,573.28 752.23 1,650.13 52.66 25,223.41 804.89 x \$\$50.00/day) (\$\$) 100.00 1x \$\$2.00/day) (\$\$) 224.70 0c/Search Fee (\$\$) 7.49	9,403.28 432.23 8,971.05 0.00 0.00 0.00 14,170.00 320.00 13,850.00 0.00 0.00 0.00 0.00 0.00 23,573.28 752.23 22,821.05 1,650.13 52.66 1,597.47 25,223.41 804.89 24,418.52 x \$\$50.00/day) (\$\$) 100.00 1x \$

INSPECTION

Date of Assignment: 24/02/2020

Trans-cab Auto Services Pte Ltd (Ang Mo Kio) Date Inspected:

24/02/2020 Inspected At: 2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	442.60 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 FL	* - FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	* - FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
6	1		*REAR TAILGATE	Repair	1,147.80 FL	*- FL
7	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
8	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
9	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	650.30 FL	*- FL
10	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
11	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
12	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
13	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
14	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
15	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
16	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
17	1		*COVER ,FLOOR UNDER NO 1	Serviceable	175.10 FL	*- FL
18	1		*COVER ,FLOOR UNDER NO 2	Serviceable	241.90 FL	*- FL
19	1		*COVER REAR FLOOR	Serviceable	229.90 FL	*- FL
20	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
22	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
23	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
24	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
25	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
26	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
27	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS
28	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	*- FS
29	1		*REAR TYRE 195/65/15	Not Necessary	350.00 FS	*- FS
30	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
31	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
32	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
33	1		*GUARD ,REAR BUMPER ,CENTER	Dented	576.31 FL	*576.31 FL
⊢=⊦ra	ncnise	part. S=SpcN	ett. L=ListItemDisc.	O-1 T (1 (CA)	44 007 04	F70 04
			- List Item Discount on I	Sub Total (S\$) Litems 25.00/25.00% (S\$)	11,307.61 1,904.33	576.31 144.08
				Total Parts (S\$)	9,403.28	432.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	<u>our Items</u>			
1	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
5	TO CHECK ELECTRICAL GEOMETRY AND COMPUTER WHEE ALIGNMENT	New	220.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
7	TO RUST PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	LABUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
12	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	100.00
	Gross Labour	14,170.00	320.00	
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >