-PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO.: GBC 507 R

APPENDIX A



(Diagram E) (Diagram D) (Diagram-C) (Diagram B) POINT OF IMPACT (Diagram A) FRONT FRONT FRONT FRONT FRONT Direction of impaddamage marked (→) (X) The vehicle VEAR SIDE sustained impact NEAR SIDE NEAR SIDE **NEAR SIDE** LEAR SIDE OFF SIDE on its Rear Portion. (See Diagram C) REAR REAR RE REAR REAR

GENERAL DESCRIPTION OF DAMAGES

Parts damaged were:

The rear bumpers and reinforcements, rear panel, both rear doors, both rear chassis were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 06/01/2020 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s Pek Tiong Auto Services as per attached Appraisement Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$ 7,800.00 after deducting the Policy Excess Clause of \$ NA.

As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's			<u>Our</u>		
	Es	timate	Amount		Revised	Amount
Spares Parts	:	9085	25		7509	73
Towing Charges	:	-	-		-	-
PB Labour Charges	:	1200	00	New -NA	880	00
Others Misc Charges	:	920	00		690	00
Paintwork	:	900	00		680	00
Total	: \$	12105	25	\$	9759	73

Under normal circumstances, the duration of repairs should not exceed <u>Seven (07)</u> days excluding Pre -Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame & Public Holidays.

Attached photographs taken during inspection Forty - Eight (48) Photographs

SPECIAL REMARKS

- 1. The inspection was conducted on a 'without prejudice' basis
- On 07/01/2020, we examined the extent of damages.
- 3. On 13/01/2020, we examined the repaired vehicle.

Yours FaithFully

TFNG PHILIPFOO

ACII CAE, AMIMI AIAME, AMSAE-A

Licensed Appraiser/Adjuster

Inspection Report Date: 20 Ja

20 January 2020

VEHICLE REGN NO :

GBC 507 R

OUR REFERENCE

PAS/PT/200116/TP

APPRAISEMENT SCHEDULE

INSPECTION REPORT DATE: 20-Jan-20 CONTINUATION SHEET NO: 1 Repairer's Recommendation / S/No Qty Parts / Labour Descriptions Remarks / Condition Estimate Amount Revised Amount PARTS SUPPLY - LIST ITEMS 40.00 40.00 Necessary 1 1se Rear bumper clips 2 Rear bumper **Badly Dented** 528.30 528.30 1pd Broken 680.00 680.00 3 Rear n/s door glass 1pd Badly dented 2717.05 2717.05 4 Rear n/s door 1pd 48.00 Rear n/s door logo Cracked 48.00 5 1pd 60.00 60.00 6 Rear n/s door 'Fiorino' emblem Cracked 1pd 125.00 7 Rear n/s door glass mldg Necessary 125.00 1pd Rear o/s door 'Fiat' emblem 48.00 48.00 8 Cracked 1pd 288.00 288.00 9 1pd Rear n/s door lower lock Bent 288.00 288.00 Badly dented Rear o/s door lower lock 10 1pd 2056.90 2056.90 Rear o/s door Badly dented 11 1p¢ 125.00 125.00 Necessary Rear o/s door glass mldg 12 1pd 680.00 Repair 13 Rear end lower panel Dented 1p¢ 10.00 10.00 Rear n/s door board clips Necessary 14 1set 10.00 Rear o/s door board clips Necessary 10.00 15 1set 58.00 58.00 Rear o/s door 'Multijet' emblem Cracked 16 1p¢ 180.00 Rear n/s door board Bent 180.00 17 1p¢ 460.00 460.00 Broken 18 1p¢ Wiper motor Broken 105.00 105.00 Wiper arm 1.9 1p¢ 128.00 128.00 Broken 20 1pd Wiper blade 8635.25 7955.25 795.52 Less: 10% Discount 8635.25 7159.73 SPECIAL NETT ITEMS 350.00 250.00 Dented 1 1set Rear bumper sensor 40.00 Necessary 40.00 2 Rear N/s door window sealant 1pt 40.00 40.00 3 Rear O/s door window sealant Necessary 1pt 10.00 10.00 Rear o/s door '4pax' sticker Necessary 4 1p¢ 10.00 10.00 Rear o/s door '70km/h' sticker Necessary 5 1pt 7509.73 9085.25 LABOUR & MISC. CHARGES Remove the necessary affected parts, 1 straighten rear end lower panel, both 1200.00 880.00 rear chassis and replace parts 120.00 150.00 Remove and refit rear n/s door parts 2 120.00 Remove and refit rear o/s door parts 150.00 3 900.00 680.00 Putty and Spraypaint on all affected parts 4 40.00 50.00 Check electrical 5 60.00 100.00 6 Tuff Kote 60.00 Remove and refit rear bumper sensors 100.00 7 30.00 50.00 8 Rewire rear portion 20.00 20.00 9 Vacuum broken glasses 150.00 120.00 Remove and refit rear n/s door glass 10 120.00 150.00 Remove and refit rear o/s door glass

repair at \$7,800.00nett

Note: Recommended lump sum

SUB / GRAND TOTAL

PRECISION APPRAISAL SERVICES

12105.25

We are sorry for the inconvenience caused

50ays. .. 5/06 25 2090: 4/00



9759.73