

22/02/2020

ASS. REC. BY:

REF: CS 31 LPC 2000243/GYF3-11 Special Instruction:

Surveyor:

90

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

24/02/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBL 507R

Insured:

Ym 7488R

at Workshop m/s

Pek Trong Auto

Tel:

6755 0688

of BIR 1017 Yishun Industrial Park A 701-258

Policy No:

Claim No:

19/20/20/VC05/022860

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3.01.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 6.1.2020 10.41a.m

Person Contacted:

Pek Trong

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

GBL 507R - CS31 MSG KUA796/3rd/302 Port - 5a/04/2019

Ym 7488R - x

\$3700, 5 Days.

S/N	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
				\$ cts	\$ cts
<u>PARTS SUPPLY - LIST ITEMS</u>					
1	1set	Rear bumper clips	Necessary	40.00	40.00
2	1pc	Rear n/s door glass	Broken 207.1	680.00	680.00
3	1pc	Rear n/s door	Badly dented 149/31	2717.05	2717.05
4	1pc	Rear n/s door logo	Cracked SVC	48.00	48.00
5	1pc	Rear n/s door 'Fiorino' emblem	Cracked	60.00	60.00
6	1pc	Rear n/s door glass mldg	Necessary SVC	125.00	125.00
7	1pc	Rear o/s door 'Fiat' emblem	Cracked	48.00	48.00
8	1pc	Rear n/s door lower lock	Bent	288.00	288.00
9	1pc	Rear o/s door lower lock	Badly dented SVC	288.00	288.00
10	1pc	Rear o/s door	Badly dented 1519.8	2056.90	2056.90
11	1pc	Rear o/s door glass mldg	Necessary	125.00	125.00
12	1pc	Rear end lower panel	Dented SVC	680.00	Repair
13	1set	Rear n/s door board clips	Necessary	10.00	10.00
14	1set	Rear o/s door board clips	Necessary	10.00	10.00
15	1pc	Rear o/s door 'Multijet' emblem	Cracked	58.00	58.00
16	1pc	Rear n/s door board	Bent	180.00	180.00
17	1pc	Wiper motor	Broken SVC	460.00	460.00
18	1pc	Wiper arm	Broken	105.00	105.00
19	1pc	Wiper blade	Broken 85	128.00	128.00
			26421	8106.95	7426.95
		Less: 10% Discount	10% 3270.78	8106.95	742.69
					6684.26
<u>SPECIAL NETT ITEMS</u>					
1	1set	Rear bumper sensor	Dented SVC	350.00	250.00
2	1pc	Rear N/s door window sealant	Necessary 30	40.00	40.00
3	1pc	Rear O/s door window sealant	Necessary 30	40.00	40.00
4	1pc	Rear o/s door '4pax' sticker	Necessary	10.00	10.00
5	1pc	Rear o/s door '70km/h' sticker	Necessary	10.00	10.00
			60	8556.95	7034.26
<u>LABOUR & MISC. CHARGES</u>					
1		Remove the necessary affected parts, straighten rear end lower panel, both rear chassis and replace parts	460	1200.00	880.00
2		Remove and refit rear n/s door parts	40	150.00	120.00
3		Remove and refit rear o/s door parts	40	150.00	120.00
4		Putty and Spraypaint on all affected parts	600	900.00	680.00
5		Check electrical	30	50.00	40.00
6		Tuff Kote		100.00	60.00
7		Remove and refit rear bumper sensors	40	100.00	60.00
8		Rewire rear portion		50.00	30.00
9		Vacuum broken glasses	10	20.00	20.00
10		Remove and refit rear n/s door glass	60	150.00	120.00
11		Remove and refit rear o/s door glass	60	150.00	120.00
Note: Recommended lump sum repair at \$7,400.00nett					
SUB / GRAND TOTAL				11576.95	9284.26

PRECISION APPRAISAL SERVICE



6670.78

1280

10% 3700

5 Days

Ce

2