

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20003141/T1KS3Q2**Date:** 11/12/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100386127
Claimant
Vehicle No : SJD9755G **Insured Vehicle No :** SKP5340X
Date of Loss: 23/02/2020 Nature of Claim: TP Claim No: 4005443387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJD9755G**
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX725988
Reg. Date: 11/04/2008 (Man. Year: 2008) Chassis No: MR053HY9305057335
Colour: Silver Odometer: 224486 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,780.82	3,983.75	1,797.07	31.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	2,210.00	760.00	25.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,750.82	6,193.75	2,557.07	29.22
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	8,750.82	4,950.00	3,800.82	43.43
+ GST 7.00/7.00% (S\$)	612.56	346.50	266.06	43.43
Nett Amount (S\$)	9,363.38	5,296.50	4,066.88	43.43
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		5,820.95		
Global Sum Settlement (S\$)		5,820.00		

INSPECTION

Date of Assignment: 24/02/2020
Date Inspected: 25/02/2020 Inspected At:

EM-1 AUTO PTE LTD
BLK 8 SIN MING INDUSTRIAL
ESTATE SECTOR C #01-68
SINGAPORE 575643

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	596.20 FL	*596.20 FL
2	1		*BOOT LID BADGE	Necessary	48.00 FL	*48.00 FL
3	1		*BOOT LID EMBLEM E	Necessary	52.00 FL	*52.00 FL
4	1		*BOOT LID EMBLEM VIOS	Necessary	52.00 FL	*52.00 FL
5	1		*BOOT LID EMBLEM SPORT	Necessary	52.00 FL	*52.00 FL
6	2		*BOOT LID STOPPER	Not Necessary	36.00 FL	*- FL
7	1		*BOOT LID INNER LOCK	Bent	129.50 FL	*129.50 FL
8	1		*BOOT LID WEATHERSTRIP	Torn	192.20 FL	*192.20 FL
9	2		*BOOT LID HINGES	Repair	144.80 FL	*- FL
10	1		*REAR BUMPER	Deformed	556.20 FL	*556.20 FL
11	1		*REAR BUMPER SIDE RETAINERS	N/S Not Necessary /O/SDeformed	161.40 FL	*80.70 FL
12	1		*REAR BUMPER ATTACHMENT RETAINERS	N/S Not Necessary /O/SDeformed	112.40 FL	*56.20 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
14	1		*REAR BUMPER BRACKETS RH	Deformed	87.20 FL	*87.20 FL
15	1		*REAR BUMPER REFLECTORS RH	Cracked	98.00 FL	*98.00 FL
16	1		*END PANEL	Bent	612.50 FL	*612.50 FL
17	1		*END PANEL TOP TRIM	Cracked	227.70 FL	*227.70 FL
18	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*20.00 FL
19	2		*SPARE TYRE PANEL TOP SIDE SPONGE	Deformed	384.00 FL	*384.00 FL
20	1		*REAR FENDER INNER TRIM RH	Not Necessary	256.10 FL	*- FL
21	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FL	*- FL
22	1		*REAR FENDER INNER SHIELD RH	Torn	59.60 FL	*59.60 FL
23	1		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	25.00 FL	*15.00 FL
24	2		*TAILLAMPS	Cut	792.80 FL	*686.00 FL
25	2		*TAILLAMPS INNER SEALER	Not Necessary	76.00 FL	*- FL
26	2		*SET TAILLAMPS CLIPS	Necessary	50.00 FL	*50.00 FL
27	1		*TAILLAMPS PANELS LH	Repair	131.50 FL	*- FL
28	1		*REAR EXHAUST SILENCER	Repair	683.10 FL	*- FL
29	2		*REAR EXHAUST MOUNTINGS	Not Necessary	85.40 FL	*- FL
30	1		*REAR EXHAUST GASKET	Not Necessary	59.50 FL	*- FL
31	1		*SET BOOT LID STICKER	Necessary	80.00 FS	*40.00 FS
32	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
33	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
34	1		*REAR BUMPER SPOILER	Deformed	800.00 FS	*500.00 FS
35	1		*REAR EXHAUST CHROME PIPE	Cut	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,251.10	5,005.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,470.28	1,021.25
Total Parts (\$\$)	5,780.82	3,983.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	900.00
2	SPRAY PAINTING	New	1,300.00	1,100.00
3	CHECK WIRING	New	40.00	30.00
4	ANTI RUST	New	100.00	30.00
5	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	30.00
7	REMOVE AND INSTALL REAR EXHAUST PIPE	New	120.00	60.00
Gross Labour Cost (\$\$)			2,970.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >