



Your Ref : S0M02H78

Date: 18th March 2020

Our Ref : CS/ASM20003142/Pyd3e2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Richard Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBQ 7544M
ACCIDENT ON 23/02/2020**

Instruction was received to inspect the vehicle Reg. No. FBQ 7544M. The inspection was conducted on 26/02/2020 at the premises of M/s Yew Tee Automobile Tech PL, Blk 25 Kaki Bukit Road 4, #01-61 Synergy @ Kaki Bukit, Singapore 417800.

The following vehicle information was recorded:

Registration Number	: FBQ 7544M
Make/Model	: Yamaha GDR155A (AEROX)
Year of Registration	: 2019
Body Colour	: Green
Chassis Number	: MH3SG4640KJ051266
Engine Capacity	: 155 cc
Speedometer Reading	: NIL

The whole motorcycle was burnt down due to external factors. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$ 9,500.00
Less: LTA Reimbursement Value (RV)	(S\$ 3,030.00)
Nett Liability	<u>S\$ 6,470.00</u>

Vehicle Inspected By:



SHERWIN BEH SWEE YANG
Technical Investigator



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.