

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003146/DES3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800150005

Claimant
Vehicle No : SH8443K **Insured Vehicle No :** SGZ7722J

Date of Loss: 13/02/2020 Nature of Claim: TP Claim No: 4054473467SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8443K	Engine No:	G4LEKU295283
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU164256
Reg. Date:	26/06/2019 (Man. Year: 2019)	Odometer:	84270 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,383.86	12,833.88	13,549.98	51.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	2,600.00	4,980.00	65.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	33,963.86	15,433.88	18,529.98	54.56
Approved Total (Overridden) (\$)		12,000.00		
(\$)	33,963.86	12,000.00	21,963.86	64.67
+ GST 7.00/7.00% (\$)	2,377.47	840.00	1,537.47	64.67
Nett Amount (\$)	36,341.33	12,840.00	23,501.33	64.67
+ Loss of Use (13.0 x S\$50.00/day) (\$)		650.00		
+ Car Rental (13.0 x S\$125.19/day) (\$)		1,627.47		
+ Doc/Search Fee (\$)		7.45		
Nett Liability (\$)		15,124.92		

INSPECTION

Date of Assignment: 24/02/2020

Date Inspected: 24/02/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming
Industrial Estate
Singapore 575644

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Not Necessary	418.30 FL	*- FL
2	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	35.00 FL	*- FL
3	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	28.00 FL	*- FL
4	1		*FRONT BUMPER SIDE BRACKET SUPPORT	Not Necessary	12.00 FL	*- FL
5	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
6	1		*HEADLAMP SUPPORT PANEL ASSY	Not Necessary	949.30 FL	*- FL
7	1		*HEADLAMP (LH)	Not Necessary	3,987.30 FL	*- FL
8	1		*FRT DOOR (LH)	Dented / Bent	1,797.20 FL	*1,797.20 FL
9	1		*FRONT DOOR PROTECTOR (LH)	Not Necessary	116.20 FL	*- FL
10	1		*REAR DOOR (LH)	Buckled	1,789.90 FL	*1,789.90 FL
11	1		*REAR DOOR RUBBER (LH)	Deformed	270.00 FL	*270.00 FL
12	1		*REAR DOOR OUTER HANDLE (LH)	Not Necessary	124.80 FL	*- FL
13	1		*REAR DOOR GEAR / REGULATOR (LH)	Not Necessary	367.84 FL	*- FL
14	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	256.80 FL	*- FL
15	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
16	1		*REAR DOOR HINGE UPPER (LH)	Not Necessary	73.88 FL	*- FL
17	1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	73.88 FL	*- FL
18	1		*REAR DOOR CHECK (LH)	Not Necessary	85.92 FL	*- FL
19	1		*REAR DOOR TRIM BOARD (LH)	Not Necessary	613.60 FL	*- FL
20	1		*DOOR CENTER PILLAR OUTER (LH)	Dented	3,764.90 FL	*3,764.90 FL
21	1		*ROCKER PANEL OUTER GARNISH	Cut	290.00 FL	*290.00 FL
22	1		*FRONT WHEEL RIM (LH)	Not Necessary	1,124.20 FL	*- FL
23	1		*FRONT WHEEL HUB CAP (LH)	Not Necessary	346.40 FL	*- FL
24	1		*FRONT WHEEL BEARING	Damaged	454.00 FL	*454.00 FL
25	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	372.50 FL	*372.50 FL
26	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	206.90 FL	*- FL
27	1		*FRONT SHOCK ABSORBER FORK (LH)	Not Necessary	206.90 FL	*- FL
28	1		*FRONT SUSPENSION UPPER ARM (LH)	Not Necessary	244.30 FL	*- FL
29	1		*FRONT DRIVE SHAFT	Not Necessary	936.70 FL	*- FL
30	1		*RACK & PINION ASSY	Not Necessary	887.40 FL	*- FL
31	1		*STG TIE ROD	Distorted	125.60 FL	*125.60 FL
32	1		*STG TIE END	Distorted	94.70 FL	*94.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*STABILIZER BAR	Not Necessary	246.80 FL	*- FL
34	1		*STABILIZER BAR BUSH (LH)	Not Necessary	22.30 FL	*- FL
35	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
36	1		*STABILIZER BRACKET	Not Necessary	10.50 FL	*- FL
37	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	296.80 FL	*296.80 FL
38	1		*KNUCKLE ARM (LH)	Distorted	363.60 FL	*363.60 FL
39	1		*ENGINE UNDER COVER	Not Necessary	469.40 FL	*- FL
40	1		*ENGINE CROSSMEMBER	Distorted	1,803.90 FL	*1,803.90 FL
41	1		*REAR BUMPER	Not Necessary	459.40 FL	*- FL
42	1		*REAR BUMPER SIDE BRACKET (LH)	Not Necessary	55.80 FL	*- FL
43	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
44	1		*REAR BUMPER SIDE UNDER (LH)	Not Necessary	33.10 FL	*- FL
45	1		*REAR FENDER (LH)	Dented	1,768.30 FL	*1,768.30 FL
46	1		*REAR WINDSCREEN MOULDING	Not Necessary	48.50 FL	*- FL
47	1		*REAR TYRE RIM (LH)	Not Necessary	1,124.20 FL	*- FL
48	1		*REAR WHEEL HUP-CAP (LH)	Not Necessary	346.40 FL	*- FL
49	1		*REAR WHEELBEARING ING & HUB	Damaged	454.00 FL	*454.00 FL
50	1		*REAR TRAILING ARM (LH)	Distorted	265.40 FL	*265.40 FL
51	1		*REAR ASSIST (LH)	Distorted	227.90 FL	*227.90 FL
52	1		*REAR SHOCK ABSORBER (LH)	Distorted	230.50 FL	*230.50 FL
53	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	133.10 FL	*- FL
54	1		*REAR CORSSMEMBER	Not Necessary	1,468.70 FL	*- FL
55	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
56	1		*STABILIZER LINK	Not Necessary	147.30 FL	*- FL
57	1		*REAR UPPER ARM (LH)	Distorted	239.50 FL	*239.50 FL
58	1		*REAR LOWER ARM (LH)	Distorted	393.10 FL	*393.10 FL
59	1		*REAR KNUCKLE ARM (LH)	Distorted	538.10 FL	*538.10 FL
60	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
61	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS
62	1		*REAR DOOR PROTECTOR (LH) (@ \$116.20 DISC 20%)	Bent	116.20 FS	*92.96 FS
63	1		*REAR DOOR TEL NO. STICKER (LH)	Not Necessary	10.00 FS	*- FS
64	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
65	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
66	1		*FRONT TYRE (LH) (@ \$216.00 DISC 50%)	Punctured	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 32,790.02 15,941.86
- List Item Discount on L Items 20.00/20.00% (\$\$) 6,406.16 3,107.98

Total Parts (\$\$) 26,383.86 12,833.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	2,000.00	800.00
2	SPRAY PAINTING CHARGE.	New	1,800.00	800.00
3	WIRING CHARGE.	New	150.00	0.00
4	TUFF KOTE.	New	150.00	40.00
5	TOWING CHARGE.	New	60.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	80.00
8	REMOVE / REFIX REVERSE SENSOR.	New	120.00	0.00
9	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
10	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
11	TRANSFER OF DOOR FRONT.	New	120.00	60.00
12	TRANSFER OF DOOR REAR.	New	120.00	60.00
13	REMOVE / REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
14	4 WHEEL ALIGNMENT.	New	120.00	60.00
15	REMOVE / REFIX RADIATOR.	New	90.00	0.00
16	REMOVE / REFIX AIRCON & REFILL GAS.	New	150.00	0.00
17	RE-SET FRT ABS SYSTEM. }	New	200.00	320.00
18	RE-SET REAR ABS SYSTEM. }	New	400.00	0.00
19	RE-SET FRT POWER WINDOW SYSTEM. }	New	200.00	0.00
20	RE-SET REAR POWER WINDOW SYSTEM. }	New	200.00	0.00
21	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }	New	480.00	0.00
Gross Labour Cost (\$\$)			7,580.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >