

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo




18/11/2019 16:25

Accident Photo



Accident Photo



Accident Photo



Accident Photo





INVOICE

TO : DREAM LEASING PTE LTD

Invoice No.: 1119/EA375

Date: 10-Dec-2019

C/O: ECLIPSE AUTO PTE LTD
155 KAKI BUKIT AVE 1 #01-00,
SHUNLI INDUSTRIAL PARK
SINGAPORE 416012

PARTICULARS

Vehicle Registration No.: SLS 2234 L
Date of Loss: 17-Nov-2019
Date of Assessment: 21-Nov-2019

SERVICES

FEES

1. Assessment with report Photographs -
Including films, developing, storage and Transport. \$400.00

TOTAL \$400.00

SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP




4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$9,815.20
Adjusted Amount:	\$6,137.00
Lump Sum:	\$5,000.00
Estimated Repair Days:	7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SLS 2234 L

ARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID	Repair	1,297.00	-
1	REAR BOOTLID 'CERATO' EMBLEM	Reuse	60.00	-
1	REAR BOOTLID 'K3' EMBLEM	Reuse	59.00	-
1	REAR BOOTLID 'LOGO' EMBLEM	Reuse	34.00	-
1	REAR BOOTLID MECHANISM LOCK	Bent	109.00	109.00
2	REAR BOOTLID REFLECTOR L/R	Repair	1,420.00	-
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R	Bent	24.00	24.00
1	REAR BOOTLID WEATHER STRIP	Cut	92.00	92.00
2	REAR FENDER INNER TRIM GARNISH L/R	Reuse	358.00	-
2	REAR TAILLAMP L/R	Cut	1,668.00	1,668.00
2	REAR TAILLAMP INNER PANEL L/R	Repair	246.00	-
2	REAR TAILLAMP INNER BLACK GASKET L/R	Necessary	30.00	30.00
1	REAR BUMPER	Cracked	688.00	688.00
1	REAR BUMPER LOWER LID GARNISH	Cracked	347.00	347.00
1	REAR BUMPER REINFORCEMENT	Bent	313.00	313.00
2	REAR BUMPER REINFORCEMENT BRACKET L/R	Bent	136.00	136.00
3	REAR BUMPER REINFORCEMENT LOWER BRACKET	Bent	75.00	75.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET L/R	Bent	42.00	42.00
2	REAR BUMPER REFLECTOR L/R	Cracked	64.00	64.00
2	REAR BUMPER SIDE RETAINER L/R	Bent	76.00	76.00
1	REAR END PANEL INNER TOP GARNISH	Cut	66.00	66.00
1	REAR END PANEL	Repair	324.00	-
			7,528.00	3,730.00
Less 10% discount			752.80	373.00
Parts Total:			6,775.20	3,357.00

ASSESSMENT REPORT FOR VEHICLE NO. SLS 2234 L

SPECIAL NETT ITEMS

2 REAR TAILLAMP CLIPS L/R - SET	Necessary	40.00	40.00
1 REAR BOOTLID INNER TRIM COVER CLIPS - SET	Necessary	50.00	50.00
1 REAR BUMPER REVERSE SENSOR	Faulty	350.00	350.00
1 REAR END PANEL INNER TOP GARNISH CLIPS - SET	Necessary	20.00	20.00
Special Nett Total :		460.00	460.00

LABOUR

S/N Description	Workshop's Estimate	Our Assessment
1 To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	100.00
2 To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	80.00	60.00
3 To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,100.00	1,000.00
4 To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00	1,100.00
5 To apply anti-rust chemical on repaired and replaced panel.	80.00	60.00
Labour Total :	2,580.00	2,320.00
TOTAL (PARTS & LABOUR) \$	9,815.20	6,137.00

The workshop has agreed to undertake the repair on a Lump Sum basis.
 The final adjusted Lump Sum contract amount is
\$5,000.00 (SINGAPORE DOLLARS FIVE THOUSAND ONLY)



Amas Ong
Automobile Assessor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer
 Signature:
 Date:

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$9,815.20
Adjusted Amount:	\$6,137.00
Lump Sum:	\$5,000.00
Estimated Repair Days:	7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SLS 2234 L

ARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID ✓ (R)	Repair	1,297.00	-
1	REAR BOOTLID 'CERATO' EMBLEM X (SVC)	Reuse	60.00	-
1	REAR BOOTLID 'K3' EMBLEM X (SVC)	Reuse	59.00	-
1	REAR BOOTLID 'LOGO' EMBLEM X (SVC)	Reuse	34.00	-
1	REAR BOOTLID MECHANISM LOCK ✓ Jm	Bent	109.00	109.00 ✓
2	REAR BOOTLID REFLECTOR L/R X (SVC)	Repair	1,420.00	-
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R X (SVC)	Bent	24.00	24.00
1	REAR BOOTLID WEATHER STRIP X (SVC)	Cut	92.00	92.00
2	REAR FENDER INNER TRIM GARNISH L/R X (SVC)	Reuse	358.00	-
2	REAR TAILLAMP L/R ✓ CRA	Cut	1,668.00	1,668.00 / 360 ✓
2	REAR TAILLAMP INNER PANEL L/R X (R)	Repair	246.00	-
2	REAR TAILLAMP INNER BLACK GASKET L/R ✓ Jm	Necessary	30.00	30.00 ✓
1	REAR BUMPER ✓ CRA	Cracked	688.00	688.00 ✓
1	REAR BUMPER LOWER LID GARNISH ✓ CRA	Cracked	347.00	347.00 310.80 ✓
1	REAR BUMPER REINFORCEMENT ✓ CRA	Bent	313.00	313.00 ✓
2	REAR BUMPER REINFORCEMENT BRACKET L/R R/H only ✓ BT	Bent	136.00	136.00 68 ✓
2	REAR BUMPER REINFORCEMENT LOWER BRACKET ✓ BT	Bent	75.00	75.00 25 ✓
2	REAR BUMPER REINFORCEMENT UPPER BRACKET L/R ✓ BT R/H	Bent	42.00	42.00 21 ✓
2	REAR BUMPER REFLECTOR L/R ✓ S.R.	Cracked	64.00	64.00 ✓
2	REAR BUMPER SIDE RETAINER L/R ✓ CRA	Bent	76.00	76.00 ✓
1	REAR END PANEL INNER TOP GARNISH X (SVC)	Cut	66.00	66.00
1	REAR END PANEL X (R)	Repair	324.00	-
			<hr/>	
			7,528.00	3,730.00
Less 10% discount			752.80	373.00
Parts Total:			<hr/>	<hr/>
			6,775.20	3,357.00

ASSESSMENT REPORT FOR VEHICLE NO. SLS 2234 L


SPECIAL NETT ITEMS

2	REAR TAILLAMP CLIPS L/R - SET ✓	Necessary	40.00	150 ✓
1	REAR BOOTLID INNER TRIM COVER CLIPS - SET ✓	Necessary	50.00	40.0 ✓
1	REAR BUMPER REVERSE SENSOR ✓	Faulty	350.00	50.0 ✓
1	REAR END PANEL INNER TOP GARNISH CLIPS - SET ✓	Necessary	20.00	350.0 ✓
Special Nett Total :			460.00	20.0 ✓

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor. ✓	120.00	30 ✓ 100.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet. X	80.00	60.00
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. ✓	1,100.00	1,000.00 ✓
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. ✓	1,200.00	600 ✓ 1,100.00
5	To apply anti-rust chemical on repaired and replaced panel. ✓	80.00	500 ✓ 60.00
Labour Total :		2,580.00	2,320.00
TOTAL (PARTS & LABOUR) \$		9,815.20	6,137.00

The workshop has agreed to undertake the repair on a Lump Sum basis.
 The final adjusted Lump Sum contract amount is
\$5,000.00 (SINGAPORE DOLLARS FIVE THOUSAND ONLY)



Amas Ong
Automobile Assessor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4/5 upon
 without problem
 Paper survey ready
 26/2/20 1.30 AM
 H-ANN
 4 day

Parts 3064.80
 Parts less 10%
 2758.32
 spe nett 250
 labour 1190
 4198.32
 H/S less 20%
 3358.65
 total
 H/S
 \$3350.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III19020613/Hyd3s2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 26-02-2020	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6901T	Veh. Inspected	SLS 2234L
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19110436	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	05/02/2020
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MJ5739693	Colour	BLACK
Odometer	71372	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	TRIANGLE	5 mm
L/H Front Tyre	195/65 R15	TRIANGLE	5 mm
R/H Rear Tyre	195/65 R15	TRIANGLE	4 mm
L/H Rear Tyre	195/65 R15	TRIANGLE	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/11/2019	Inspection Date	21/11/2019
Survey held at	ECLIPSE AUTO PTE LTD 155 KAKI BUKIT AVENUE 1 #01-00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2234L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	1,297.00	-
1	REAR BOOTLID 'CERATO' EMBLEM	SERVICEABLE	60.00	-
1	REAR BOOTLID 'K3' EMBLEM	SERVICEABLE	59.00	-
1	REAR BOOTLID 'LOGO' EMBLEM	SERVICEABLE	34.00	-
1	REAR BOOTLID MECHANISM LOCK	JAMMED	109.00	109.00
2	REAR BOOTLID REFLECTOR L/R	SERVICEABLE	1,420.00	-
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R	SERVICEABLE	24.00	-
1	REAR BOOTLID WEATHER STRIP	SERVICEABLE	92.00	-
2	REAR FENDER INNER TRIM GARNISH L/R	SERVICEABLE	358.00	-
2	TAILLAMP L/R	CRACKED	1,668.00	1,360.00
2	REAR TAILLAMP INNER PANEL L/R	TO REPAIR SEE LABOUR	246.00	-
2	REAR TAILLAMP INNER BLACK GASKET L/R	NECESSARY	30.00	30.00
1	REAR BUMPER	CRUSHED	688.00	688.00
1	REAR BUMPER LOWER LID GARNISH	CRACKED	347.00	310.80
1	REAR BUMPER REINFORCEMENT	CRACKED	313.00	313.00
2	REAR BUMPER REINFORCEMENT BRACKET L/R	O/S BENT	136.00	68.00
3	REAR BUMPER REINFORCEMENT LOWER BRACKET	BENT 1PC ONLY	75.00	25.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET L/R	O/S BENT	42.00	21.00
2	REAR BUMPER REFLECTOR L/R	SCRATCHED	64.00	64.00
2	REAR BUMPER SIDE RETAINER L/R	CRUSHED	76.00	76.00
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	66.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	324.00	-
	LESS 10% DISCOUNT		-752.80	-306.48
			6,775.20	2,758.32
SPECIAL NETT ITEMS				
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY	40.00	15.00
1	SET REAR BOOTLID INNER TRIM COVER CLIPS (SN)	NECESSARY	50.00	20.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	20.00	15.00
			460.00	250.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	30.00
	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET.	NOT NECESSARY	80.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,100.00	600.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR TAILLAMP INNER PANEL L/R AND REAR END PANEL.		1,200.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		80.00	60.00
			2,580.00	1,190.00
GRAND TOTAL			9,815.20	4,198.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,350.00

Report Ref No. CS3/III19020613/Hyd3s2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.