

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG20003157/NQD3E2

Date: 30/04/2020

REFERENCE

Insured/Claimant:	JAMALUDIN BIN MOHAMED	Policy No:	1900023135
Date of Loss:	21/02/2020	Nature of Claim:	OD
		Claim No:	7533360859SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ9402M		
Make & Model:	HONDA CB400, 399cc	Engine No:	NC47E1005292
Reg. Date:	09/01/2015 (Man. Year: 2014)	Chassis No:	NC471005269
Colour:	Red	Odometer:	80976 km
Engine Capacity:	399 cc		
Market Value/New Car Price:	S\$10,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	160/60 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,637.00	8,386.50	2,250.50	21.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	700.00	1,370.00	66.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,707.00	9,086.50	3,620.50	28.49
Approved Total (Overridden) (\$\$)		6,500.00		
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	12,207.00	6,000.00	6,207.00	50.85
+ GST 7.00/7.00% (\$\$)	854.49	420.00	434.49	50.85
Nett Amount (\$\$)	13,061.49	6,420.00	6,641.49	50.85

INSPECTION

Date of Assignment:	25/02/2020		
Date Inspected:	26/02/2020	Inspected At:	Bike Production Pte Ltd (HQ)
			610 SERANGOON ROAD
			Singapore 218216

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL AXLE	Scratched	95.00 FL	*95.00 FL
2	2		*STEERING STEM BEARING	Necessary	90.00 FL	*90.00 FL
3	1		*FRONT BRAKE DISK	Serviceable	305.00 FL	*- FL
4	1		*FRONT BRAKE CALIPER	Serviceable	380.00 FL	*- FL
5	1		*FRONT RIGHT FORK ASSEMBLY	Scratched	1,105.00 FL	*1,105.00 FL
6	1		*STEERING HEAD CROWN	Serviceable	430.00 FL	*- FL
7	1		*STEERING STEM UNDERBRACKET	Serviceable	480.00 FL	*- FL
8	1		*WINDSHIELD	Cracked	205.00 FL	*205.00 FL
9	1		*HEADLAMP ASSEMBLY	Cracked	480.00 FL	*480.00 FL
10	1		*HEADLAMP BRACKET	Bent	335.00 FL	*335.00 FL
11	1		*OUTER METER COVER	Cracked	175.00 FL	*175.00 FL
12	1		*INNER METER COVER	Cracked	175.00 FL	*175.00 FL
13	1		*UPPER CRASH BAR RIGHT	Scratched	180.00 FL	*180.00 FL
14	1		*UPPER CRASH BAR LEFT	Scratched	180.00 FL	*180.00 FL
15	1		*RIGHT BALANCER	Scratched	95.00 FL	*95.00 FL
16	1		*LEFT VIEW MIRROR	Scratched	140.00 FL	*140.00 FL
17	1		*RIGHT VIEW MIRROR	Scratched	140.00 FL	*140.00 FL
18	1		*HANDLE BAR	Bent	195.00 FL	*195.00 FL
19	1		*BRAKE LEVER	Scratched	75.00 FL	*75.00 FL
20	1		*RIGHT FRONT SIGNAL	Scratched	140.00 FL	*140.00 FL
21	1		*LEFT FRONT SIGNAL	Broken	140.00 FL	*140.00 FL
22	1		*RIGHT BODY FAIRING	Scratched	330.00 FL	*330.00 FL
23	1		*LEFT BODY FAIRING	Scratched	330.00 FL	*330.00 FL
24	2		*HONDA WING DECAL	Necessary	90.00 FL	*40.00 FL
25	2		*MARK X DECAL	Necessary	130.00 FL	*80.00 FL
26	1		*ENGINE COVER ASSY RIGHT	Scratched	395.00 FL	*395.00 FL
27	1		*ENGINE COVER GASKET	Necessary	65.00 FL	*65.00 FL
28	1		*LOWER ALUMINIUM PLATE	Scratched	145.00 FL	*145.00 FL
29	1		*BRAKE PEDAL	Bent	105.00 FL	*105.00 FL
30	1		*FRONT RIGHT FOOTREST HOLDER	Scratched	195.00 FL	*195.00 FL
31	1		*FRONT RIGHT FOOTREST	Scratched	95.00 FL	*95.00 FL
32	1		*EXHAUST ASSEMBLY	Scratched	1,800.00 FL	*1,800.00 FL
33	3		*ENGINE OIL	Necessary	90.00 FS	*90.00 FS
34	1		*FRONT SPORT RIM	Scratched	700.00 FS	*200.00 FS
35	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*15.00 FS
36	1		*REAR TOP CASE	Scratched	450.00 FS	*450.00 FS
37	1		*REAR BOX BRACKET	Serviceable	220.00 FS	*- FS
38	1		*REAR RIGHT SIDE CASE	Scratched	175.00 FS	*175.00 FS
39	1		*REAR RIGHT FOOTREST	Scratched	95.00 FL	*95.00 FL
40	2		*REAR RIGHT FOOTREST HOLDER	Bent	195.00 FL	*195.00 FL
41	1		*FRONT MUDGUARD	Scratched	195.00 FL	*195.00 FL
42	1		*FRONT MUDGUARD BRACE	Bent	125.00 FL	*125.00 FL
43	1		*INNER COVER LEFT	Cracked	75.00 FL	*75.00 FL
44	1		*INNER COVER RIGHT	Cracked	75.00 FL	*75.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,635.00	9,215.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	998.00	828.50
Total Parts (\$\$)	10,637.00	8,386.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	90.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS	New	800.00	450.00
3	REMOVE, BALANCING AND REFIT FRONT WHEEL RIM	New	150.00	0.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	50.00
5	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	450.00	0.00
6	SPRAY PAINTING	New	400.00	200.00
Gross Labour Cost (S\$)			2,070.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >