

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20003158/UGS3Q2

Date: 26/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010662-01

Claimant
Vehicle No : GBB8211X **Insured Vehicle No :** SGK4439B

Date of Loss: 22/02/2020 Nature of Claim: TP Claim No: 1202000009596

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB8211X	Engine No:	K9KF276D089704
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1YBAM20U0002888
Reg. Date:	26/05/2010 (Man. Year: 2010)	Odometer:	247591 km
Colour:	Silver		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,832.41	2,241.51	4,590.90	67.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,140.00	2,360.00	67.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,332.41	3,381.51	6,950.90	67.27
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	10,332.41	2,700.00	7,632.41	73.87
+ GST 7.00/7.00% (S\$)	723.27	189.00	534.27	73.87
Nett Amount (S\$)	11,055.68	2,889.00	8,166.68	73.87
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,189.00		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment: 25/02/2020

Date Inspected: 27/02/2020 Inspected At:

Automobile Integrated Management
Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01, Kaki Bukit
(South Wing)
Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 May 2020)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB8211X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE -LH	Dented / Bent	1,281.60 FN	*1,281.60 FN
2	1		*TAILGATE OUTER GARNISH	Not Necessary	336.10 FN	*- FN
3	1		*TAILGATE LOWER LOCK	Not Necessary	106.50 FN	*- FN
4	1		*TAILGATE INNER LOCK	Not Necessary	183.90 FN	*- FN
5	1		*TAILGATE INNER LOCK ACTUATOR	Not Necessary	190.60 FN	*- FN
6	1		*TAILGATE INNER TRIM	Not Necessary	130.50 FN	*- FN
7	1		*TAILGATE CHECKER	Not Necessary	89.90 FN	*- FN
8	1		*TAILGATE OPENING W/STRIP	Dented / Bent	130.60 FN	*130.60 FN
9	1		*TAILGATE -RH	Not Necessary	960.90 FN	*- FN
10	1		*TAILGATE W/STRIP	Necessary	86.90 FN	*86.90 FN
11	1		*TAILGATE LOWER LOCK	Not Necessary	106.50 FN	*- FN
12	1		*TAILGATE LOWER LOCK STRIKER	Not Necessary	41.50 FN	*- FN
13	1		*TAILGATE CHECKER	Not Necessary	89.90 FN	*- FN
14	2		*TAILLAMPS -L/R	Not Necessary	573.00 FN	*- FN
15	1		*REAR BUMPER	Dented / Deformed	624.80 FN	*624.80 FN
16	2		*REAR BUMPER REFLECTOR -L/R	Not Necessary	131.00 FN	*- FN
17	1		*REAR BUMPER TOW COVER	Not Necessary	28.90 FN	*- FN
18	1		*REAR BUMPER FOAM	Not Necessary	130.20 FN	*- FN
19	2		*REAR BUMPER SIDE RETAINER -L/R	Not Necessary	97.20 FN	*- FN
20	1		*REAR END PANEL	Repair	424.00 FN	*- FN
21	1		*REAR END PANEL INNER MEMBER	Not Necessary	518.10 FN	*- FN
22	1		*REAR END PANEL TOP TRIM	Not Necessary	89.90 FN	*- FN
23	1		*REAR EXHAUST PIPE	Not Necessary	291.60 FN	*- FN
24	1		*REAR SPARE WHEEL CARRIER	Not Necessary	175.60 FN	*- FN
25	1		*REAR SPARE WHEEL LOCK CATCH	Not Necessary	105.20 FN	*- FN
26	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
28	1		*REAR STICKER 5 PAX	Necessary	10.00 FS	*10.00 FS
29	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
30	2		*SET TAILGATE GLASS SEALANT -L/R	Necessary	120.00 FS	*80.00 FS
31	2		*SET TAILGATE FOAM TAPE -L/R	Not Necessary	90.00 FS	*- FS
32	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	7,524.90	2,453.90
- Nett Item Discount on N Items 10.00/10.00% (S\$)	692.49	212.39
Total Parts (S\$)	6,832.41	2,241.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	300.00	200.00
3	TO REMOVE ,REFIX REAR REVERSE SENSOR	New	80.00	50.00
4	TO REMOVE,REFIX REAR EXHAUST	New	100.00	0.00
5	TO RESPRAY UNDERCOATING	New	150.00	60.00
6	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	0.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	300.00
8	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	500.00
Gross Labour Cost (\$\$)			3,500.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >