

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003168/DKA3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994309

Claimant
Vehicle No : SHA5186P **Insured Vehicle No :** SLK6629Y

Date of Loss: 15/02/2020 Nature of Claim: TP Claim No: 4170498398SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA5186P		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU298141
Reg. Date:	17/07/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164776
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	70,034.24	29,954.84	40,079.40	57.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,370.00	3,160.00	5,210.00	62.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	78,404.24	33,114.84	45,289.40	57.76
Approved Total (Overridden) (S\$)		26,000.00		
(S\$)	78,404.24	26,000.00	52,404.24	66.84
+ GST 7.00/7.00% (S\$)	5,488.30	1,820.00	3,668.30	66.84
Nett Amount (S\$)	83,892.54	27,820.00	56,072.54	66.84
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/02/2020

Date Inspected: 26/02/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming
Industrial Estate
Singapore 575644

Estimated Period of Repair: 14.0 days

Adjuster: BRYAN TANI

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,253.80 FL	*2,253.80 FL
2	1		*BONNET RUBBER (LH)	Not Necessary	12.40 FL	*- FL
3	1		*BONNET RUBBER (RH)	Not Necessary	12.40 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Bent	237.40 FL	*237.40 FL
5	1		*BONNET LOCK	Bent	127.30 FL	*127.30 FL
6	1		*BONNET ABSORBER	No such part	35.70 FL	*- FL
7	1		*BONNET INSULATOR	Not Necessary	230.10 FL	*- FL
8	1		*BONNET SEAL	Not Necessary	38.30 FL	*- FL
9	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
10	1		*BONNET CABLE	Not Necessary	29.90 FL	*- FL
11	1		*RADIATOR GRILLE	Broken	1,227.50 FL	*1,227.50 FL
12	1		*FRONT BUMPER COVER	Broken	418.30 FL	*418.30 FL
13	1		*FRONT BUMPER SPONGE /ABSORBER	Dislodged	86.90 FL	*86.90 FL
14	1		*FRONT BUMPER REINFORCEMENT	Dented	1,075.10 FL	*1,075.10 FL
15	1		*FRONT BUMPER GRILLE (LH/RH)	O/S Not Necessary / N/SCut/Broken	373.80 FL	*186.90 FL
16	1		*FRONT BUMPER TOWING COVER	Serviceable	29.00 FL	*- FL
17	2		*FRONT BUMPER MOULDING CENTRE UPPER (LH/RH)	Cut (1 PCS ONLY)	217.00 FL	*108.50 FL
18	1		*FRONT BUMPER LOWER STIFFNER	Cracked	85.10 FL	*85.10 FL
19	1		*FRONT BUMPER LIP	Dislodged	35.10 FL	*35.10 FL
20	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	70.00 FL	*- FL
21	1		*FRONT BUMPER BRACKET (LH/RH)	O/S Not Necessary / N/S Broken	56.00 FL	*28.00 FL
22	1		*FRONT BUMPER SIDE BRACKET SUPPORT	Not Necessary	12.00 FL	*- FL
23	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
24	1		*FRONT BUMPER STRIP ASSY	Dislodged	29.40 FL	*29.40 FL
25	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	949.30 FL	*949.30 FL
26	2		*HEADLAMP (LH/RH)	N/S Broken / O/S Cracked	7,974.60 FL	*2,396.00 FL
27	2		*HEADLAMP HALOGEN BULB (LH/RH)	Not Necessary	28.80 FL	*- FL
28	1		*DAY LIGHT ,LH	Dislodged / Broken	642.50 FL	*642.50 FL
29	1		*DAY LIGHT ,RH	Mtg Cracked	642.50 FL	*642.50 FL
30	2		*DAY LIGHT WIRE ,LH/RH	Not Necessary	1,171.00 FL	*- FL
31	1		*BUZZER ASSY -PIEZO (LH/RH)	N/S Broken /O/S Not Necessary	776.00 FL	*388.00 FL
32	1		*RADIATOR INVERTER	Bent / Punctured	884.80 FL	*884.80 FL
33	1		*RADIATOR	Bent / Punctured	510.50 FL	*510.50 FL
34	1		*RADIATOR BLOWER MOTOR	Dented / Damaged	576.00 FL	*576.00 FL
35	1		*RADIATOR FAN	Broken	375.10 FL	*375.10 FL
36	1		*RADIATOR SHROUD	Broken	275.50 FL	*275.50 FL
37	1		*RADIATOR HOSE UPPER	Not Necessary	66.20 FL	*- FL
38	1		*RADIATOR HOSE LOWER	Bent / Deformed	66.20 FL	*66.20 FL
39	2		*RADIATOR AIR GUARD (LH/RH)	Broken / Deformed	52.80 FL	*52.80 FL
40	2		*RADIATOR AUR GUARD ,UPR (LH/RH)	Broken (1 PCS ONLY)	55.00 FL	*27.50 FL
41	1		*HORN UNIT (LH/RH)	N/S Damaged /O/S Not Necessary	145.60 FL	*72.80 FL
42	1		*FRONT FENDER (LH/RH)	N/S Buckled / O/S Not Necessary	981.40 FL	*490.70 FL
43	2		*FRONT FENDER APRON PANEL UPPER (LH/RH)	Not Necessary	259.20 FL	*- FL
44	2		*FRONT FENDER SHIELD (LH/RH)	Dislodged / Broken	229.40 FL	*229.40 FL
45	2			N/S Broken / O/S Cut	712.00 FL	*712.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*FLAP ASSY ACTIVE AIR UPPER (LH/RH) *ACTUATOR ACTIVE AIR (LH/RH)	N/S Damaged/ O/S Not Necessary	514.20 FL	*257.10 FL
47	2		*FRONT FENDER RETAINER	Not Necessary	82.80 FL	*- FL
48	1		*AIRCON CONDENSER	Bent / Punctured	663.60 FL	*663.60 FL
49	1		*AIRCON SUCTION & LIQUID HOSE	Dented	679.60 FL	*679.60 FL
50	1		*AIRCON DISCHARGE HOSE	Not Necessary	148.50 FL	*- FL
51	1		*FRT DOOR (LH)	Not Necessary	1,797.20 FL	*- FL
52	1		*FRT DOOR RUBBER	Not Necessary	250.00 FL	*- FL
53	1		*FRONT DOR HINGE UPPER (LH)	Not Necessary	65.76 FL	*- FL
54	1		*FRONT DOR HINGE LOWER (LH)	Not Necessary	65.76 FL	*- FL
55	1		*FRONT DOOR CHECK (LH)	Not Necessary	72.98 FL	*- FL
56	1		*FRONT DOOR TRIM BOARD (LH)	Not Necessary	796.80 FL	*- FL
57	2		*FRT SAFETY BELT (ASSY) (LH/RH)	Activated	897.80 FL	*897.80 FL
58	2		*FRT SAFETY BELT BUCKLE	Not Necessary	318.20 FL	*- FL
59	1		*FRONT WINDSCREEN GLASS	Not Necessary	1,558.10 FL	*- FL
60	1		*FRONT WINDSCREEN MOULDING	Not Necessary	57.30 FL	*- FL
61	2		*FRONT WINDSCREEN PILLAR OUTER (LH/RH)	Repair	7,529.80 FL	*- FL
62	1		*WIPER DANEL TOP GARNISH	Not Necessary	181.20 FL	*- FL
63	1		*WIPER LINK	Not Necessary	224.00 FL	*- FL
64	2		*FRONT WHEEL RIM (LH/RH)	Not Necessary	2,248.40 FL	*- FL
65	2		*FRONT WHEEL HUB CAP (LH/RH)	Not Necessary	692.80 FL	*- FL
66	2		*FRONT WHEEL BEARING	Not Necessary	908.00 FL	*- FL
67	2		*FRONT SHOCK ABSORBER (ASSY) (LH/RH)	Damaged	745.00 FL	*745.00 FL
68	2		*FRONT SHOCK ABSORBER MOUNTING (LH/RH)	Not Necessary	413.80 FL	*- FL
69	2		*FRONT SHOCK ABSORBER FORK (LH/RH)	No such part	413.80 FL	*- FL
70	2		*FRONT SUSPENSION UPPER ARM (LH/RH)	No such part	488.60 FL	*- FL
71	2		*FRONT DRIVE SHAFT (LH/RH)	Not Necessary	1,873.40 FL	*- FL
72	1		*RACK & PINION ASSY	Not Necessary	887.40 FL	*- FL
73	2		*STG TIE ROD	Not Necessary	251.20 FL	*- FL
74	2		*STG TIE END	Not Necessary	189.40 FL	*- FL
75	1		*STABILIZER BAR	Not Necessary	246.80 FL	*- FL
76	2		*STABILIZER BAR BUSH (LH/RH)	Not Necessary	44.60 FL	*- FL
77	2		*STABILIZER BAR LINK	Not Necessary	184.20 FL	*- FL
78	2		*STABILIZER BRACKET	Not Necessary	21.00 FL	*- FL
79	2		*FRONT SUSPENSION LOWER ARM (LH/RH)	Distorted	593.60 FL	*593.60 FL
80	2		*KNUCKLE ARM (LH/RH)	Not Necessary	727.20 FL	*- FL
81	2		*ABS SENSOR	Not Necessary	580.00 FL	*- FL
82	1		*WIRING -ENGINE	Not Necessary	3,474.00 FL	*- FL
83	1		*WIRING -FRONT	Not Necessary	3,802.10 FL	*- FL
84	1		*STEERING AIRBAG COMPLETE	Activated	1,090.90 FL	*1,090.90 FL
85	1		*AIRBAG CONTROL MODULE	Activated	1,243.70 FL	*1,243.70 FL
86	1		*KNEE CONTROL AIRBAG MODULE ASSY	Activated	578.60 FL	*578.60 FL
87	1		*AIR BAG ASSY -PASSENGER	Activated	1,951.20 FL	*1,951.20 FL
88	1		*STEERING ANGLE ASSY	Not Necessary	786.90 FL	*- FL
89	1		*SENSOR ASSY IMPACT -FRT INPACT	Not Necessary	643.90 FL	*- FL
90	2		*AIRBAG SENSOR	Activated	696.20 FL	*696.20 FL
91	2		*SAFETY BELT (ASSY) (LH/RH)	Rear Activated	626.40 FL	*626.40 FL
92	2		*SAFETY BELT BUCKLE (LH/RH)	Not Necessary	318.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	2		*REAR WHEELBEARING ING & HUB	Not Necessary	908.00 FL	*- FL
94	2		*REAR TRAILING ARM (LH/RH)	Not Necessary	530.80 FL	*- FL
95	2		*REAR ASSIST (LH/RH)	Not Necessary	455.80 FL	*- FL
96	2		*REAR SHOCK ABSORBER (LH/RH)	Not Necessary	461.00 FL	*- FL
97	2		*REAR SHOCK ABSORBER MOUNTING (LH/RH)	Not Necessary	266.20 FL	*- FL
98	1		*REAR CROSSMEMBER	Not Necessary	1,468.70 FL	*- FL
99	2		*STABILIZER BAR	Not Necessary	774.60 FL	*- FL
100	2		*STABILIZER LINK	Not Necessary	294.60 FL	*- FL
101	2		*REAR UPPER ARM (LH/RH)	Not Necessary	479.00 FL	*- FL
102	2		*REAR LOWER ARM (LH/RH)	Not Necessary	786.20 FL	*- FL
103	2		*REAR KNUCKLE ARM (LH/RH)	Not Necessary	1,076.20 FL	*- FL
104	1		*FRONT DOOR COMFORT LOGO (LH/RH)	Not Necessary	75.00 FS	*- FS
105	1		*EMBLEM -BLUE DRIVE (LH/RH)	N/S Necessary/O/SNot Necessary	53.20 F	*26.60 FN
106	1		*FRONT NUMBER PLATE	Dislodged	25.00 FS	*25.00 FS
107	1		*FRONT NO PLATE TRIM COVER	Dislodged	30.00 FS	*30.00 FS
108	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
109	1		*FRONT ERP STICKER	Necessary	30.00 FS	*30.00 FS
110	2		*FRONT TYRE (LH/RH)	Not Necessary	432.00 FS	*- FS
111	1		*UNIT ASSY -SMART CRU (RADAR SENSOR)	Mtg Cracked / Dented	2,910.90 FL	*2,910.90 FL
112	1		*AIR CLEANER ASSY	Broken	836.50 FL	*836.50 FL
113	1		*ENGINE CROSSMEMBER	Front Distorted	1,803.90 FL	*1,803.90 FL
114	1		*ELECTRIC CLUTCH PUMP	Broken	4,831.80 FL	*4,831.80 FL
115	1		*ELECTRIC CLUTCH PUMP FLUID TANK	Broken	688.70 FL	*250.00 FL
116	1		*INVERTER ELECTRIC WATER PUMP	Broken	1,383.50 FL	*1,383.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	87,370.00	37,410.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	17,335.76	7,450.64
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	5.32

Total Parts (\$\$)	70,034.24	29,954.84
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	150.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	60.00	0.00
6	FRONT CHASSIS ALIGNMENT CHARGE	New	400.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	800.00	200.00
8	TRANSFER OF DOOR	New	120.00	0.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	0.00
10	4 WHEEL ALIGNMENT	New	120.00	60.00
11	REMOVE/REIX RADIATOR	New	90.00	50.00
12	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
13	REMOVE/REFIX ENGINE	New	500.00	0.00
14	REMOVE /REFIX DASHBOARD	New	450.00	180.00
15	REMOVE/REFIX FUSE BOX	New	180.00	0.00
16	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
17	RE-SET FRT ABS SYSTEM }	New	200.00	320.00
18	RE-SET REAR ABS SYSTEM }	New	400.00	0.00
19	RE-SET FRT POWER WINDOW SYSTEM }	New	200.00	0.00
20	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
Gross Labour Cost (\$\$)			8,370.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >