

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20003169/QEA3N2

**Date:** 19/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993863

**Claimant**  
**Vehicle No :** SLK3144Z **Insured Vehicle No :** SMF9064X

Date of Loss: 21/02/2020 Nature of Claim: TP Claim No: 7520484934SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLK3144Z</b>		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Engine No:	P520422697
Reg. Date:	12/01/2017 (Man. Year: 2016)	Chassis No:	JM6BN22A8H0137022
Colour:	Blue	Odometer:	207072 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,329.00	3,872.76	3,456.24	47.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,450.00	1,350.00	48.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,129.00</b>	<b>5,322.76</b>	<b>4,806.24</b>	<b>47.45</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,250.00</b>		
<b>(\$\$)</b>	10,129.00	4,250.00	5,879.00	58.04
<b>+ GST 7.00/7.00% (\$\$)</b>	709.03	297.50	411.53	58.04
<b>Nett Amount (\$\$)</b>	<b>10,838.03</b>	<b>4,547.50</b>	<b>6,290.53</b>	<b>58.04</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>4,854.95</b>		

### INSPECTION

Date of Assignment: 25/02/2020

Date Inspected: 25/02/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)  
1090 LOWER DELTA ROAD #05-12  
Singapore 169201

Estimated Period of Repair: 4.0 days

---

**Adjuster:** OI SUN PIN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,200.40 FL	*1,068.00 FL
2	1		*FRONT BONNET LOCK	Serviceable	251.10 FL	*- FL
3	1		*FRONT BONNET LOCK CATCH	Serviceable	180.00 FL	*- FL
4	1		*FRONT SUPPORT PANEL	Serviceable	493.50 FL	*- FL
5	1		*F/R HEADLAMP	Serviceable	1,200.00 FL	*- FL
6	1		*F/L HEADLAMP	Crumpled	1,200.00 FL	*1,200.00 FL
7	1		*FRONT BUMPER	Crumpled	1,100.00 FL	*1,100.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Serviceable	466.85 FL	*- FL
9	1		*FRONT BUMPER LH SIGNAL LAMP	Crumpled	174.70 FL	*174.70 FL
10	1		*FRONT BUMPER RH SIGNAL LAMP	Serviceable	174.70 FL	*- FL
11	1		*FRONT BUMPER TOP PANEL	Crumpled	350.00 FL	*350.00 FL
12	1		*RADIATOR GRILLE NOSE PANEL	Crumpled	680.00 FL	*581.00 FL
13	1		*RADIATOR GRILLE CENTER BRACKET	Serviceable	165.00 FL	*- FL
14	1		*RADIATOR GRILLE MAZDA LOGO	Serviceable	60.00 FL	*- FL
15	1		*RADIATOR GRILLE LH SIDE GRILLE BLACK	Cracked	120.00 FL	*50.00 FL
16	1		*RADIATOR GRILLE RH SIDE GRILLE BLACK	Serviceable	120.00 FL	*- FL
17	1		*RADIATOR GRILLE CHROME RH MOULDING	Serviceable	350.00 FL	*- FL
18	1		*RADIATOR GRILLE CHROME LH MOULDING	Scratched	350.00 FL	*200.00 FL
19	1		*RADIATOR GRILLE LH CHROME TRIM INNER SEAL	Not Necessary	80.00 FL	*- FL
20	1		*RADIATOR GRILLE RH CHROME TRIM INNER SEAL	Not Necessary	80.00 FL	*- FL
21	1		*RADIATOR GRILLE INNER LH BRACKET	Cracked	36.00 FL	*36.00 FL
22	1		*RADIATOR GRILLE INNER RH BRACKET	Not Necessary	36.00 FL	*- FL
23	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	68.00 FL	*- FL
24	1		*BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
25	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,116.25</b>	<b>4,824.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,787.25</b>	<b>951.94</b>
<b>Total Parts (\$\$)</b>	<b>7,329.00</b>	<b>3,872.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO LABOUR CHARGE FOR REMOVING OUT FRONT SUPPORT PANEL ,FRONT BONNET ,FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	750.00
2	TO RESPRAY FRONT BONNET ,FRONT SUPPORT PANEL ,FRONT BUMPER	New	1,600.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,800.00</b>	<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >