

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003171/AEA3N2
Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800094602
Claimant
Vehicle No : SKX314M **Insured Vehicle No :** SDR8182M
 Date of Loss: 21/02/2020 Nature of Claim: TP Claim No: 3145267500SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX314M**
 Make & Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A) Engine No: CVK058292
 Reg. Date: 26/04/2018 (Man. Year: 2018) Chassis No: WAUZZZF47JA142267
 Colour: Grey Odometer: 37609 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,825.80	1,656.00	3,169.80	65.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	630.00	400.00	38.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,855.80	2,286.00	3,569.80	60.96
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	5,855.80	1,800.00	4,055.80	69.26
+ GST 7.00/7.00% (S\$)	409.91	126.00	283.91	69.26
Nett Amount (S\$)	6,265.71	1,926.00	4,339.71	69.26
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		2,326.00		

INSPECTION

Date of Assignment: 24/02/2020
 Date Inspected: 24/02/2020 Inspected At: J-mart Motor Pte Ltd (HQ)
 Blk 5 Defu Lane 10, #01-578
 Singapore 539186
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER	Repair	2,466.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	1,840.00 FL	*1,840.00 FL
3	1		*REAR BUMPER RH REFLECTOR	Not Necessary	76.00 FL	*- FL
4	1		*RH TAILLAMP	Not Necessary	980.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,362.00	1,840.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	536.20	184.00
Total Parts (\$\$)	4,825.80	1,656.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	500.00	200.00
2	SPRAY PAINTIGN	New	500.00	400.00
3	WIRING	New	30.00	30.00
			Gross Labour Cost (S\$)	630.00
			1,030.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >