

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003175/T1EA3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100502610
Claimant
Vehicle No : SMA114X **Insured Vehicle No :** SLL4942A
Date of Loss: 20/02/2020 **Nature of Claim:** TP **Claim No:** 7234402994SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA114X**
 Make & Model: VOLKSWAGEN PASSAT B8, 1.8 TFSI (A) Engine No: CJS288317
 Reg. Date: 16/07/2018 (Man. Year: 2018) Chassis No: WVVZZZ3CZJE222540
 Colour: Black Odometer: 35452 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,970.80	2,970.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	4,440.00	2,880.00	39.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,290.80	7,410.80	2,880.00	27.99
+ GST 7.00/7.00% (S\$)	720.36	518.76	201.60	27.99
Nett Amount (S\$)	11,011.16	7,929.56	3,081.60	27.99
+ Loss of Use (7.0 x S\$90.00/day) (S\$)		630.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		180.00		
Nett Liability (S\$)		8,741.56		

INSPECTION

Date of Assignment: 27/02/2020
 Date Inspected: 27/02/2020 Inspected At: Volkswagen Group Singapore Pte Ltd
 247 Alexandra Road
 Singapore 159934
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,486.25 FS	*1,486.25 FS
2	1		*GUIDE PIECE (BUMPER BRACKET RHS)	Necessary	39.51 FS	*39.51 FS
3	1		*SET SENSOR BRACKET	Necessary	42.59 FS	*42.59 FS
4	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
5	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
6	1		*FENDER	Bent	642.60 FS	*642.60 FS
7	1		*REAR VIEW MIRROR HOUSING	Cut	624.51 FS	*624.51 FS
Total Parts (\$)					2,970.80	2,970.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	3,200.00	2,000.00
Gross Labour Cost (\$\$)			7,320.00	4,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >