

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20003176/EGA3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJP7369M	Insured Vehicle No :	SHA1231T
Date of Loss: 24/02/2020	Nature of Claim: TP	Claim No: MCT20020489

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP7369M		
Make & Model:	BMW 218I, 1.5 ACTIVE TOURER D/AB LED DSC AB (A)	Engine No:	32985247B38A15A
Reg. Date:	31/05/2018 (Man. Year: 2018)	Chassis No:	WBA2A320307A00912
Colour:	Silver	Odometer:	30592 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,556.70	1,125.45	1,431.25	55.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	1,934.00	733.00	27.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,223.70	3,059.45	2,164.25	41.43
+ GST 7.00/7.00% (S\$)	365.66	214.16	151.50	41.43
Nett Amount (S\$)	5,589.36	3,273.61	2,315.75	41.43
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
Nett Liability (S\$)		3,513.61		

INSPECTION

Date of Assignment:	09/03/2020	
Date Inspected:	09/03/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2020)
Parts:	M1-MPV	BMW 218I 1.5 ACTIVE TOURER D/AB LED DSC AB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP7369M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER PANEL PRIMED (PD)	Dented	1,045.45 FS	*1,045.45 FS
3	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	61.35 FS	*- FS
4	1		*REAR BUMPER CARRIER	Not Necessary	460.40 FS	*- FS
5	1		*SUPPORT	Not Necessary	45.55 FS	*- FS
6	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	60.70 FS	*- FS
7	2		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	10.20 FS	*- FS
8	2		*ULTRASONIC SENSOR GLACIERSIL	Not Necessary	740.00 FS	*- FS
9	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,556.70	1,125.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	934.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,667.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >