

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20003177/ESF3E2

**Date:** 20/07/2020

### REFERENCE

Insured/Claimant: NG SIEW CHYE PETER VINCENT  
Date of Loss: 21/02/2020

Policy No:  
Nature of Claim: OD Claim No: 2990097247SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLD9595C</b>		
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Engine No:	DAX055837
Reg. Date:	27/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF8K2091084
Colour:	Grey	Odometer:	7054 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$194,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,660.84	15,152.96	10,507.88	40.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,412.00	12,557.00	8,855.00	41.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>47,072.84</b>	<b>27,709.96</b>	<b>19,362.88</b>	<b>41.13</b>
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	46,572.84	27,209.96	19,362.88	41.58
<b>+ GST 7.00/7.00% (S\$)</b>	3,260.10	1,904.70	1,355.40	41.58
<b>Nett Amount (S\$)</b>	<b>49,832.94</b>	<b>29,114.66</b>	<b>20,718.28</b>	<b>41.58</b>

### INSPECTION

Date of Assignment: 26/02/2020  
Date Inspected: 25/02/2020 Inspected At:

281 Alexandra Road  
Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 12.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Dented	1,344.00 FS	*1,075.20 FS
2	1		*FRONT FENDER BRACKET - RH	Not Necessary	17.00 FS	*- FS
3	1		*FRONT FENDER CENTRE BRACKET - RH	Not Necessary	17.00 FS	*- FS
4	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	98.00 FS	*- FS
5	1		*S-LINE INSCRIPTION	Necessary	117.00 FS	*93.20 FS
6	2		*FRONT WHEEL COVER - LH / RH	Cut	1,190.00 FS	*952.00 FS
7	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	248.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	36.00 FS	*- FS
9	1		*FRONT DOOR - RH	Dented	2,972.00 FS	*2,377.60 FS
10	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
11	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
12	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	249.00 FS	*- FS
13	1		*FRONT DOOR OUTER SEAL - RH	Necessary	193.00 FS	*154.40 FS
14	1		*FRONT DOOR CATCH	Bent	137.00 FS	*109.60 FS
15	1		*FRONT DOOR COVER - RH	Crushed	683.00 FS	*546.00 FS
16	1		*EXTERIOR MIRROR MOUNTING	Broken	1,647.00 FS	*1,317.60 FS
17	1		*MIRROR CAP - RH	Missing	445.00 FS	*355.60 FS
18	1		*MIRROR GLASS - RH	Missing	1,797.00 FS	*1,437.60 FS
19	1		*CORNER TRIM - RH	Cut	43.00 FS	*34.08 FS
20	1		*WINDOW GUIDE TRIM STRIP - RH	Cut	320.00 FS	*256.00 FS
21	1		*FRONT WINDOW SLOT SEAL - RH	Cut	580.00 FS	*463.60 FS
22	1		*WATER DEFLECTOR STRIP - RH	Not Necessary	63.00 FS	*- FS
23	1		*WINDOW GUIDE - RH	Not Necessary	454.00 FS	*- FS
24	1		*PILLAR A/B SECTIONAL PART - RH	Dented	3,380.00 FS	*2,704.00 FS
25	1		*BONNET	Repair	3,824.00 FS	*- FS
26	1		*BONNET ATTACHMENT PARTS	Not Necessary	133.00 FS	*- FS
27	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	26.00 FS	*- FS
28	2		*BONNET IMPACT PROTECTION - LH / RH	Not Necessary	52.00 FS	*- FS
29	1		*FRONT WINDSCREEN	Necessary	1,357.00 FS	*1,085.60 FS
30	1		*RAIN SENSOR GEL FOIL	Necessary	130.00 FS	*104.00 FS
31	1		*RAIN SENSOR RETAINING SPRING	Necessary	20.00 FS	*14.80 FS
32	1		*FRONT DOOR WINDOW - RH	Cut	278.00 FS	*222.00 FS
33	1		*FRONT ALUMINIUM RIM - RH	Cut	954.00 FS	*762.80 FS
34	1		*FRONT TYRE - RH	Torn	1,193.00 FS	*414.00 FS
35	1		*FRONT DOOR HINGE HALF UPPER PART - RH UPPER	Not Necessary	43.00 FS	*- FS
36	1		*FRONT DOOR HINGE HALF LOWER PART - RH UPPER	Not Necessary	43.00 FS	*- FS
37	1		*FRONT DOOR HINGE HALF UPPER PART - RH LOWER	Not Necessary	43.00 FS	*- FS
38	1		*FRONT DOOR HINGE HALF LOWER PART - RH LOWER	Not Necessary	43.00 FS	*- FS
39	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
40	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
41	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
42	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
43	1		*SUNDRIES	Necessary	600.00 FS	*34.72 FS
44	1		*FRONT FENDER INNER TOP COVER	Broken	23.20 FS	*23.20 FS
45	1		*FRONT FENDER INNER TOP OUTER COVER	Broken	58.64 FS	*58.64 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 25,660.84 15,152.96**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY AND RHS DOOR WINDOW GLASS	New	400.00	400.00
3	TO RENEW FRONT WINDSCREEN TO FACILITATE A-PILLAR RENEWAL	New	480.00	480.00
4	TO INSTALL FRONT WINDSCREEN AND RHS FRONT DOOR WINDOW GLASS SOLAR FILM	New	600.00	600.00
5	TO DISLODGE AND REINSTALL RHS A-PILLAR AND RHS FRONT DOOR HARNESS, MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	780.00	780.00
6	TO REMOVE AND REINSTALL CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	3,200.00
7	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
8	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS FRONT DOOR. CUT OUT AND REWELD RHS A-PILLAR. TO RENEW RHS FRONT FENDER, BONNET AND RHS FRONT DOOR. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	3,500.00
9	TO RESPRAY RHS FRONT FENDER, BONNET, RHS A-PILLAR, DOOR ENTRANCES, RHS FRONT DOOR, DOOR COVER, RHS WING MIRROR COVER AND BOTH FRONT WHEEL ARCH TRIMS. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT	New	6,000.00	3,125.00
10	TO RENEW RHS FRONT RIM AND TYRE. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
11	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>21,412.00</b>	<b>12,557.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >