

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003193/KSF3Q2

Date: 02/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30767519000
Claimant Vehicle No :	PC6161Z	Insured Vehicle No :	GBH8713H
Date of Loss:	20/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D206080/C02/GBH8713H/CHUA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6161Z	Engine No:	6HK1486015
Make & Model:	ISUZU LT134P, 7.8 D (A)	Chassis No:	JALLT134P97000090
Reg. Date:	24/02/2010 (Man. Year: 2009)	Odometer:	412750 km
Colour:	Multi-colour		
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	11R22.5	Rear Tyre Size:	11R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Linglong 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Linglong 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,762.49	2,916.75	11,845.74	80.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,860.00	1,400.00	4,460.00	76.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,622.49	4,316.75	16,305.74	79.07
Approved Total (Overridden) (\$\$)		3,400.00		
Nett Amount (\$\$)	20,622.49	3,400.00	17,222.49	83.51

INSPECTION

Date of Assignment:	29/10/2020	
Date Inspected:	03/04/2020 Inspected At:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265 Singapore 569536
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Nov 2020)	
Parts:	N/A	ISUZU LT134P 7.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6161Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR ENGINE COVER OUTER HANDLE	Not Necessary	85.50 FL	*- FL
2	2		*REAR ENGINE COVER DAMPER	Serviceable	780.00 FL	*- FL
3	1		*REAR ENGINE COVER (FIBRE WITH VENTILATOR)	Not Necessary	5,244.00 FL	*- FL
4	1		*REAR ENGINE COVER HANDLE WITH LOCK	Repair	265.80 FL	*- FL
5	2		*REAR ENGINE COVER HINGE	Repair	410.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,288.00 FL	*- FL
7	1		*REAR BUMPER (FIBRE)	Bent	3,255.00 FL	*3,255.00 FL
8	2		*REAR BUMPER SUPPORT BRACKET	Repair	440.00 FL	*- FL
9	2		*REAR BUMPER BEAM	Not Necessary	1,300.00 FL	*- FL
10	2		*REAR LH & RH BUMPER SIDE PANEL	Serviceable	776.40 FL	*- FL
11	2		*REAR LH & RH TAIL LAMP ASSY	Serviceable	1,760.00 FL	*- FL
12	2		*REAR ENGINE COVER ADJUSTER HINGES	Repair	310.00 FL	*- FL
13	1		*60KM/H STICKER	Serviceable	35.00 FS	*- FS
14	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
15	1		*REAR NUMBER PLATE CHROME GARNISH WITH LIGHT BULB	Cracked	150.00 FS	*150.00 FS
16	1		*REAR FIRE INSULATION FOAM FOR REAR BUMPER AND REAR ENGINE COVER	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,149.70	3,405.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	2,387.21	488.25
Total Parts (\$\$)	14,762.49	2,916.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK OUT THE ACCIDENT DAMAGED PORTION.TO PANEL BEATING;;RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,800.00	600.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON ACCIDENT DAMAGE AREA AND OTHER AFFECTED AREA/PANEL	New	3,200.00	800.00
3	TO SPRAY UNDER-CARRIAGE INSULATION FOAM	New	480.00	0.00
4	TO CUT AND WELD EXHAUST SILENCER AND EXHAUST MOULDING/BRACKET AND REFIX	New	380.00	0.00
Gross Labour Cost (\$\$)			5,860.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >