

ASS. REC. BY:

REF:

C72 / 20003193 / KSP3

## ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC 61617

Yr Regn:

02, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Isuzu

c.c

7780

Colour

Multi Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

412750

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JALUT134P - P7000 PC

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175R16

Ling R: Long 11R 22.5 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

20/12/19

D.O.I.

3/4/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA &amp; EM not in wksp.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	331D

### Vehicle Details

Vehicle No.:	PC6161Z
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2020
Vehicle Make:	ISUZU
Vehicle Model:	LT134P
Primary Colour:	Multicolor
Manufacturing Year:	2009
Engine No.:	6HK1486015
Chassis No.:	JALLT134P97000090
Maximum Power Output:	-
Open Market Value:	\$103,394.00
Original Registration Date:	24 Feb 2010
First Registration Date:	24 Feb 2010
Transfer Count:	2
Actual ARF Paid:	\$5,170.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	23 Feb 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$17,000.00
COE Rebate Amount:	\$43.00
<b>Total Rebate Amount:</b>	<b>\$43.00</b>

The information contained herein is correct as at 14 Feb 2020

OK

**SERVE YOU MOTOR SERVICE**  
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2  
 #01-265, SINGAPORE 569536  
 TEL. NO: 64810555 / FAX NO. 64831654  
 E-MAIL: elainesyms@gmail.com

*Not Authorise*  
*11 Sep 87*  
*Runny After Paint*  
*4 days*

INS: CHINA TAIPING INSURANCE SINGAPORE PTE LTD

OWNER: CITY TRANSIT PTE LTD

Registration no. : PC 6161 Z / ISUZU LT134P

Date : 25-Feb-20

DOA: 20.12.2019

Quotation No. : CM191208

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Rear engine cover outer handle	\$85.50
2	2	Rear engine cover damper \$390 each	\$780.00 X
3	1	Rear engine cover (fibre with ventilator)	\$5,244.00 ?
4	1	Rear engine cover handle with lock	\$265.80 X
5	2	Rear engine cover hinge \$205 each	\$410.00 X
6	1	Rear bumper reinforcement	\$1,288.00 ?
7	1	Rear bumper (fibre)	\$3,255.00 ✓
8	2	Rear bumper support bracket \$220 each	\$440.00 X
9	2	Rear bumper beam \$650 each	\$1,300.00 ?
10	2	Rear LH&RH bumper side panel \$388.20 each	\$776.40 X
11	2	Rear LH&RH tail lamp assy \$880 each	\$1,760.00 X
12	2	Rear engine cover adjuster hinges \$155 each	\$310.00 X
			<hr/> \$15,914.70
			Less 15 % \$2,387.21
			<hr/> Total: \$13,527.50

SPECIAL NETT ITEMS

1	1	60 km/h sticker
2	1	Rear number plate
3	1	Rear number plate chrome garnish with light bulb
4	1	Rear fire insulation foam for rear bumper and rear engine cover

Total:

*15 Jan*  
*my* \$35.00  
*cm* \$50.00 X  
*cm* \$150.00 ✓  


---

\$1,000.00 ?  


---

\$1,235.00

LABOUR & MISC CHARGES

1	To knock out the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.
2	Supply spray paint material and necessary items to respray on accident damage area and other affected area / panel.
3	To spray under-carriage insulation foam.
4	To cut and weld exhaust silencer and exhaust moulding/ bracket and refix.

*Good*  
 \$1,800.00

*Good*  
 \$3,200.00

\$480.00 ?

*na* \$380.00 X

<b>TOTAL</b>		\$5,860.00
<b>Total Parts and Labour Cost of Repair</b>		<hr/> \$ <b>20,622.50</b>