

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3590C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER LH	TO REPAIR SEE LABOUR	945.30	-
1	FRT FENDER LINING LH	NOT NECESSARY	196.60	-
1	FRT FENDER HYBRID EMBLEM	NECESSARY	53.50	53.50
1	FRONT BUMPER ASSY	TO REPAIR SEE LABOUR	499.90	-
1	FRT LH FOG LH	SCRATCHED	920.00	920.00
	LESS 25% DISCOUNT		-653.83	-243.38
			1,961.47	730.12
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT FENDER LH AND FRONT BUMPER ASSY.		760.00	640.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	CHECK WIRING.		60.00	50.00
	TUFF COAT.		80.00	50.00
			1,500.00	1,140.00
GRAND TOTAL			3,461.47	1,870.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,500.00

Report Ref No. NS/INC20003199/Ftd3e2


PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.