

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003218/QES3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994128

Claimant
Vehicle No : SHB5349G **Insured Vehicle No :** GX2005P

Date of Loss: 21/02/2020 Nature of Claim: TP Claim No: 6515804908SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5349G		Engine No:	2ZRS109146
Make & Model:	TOYOTA PRIUS, 1.8 (A)		Chassis No:	JTDKB3FU303575478
Reg. Date:	30/11/2017 (Man. Year: 2017)		Odometer:	252843 km
Colour:	Maroon			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,783.10	8,333.44	28,449.66	77.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,030.00	2,160.00	2,870.00	57.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	41,813.10	10,493.44	31,319.66	74.90
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (7.0 x S\$112.35/day) (S\$)		786.45		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		11,386.89		

INSPECTION

Date of Assignment: 24/02/2020

Date Inspected: 24/02/2020 Inspected At: SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUPPORT S/A UPPER (DISC 25%)	Bent	364.90 F	*273.68 F
2	1		*COOLANT (DISC 25%)	Necessary	12.30 F	*9.23 F
3	1		*COVER ,FR BUMPER (DISC 25%)	Crumpled	495.50 F	*371.63 F
4	1		*COVER ,FR BUMPER LH (DISC 25%)	Missing	28.10 F	*21.08 F
5	1		*COVER ,FR BUMPER RH (DISC 25%)	Missing	28.10 F	*21.08 F
6	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
7	1		*GRILLE SUB-ASSY (DISC 25%)	Crumpled	335.60 F	*251.70 F
8	1		*EMBLEM ASSY FRONT (DISC 25%)	Crumpled	87.10 F	*65.33 F
9	1		*GRILLE ,RADIATOR (DISC 25%)	Crumpled	165.00 F	*123.75 F
10	1		*BRACKET ,FR BUMPER (DISC 25%)	Cracked	99.80 F	*74.85 F
11	1		*SUPPORT ,FR BUMPER LH (DISC 25%)	Broken	82.30 F	*61.73 F
12	1		*SUPPORT ,FR BUMPER RH (DISC 25%)	Broken	76.90 F	*57.68 F
13	1		*ABSORBER ,FR BUMPER (DISC 25%)	Crumpled	70.30 F	*52.73 F
14	1		*REINFORCEMENT FRONT UPPER (DISC 25%)	Bent	691.10 F	*518.33 F
15	1		*HOOD SUB-ASSY (DISC 25%)	Dented	938.40 F	*703.80 F
16	1		*HINGE ASSY ,HOOD ,LH (DISC 25%)	Bent	57.00 F	*42.75 F
17	1		*HINGE ASSY ,HOOD ,RH (DISC 25%)	Bent	57.00 F	*42.75 F
18	1		*COVER ,RADIATOR (DISC 25%)	Crumpled	227.80 F	*170.85 F
19	1		*INLET ,AIR CLEANER NO 2 (DISC 25%)	Crumpled	93.90 F	*70.43 F
20	1		*INLET ,AIR CLEANER NO 3 (DISC 25%)	Crumpled	35.30 F	*26.48 F
21	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
22	1		*SUPPORT S/A LH (DISC 25%)	Bent	237.00 F	*177.75 F
23	1		*SUPPORT S/A RH (DISC 25%)	Bent	237.00 F	*177.75 F
24	1		*SEAL ,HOOD TO FR END (DISC 25%)	Cut	24.40 F	*18.30 F
25	1		*ABSORBER ,FR BUMPER LOWER (DISC 25%)	Cracked	117.00 F	*87.75 F
26	1		*COVER ASSY ,ENGINE (DISC 25%)	Crumpled	180.10 F	*135.08 F
27	1		*UNIT ,HEADLAMP ,LH (DISC 10%)	Crumpled	2,558.90 F	*2,303.01 F
28	1		*UNIT ,HEADLAMP ,RH (DISC 10%)	Crumpled	2,558.90 F	*2,303.01 F
29	1		*NUMBER PLATE (SN)	Missing	35.00 F	*35.00 F
30	1		*NUMBER PLATE FRAME (SN)	Missing	25.00 F	*25.00 F
31	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
32	1		*FENDER SUB-ASSY ,FR LH	Repair	933.10 F	*- F
33	1		*PANEL SUB-ASSY ,FRONT DOOR LH	Repair	1,249.60 F	*- F
34	1		*SUPPORT SUB-ASSY LOWER	Serviceable	397.40 F	*- F
35	1		*SUPPORT S/A LH	Serviceable	237.00 F	*- F
36	1		*SUPPORT S/A RH	Serviceable	237.00 F	*- F
37	1		*BRACE ,HOOD LOCK SUPPORT	Serviceable	76.20 F	*- F
38	1		*SUPPORT ,RADIATOR UPPER LH	Serviceable	76.70 F	*- F
39	1		*SUPPORT ,RADIATOR UPPER RH	Serviceable	76.70 F	*- F
40	1		*COMPUTER SUB-ASSY HEADLAMP ,LH NO.1	Serviceable	486.40 F	*- F
41	1		*COMPUTER SUB-ASSY HEADLAMP ,LH NO.1	Serviceable	486.40 F	*- F
42	1		*HORN ASSY ,HIGH	Serviceable	112.80 F	*- F
43	1		*HORN ASSY ,LOW	Serviceable	112.80 F	*- F
44	1		*AIR CON CONDENSER ASSY	Serviceable	1,317.70 F	*- F
45	1		*TUBE & ACCESSORY	Serviceable	574.40 F	*- F
46	1		*HOSE SUB-ASSY DISCHARGE	Serviceable	337.10 F	*- F
47	1		*GUIDE ,RADIATOR AIR	Serviceable	93.90 F	*- F
48	1		*GUIDE ,RADIATOR AIR ,UPPER	Serviceable	44.70 F	*- F
49	1		*GUIDE ,RADIATOR AIR ,LH	Serviceable	58.80 F	*- F
50	1		*GUIDE ,RADIATOR AIR ,RH	Serviceable	54.60 F	*- F
51	1		*SEAL ,RADIATOR TO RH	Serviceable	24.80 F	*- F
52	1		*SEAL ,RADIATOR TO LH	Serviceable	24.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*RADIATOR ASSY	Serviceable	1,841.10 F	*- F
54	1		*FAN RADIATOR ,LH	Serviceable	181.80 F	*- F
55	1		*FAN RADIATOR ,RH	Serviceable	233.00 F	*- F
56	1		*FAN SUPPORT RADIATOR	Serviceable	219.30 F	*- F
57	1		*MOTOR ,COOLING FAN ,LH	Serviceable	543.50 F	*- F
58	1		*MOTOR ,COOLING FAN ,RH	Serviceable	443.40 F	*- F
59	1		*HOSE ,RADIATOR ,NO .1	Serviceable	42.60 F	*- F
60	1		*HOSE ,RADIATOR ,NO .2	Serviceable	40.20 F	*- F
61	1		*HOSE ,WATER BYPASS ,NO.1	Serviceable	37.40 F	*- F
62	1		*HOSE ,WATER BYPASS ,NO.2	Serviceable	37.40 F	*- F
63	1		*HOSE ,WATER BYPASS ,NO.3	Serviceable	20.10 F	*- F
64	1		*HOSE ,WATER BYPASS ,NO.4	Serviceable	13.20 F	*- F
65	1		*PIPE ,WATER BYPASS ,NO.1	Serviceable	11.00 F	*- F
66	1		*PIPE ,WATER BYPASS ,NO.2	Serviceable	11.00 F	*- F
67	1		*WIPER WASHER INLET	Serviceable	55.40 F	*- F
68	1		*WIPER WASHER JAR	Serviceable	183.60 F	*- F
69	1		*SEAL ,HOOD TO FR END	Serviceable	24.40 F	*- F
70	1		*ABSORBER ,FR BUMPER LOWER	Serviceable	117.00 F	*- F
71	1		*REINFORCEMENT FRONT LOWER	Serviceable	238.50 F	*- F
72	1		*EXTENSION SUBASSY ,LH	Serviceable	116.30 F	*- F
73	1		*EXTENSION SUBASSY ,RH	Serviceable	116.30 F	*- F
74	1		*LAMP ASSY ,FOG ,LH	Serviceable	910.20 F	*- F
75	1		*LAMP ASSY ,FOG ,RH	Serviceable	910.20 F	*- F
76	1		*COVER ASSY ,ENGINE	Serviceable	180.10 F	*- F
77	1		*INSULATOR ,HOOD	Serviceable	393.90 F	*- F
78	1		*LOCK ASSY ,HOOD	Serviceable	131.10 F	*- F
79	1		*CABLE ASSY ,HOOD	Serviceable	53.20 F	*- F
80	1		*THERMISTOR ASSY	Serviceable	68.00 F	*- F
81	1		*INVERTER WATER PUMP ASSY	Serviceable	432.00 F	*- F
82	1		*HOSE HV WATER PUMP INLET	Serviceable	37.90 F	*- F
83	1		*HOSE HV WATER PUMP OUTLET	Serviceable	29.60 F	*- F
84	1		*TANK ASSY ,INVERTER RESERVE	Serviceable	371.30 F	*- F
85	1		*HOSE ,INVERTER COOLING INLET	Serviceable	43.10 F	*- F
86	1		*HOSE ,INVERTER COOLING OUTLET	Serviceable	29.60 F	*- F
87	1		*HOSE ,INVERTER RADIATOR INLET	Serviceable	40.70 F	*- F
88	1		*WIRE ,ENGINE ROOM MAIN	Serviceable	6,138.00 F	*- F
89	1		*BATTERY	Serviceable	1,584.90 F	*- F
90	1		*CLAMP SUB-ASSY BATTERY	Serviceable	41.40 F	*- F
91	1		*CLAMP ,BATTERY ,NO.2	Serviceable	43.30 F	*- F
92	1		*INLET ,AIR CLEANER ,NO 1	Serviceable	130.50 F	*- F
93	1		*RESONATOR ,INTAKE AIR	Serviceable	14.90 F	*- F
94	1		*BRACKET AIR CLEANER	Serviceable	26.90 F	*- F
95	1		*AIR CLEANER ASSY	Serviceable	956.20 F	*- F
96	1		*FENDER SUB-ASSY ,FR RH	Serviceable	933.10 F	*- F
97	1		*EMBLEM SIDE PANEL (HYBRID)	Serviceable	52.90 F	*- F
98	1		*SEAL SUB-ASSY ,RH	Serviceable	50.20 F	*- F
99	1		*LINER ,FR FENDER RH	Serviceable	198.40 F	*- F
100	1		*PAD ,FR WHEEL RH	Serviceable	57.70 F	*- F
101	1		*PROTECTOR ,FR FENDER LH	Serviceable	90.40 F	*- F
102	1		*SEAL SUB-ASSY ,LH	Serviceable	50.20 F	*- F
103	1		*LINER ,FR FENDER ,LH	Serviceable	194.30 F	*- F
104	1		*PAD ,FR WHEEL LH	Serviceable	57.70 F	*- F
105	1		*APRON SUB-ASSY ,FRONT FENDER ,LH	Serviceable	944.20 F	*- F

F=Franchise part.

Total Parts (S\$) **36,783.10** **8,333.44**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,352.00	900.00
2	SPRAY PAINT	New	2,628.00	1,100.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	30.00
5	TO TOP UP A/C GAS	New	120.00	70.00
6	TO REMOVE AND REFIT WIRE HARDESS	New	250.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	20.00
8	TO WASH AND VACUUM	New	60.00	0.00
9	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	New	120.00	20.00
10	TO CONDUCT RADIATOR PRESSURE CHECK	New	120.00	0.00
Gross Labour Cost (\$)			5,030.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >