Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003221/KBS3Q2

**Date:** 03/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800144338

Claimant
Vehicle No: SLK3541K

Insured Vehicle No: SMG1340X

Date of Loss: 25/02/2020 Nature of Claim: TP Claim No: 2092184961SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLK3541K

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR990124

Reg. Date: 13/01/2017 (Man. Year: 2017) Chassis No: JTDKB3FU603543723

Colour: Metallic Silver Odometer: 179269 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	630.59	136.95	493.64	78.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	580.47	193.60	386.87	66.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,211.06	330.55	880.51	72.71
+ GST 7.00/7.00% (S\$)	84.77	23.14	61.63	72.70
Nett Amount (S\$)	1,295.83	353.69	942.14	72.71
+ Car Rental (3.0 x S	\$69.94/day) (S\$)	209.82		
+ Doc/	Search Fee (S\$)	7.45		
N	ett Liability (S\$)	570.96		

**INSPECTION** 

Date of Assignment: 25/02/2020

Date Inspected: 26/02/2020 Inspected At: 385 SIN MING DRIVE

Repairer:Esteem Performance Pte Ltd

(HQ)

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Not Necessary	450.80 FL	*-FL	
2	1		*FRT BMP CLIP	Not Necessary	40.00 FL	*-FL	
3	1		*FRT BMP LH	Serviceable	107.20 FL	*- FL	
4	1		*FRT BMP RH	Serviceable	107.20 FL	*- FL	
5	1		*LHF HUB CAP	Dented / Cut	195.65 FL	*195.65 FL	
F=Franchise part. L=ListItemDisc.							
				Sub Total (S\$)	900.85	195.65	
	- List Item Discount on L Items 30.00/30.00% (S\$)			270.26	58.70		
				Total Parts (S\$)	630.59	136.95	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	45.0 WU X 50.00 SGD/H	New	225.00	25.00
2	LABOUR COST 50.0 WU X 50.00 SGD/H	New	250.00	140.00
3	MATERIAL COST	New	105.47	28.60
		Gross Labour Cost (S\$)	580.47	193.60
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >