Esteem Performance Pte Ltd 385 Sin Ming Drive, Vicom Vehicle Inspection Centre (575718)

Insurer Reference: SMG1340X Repairer Reference: 030192

Date calculated: 25/02/2020 6:22 PM

Full Report Registration: SLK3541K Printed: 25/02/2020 6:22 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

AIG Asia Pacific Insurance

Pte Ltd

Printed by:

Claim Reference:

Carmen SG SMG1340X

Currency: Date of Incident: SGD 25/02/20

Estimated Repair Time: Actual Repair Days:

Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration: VIN number: Odometer:

TOYOTA

PRIUS IV BASE MODEL

70 P5 01 SLK3541K

Not Witherite

Vehicle Condition

Vehicle Status


Pre-Accident Damage: Date of Inspection:

Damage Areas

AII Underbody

LKK Auto Consultants hence notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS			15.0	75.00
0742	R/F WING REPAIR		10	30.0*	150.00
	Labour Cost		Hrs	WU	
	Panel / Mechanical Labour		4.50	45.0	225.00
	Total of Labour				225.00
Paint					
Paint Work	SYSTEM AZT		Tim	ne Basis	10 WU/h
Code	Description			WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R			11.0	
	R/F WING REPAIR PAINTING <50%			11.0	
	BONNET SURFACE PAINT			8.0	
Paint Materia	al Per Part				
Code	Description				Price SGD
0283 0742 0471	FRONT BUMPER NEW PART PAINT K1R R/F WING REPAIR PAINTING <50% BONNET SURFACE PAINT				48.16 10.50 19.71
	Labour Cost - Paint Factor 5 Time Paint	0.00 SGD/h	Hrs	WU 30.0	Price SGD
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic Total	10 WII /b	0.30 5.00	3.0 50.0	15.00 250.00
	Total	10 WU/h	5.00	50.0	250.00
	Material Cost - Paint New Part Painting - Plastic K1R Repair Painting Surface-/Blend Paint Material-constant Metal Material-constant Plastic Total				Price SGD 48.16 10.50 19.71 18.10 9.00 105.47
Spare Part	s				

Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD	
FRONT BUMPER	52119 47962		450.80	7
FRT BMP CLIP	FRT BMP CLIP		40.00	
FRT BMP LH	SIDE RETAINER		آل 107.20)	<
FRT BMP RH	SIDE RETAINER		/m 107.20	X
LHF HUB CAP	LHF HUB CAP		Nell 6 195.65 L	/
	FRONT BUMPER FRT BMP CLIP FRT BMP LH FRT BMP RH	FRONT BUMPER 52119 47962 FRT BMP CLIP FRT BMP CLIP FRT BMP LH SIDE RETAINER FRT BMP RH SIDE RETAINER	FRONT BUMPER 52119 47962 FRT BMP CLIP FRT BMP CLIP FRT BMP LH SIDE RETAINER FRT BMP RH SIDE RETAINER	FRONT BUMPER 52119 47962 450.80 FRT BMP CLIP FRT BMP CLIP 40.00 FRT BMP LH SIDE RETAINER 107.20 FRT BMP RH SIDE RETAINER

f: OEM Parts

	0.00
Savings	900.85
Subtotal	-270.26
Subtotal Discount(+30.00%)	630.59
Total	

Final Calculation	SGD	SGD
Parts Total Discount(+30.00%) Total Parts	900.85 -270.26	630.59
Labour Time Base 10 WU/h Total 45.0 WU X 50.00 SGD/h Total of Labour	225.00	225.00
Paint Work Time Base 10 WU/h Labour Cost 50.0 WU X 50.00 SGD/h Material Cost Total Paint Including Material	250.00 105.47	355.47
		1,211.06
Repair Cost Excludes GST		84.77
GST (+7.0%) Repair Cost Included GST		1,295.83

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.