

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 5278Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER	CUT	265.00	265.00
1	FORK ASSY	* CHECK	850.00	-
1	LEFT HAND MIRROR	MISSING	165.00	165.00
1	LEFT HAND MIRROR BRACKET	MISSING	120.00	120.00
1	RH HAND BRAKE LEVER	CUT	65.00	65.00
1	HANDLE BAR	* CHECK	185.00	-
1	GRIP	CUT	85.00	85.00
1	STEERING CON	* CHECK	150.00	-
1	RIGHT HAND BODY BEADING TOP	CUT	85.00	85.00
1	LEFT HAND BODY BEADING TOP	CUT	85.00	85.00
1	RIGHT HAND BODY BEADING LOW	CUT	75.00	75.00
1	LEFT HAND BODY BEADING LOW	CUT	75.00	75.00
1	FOOT REST RUBBER SHIELD	TORN	65.00	65.00
1	MUFFLER ASSY	* CHECK	795.00	-
	LESS 10% DISCOUNT		-	-108.50
			3,065.00	976.50
	LABOUR			
	BODY WORK.		350.00	200.00
	SPRAY WORK.		480.00	300.00
	TRANSPORT.		80.00	60.00
	LABOUR.		500.00	250.00
			-	-
			-	-
			-	-
			1,410.00	810.00
	GRAND TOTAL		4,475.00	1,786.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$1,980.00 NETT)			1,400.00

Report Ref No. CC4/FCI20003236/T1da3q2





Report Ref No. CC4/FCI20003236/T1da3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.