

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20003237/Dpa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	15/04/2021	
	ATTN:SAW THEN	G		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLQ 2420B	Veh. Inspected	ł	SHC 8425U	
	Policy No.	P2364588	Coverage (\$)		0.00	
	Claim No.	S0M02HC0	Excess (\$)		0.00	
	Assign From		Assign Date		26/02/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	KMHLB41UMGU077328	Colour		BLUE	
	Odometer	434296 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE		5 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE		5 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE		5 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	17/02/2020	Inspection Dat	e	27/02/2020	
	Survey held at	BIFROST AUTO PTE LTD				
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				
	<del>- '</del>					