BIFROST AUTO PTE LTD

REPAIR ESTIMATE

| - | - | _ | _ | |
|-------|---|---|---|----|
| 1) A | | | _ | ٠ |
| - | ı | | _ | ٠. |

17-Feb-20

INSURANCE: ____AXA

MODEL:

HYUNDAI 140

VEHICLE NO.: SHC8425U

| | QTY | LIST PRICE | AMOUNT | |
|---|-----|----------------------|-----------------------------------|--------------|
| ONNET 1/54 | 1 | \$2,265.90 | \$2,265.90 | 1 |
| ONNET RUBBER (LH) ► トル | 1 | \$15.70 | \$15.70 | - |
| ONNET RUBBER (RH) | 1 | \$6.20 | \$6.20 | - |
| ONNET HINGE (LH/RH) NH | 2 | \$82.00 | \$164.00 | |
| ONNET LOCK MH | 1 | \$42.40 | \$42.40 | X |
| ONNET ABSORBER (LH ONLY) ► ► | 1 | \$61.60 | \$61.60 | X |
| ONNET INSULATOR HH | 1 | \$202.50 | \$202.50 | |
| ONNET SEAL HH | 1 | \$31.90 | \$31.90 | X |
| ONNET INSULATOR CLIPS MLI | 1 | \$7.00 | \$7.00 | × |
| ADIATOR GRILLE HEMBLEM NL | 1 | \$39.50 | \$39.50 | × |
| ADIATOR GRILLE HH | 1 | \$1,480.00 | \$1,480.00 | X |
| RONT BUMPER COVER Broken | 1 | \$1,052.20 | \$1,052.20 | |
| RONT BUMPER GRILLE (RH) ~~~ | 1 | \$49.20 | \$49.20 | X |
| RONT BUMPER BRACKET TOP (RH) | 1 | \$44.80 | \$44.80 | × |
| RONT BUMPER CENTRE GRILLE TOP GARNISH (140), N. S | . 1 | \$32.00 | \$32.00 | 4 |
| RONT BUMPER BRACKET (RH) hole (4.60) | 1 | \$49.20 | \$ 49 .20 | |
| RONT BUMPER SIDE BRACKET HLI | 1 | \$4.60 | \$4.60 | × |
| RONT BUMPER RETAINER MOUNTING LL | 1 | \$8.00 | \$8.00 | × |
| RONT BUMPER GRILLE AIR DUCT HH | 1 | \$26.20 | \$26.20 | 7 |
| EADLAMP SUPPORT PANEL ASSY borker | 1 | \$907.40 | \$907.40 | 1 |
| EADLAMP (LH/RH) 0/5 booker HIS NH / 1388.00) | 2 | \$2,776.00 | \$5,552.00 | 11 |
| EADLAMP SUPPORT TOP COVER HA | 1 | \$222.60 | \$222.60 | X |
| ADIATOR Hy | 1 | \$708.50 | \$708.50 | |
| ADIATOR FAN BLADE, COWLING, MOTOR ASSY NA | 1 | \$792.95 | \$792.95 | |
| ADIATOR BRACKET (LH/RH) HA | 2 | \$5.40 | \$10.80 | X |
| RONT FENDER (RH) Dean | 1 | \$566.30 | \$566.30 | - |
| CONT FENDER SHIELD (RH) 2 tom defined | 1 | \$174.90 | | 71 |
| RONT FENDER MUDFLAP (RH) HL | 1 | \$13.50 | \$13.50 | × |
| CONT FENDER RETAINER NA | 1 | \$3.00 | \$3.00 | X |
| RCON CONDENSER HL | 1 | \$947.80 | \$947.80 | × |
| ONT DOOR MIRROR SIDE GARNISH HW | 1 | \$225.00 | \$225.00 | |
| ONT DOOR (RH) NA | 1 | \$2,256.40 | \$2,256.40 | |
| ONT DOOR RUBBER NA | 1 | \$96.00 | | - 2 |
| ONT DOOR HINGE UPPER (RH) | 1 | \$44.50 | | |
| ONT DOOR HINGE LOWER (RH) | 1 | \$44.50 | | |
| ONT DOOR CHECK (RH) NH | 1 | \$91.80 | | X |
| ONT DOOR MIRROR (RH) | 1 | \$670.00 | | 4 |
| ONT WINDSCREEN MOULDING NH | 1 | \$23.70 | \$23.70 | X |
| ONT WINDSCREEN SEALANT HA | 1 | \$40.00 | | Y |
| ONT WINDSCREEN PILLAR OUTER (RH) Meyer | . 1 | \$1,535.90 | 04.505.00 | × |
| | | | | / |
| ONT WHEEL RIM (RH) 2 ou stroke 325.30 | 1 | 3550 60 1 | \$650 60 | 4 |
| ONT WHEEL RIM (RH) & MANNE 325.30 ONT WHEEL HUB CAP (RH) CW 103.10 ONT WHEEL NUT NA | 1 1 | \$650.60 \$214.20 | \$ 650.6 0 \$214.20 | سامبر سسا |

| STIMATE TOTAL | | | | \$26,809.72 |
|--|--|------------|----------------------|-----------------------|
| TOTAL LABOUR | | | | \$3,590.00 |
| TO TESEL ADO FAUIL | | | φ150.00 | \$150.00 |
| Remove/Refix Front Windscreen Glass To reset ABS Fault | | 1 | \$120.00 \$150.00 | \$120.00 |
| | 1 | \$130.00 | \$130.00 | |
| emove/Refix Radiato emove/Refix Aircon 8 | 1 | \$90.00 | \$90.00 | |
| Front/Four Wheel Alignment | | 1 | \$120.00 | \$120.00 |
| emove/Refix Underca | | 1 | \$400.00 | \$400.00 |
| ransfer of Door Mech | | 1 | \$80.00 | \$80.00 |
| owing Charge | | 1 | \$50.00 | \$50.00 |
| uff Kote | Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company | 1 | \$150.00 | \$ 150.0 0 |
| Viring Charge | No illegal modification(s) is allowed | 1 | \$100.00 | \$100.0 0 |
| Spray Painting Charge | Third party survey is on a "Without Prejudice" basis | 1 | \$1,000.00 | \$1,000.0 0 |
| Panel Beating | To display damaged part(s) during resurvey Parts prices are subject to confirmation | 1 | \$1,200.00 | \$1,200.00 |
| abour Charge | To resurvey before/after spray painting To display damaged pag(s) during resurvey | | | |
| - h Oh - | the Repairer of the following: | | | |
| UB TOTAL | LKK Auto Consultants hence notify | 100.00 | | \$382.00 |
| IID TOTAL | | 100.00 | | |
| RONT TYRE (RH) | N SN | 1 | \$216.00 | \$216.00 |
| RONT FENDER ADVERTISEMENT LOGO المدر SN | | 1 | \$100.00 | \$100.00 |
| | URED COMFORT LOGO HH SN | 1 | \$66.00 | \$66.00 |
| | | | | |
| ISCOUNTED TOTAL 844.7.36 | | | | \$22,837.72 |
| ESS 20% | | | | \$5,709.43 |
| UB TOTAL | 10559.20 | | | \$28,547.15 |
| | 1.0 | | | |
| NUCKLE ARM (RH) | 2 duonal (552.00) | 1 | \$1,104.00 | \$1,104.00 |
| | LOWER ARM (RH) 2 dubban | 1 | \$595.90 | \$595.90 |
| TABILIZER BRACKE | | 1 | \$24.00 | \$24.00 |
| TABILIZER BAR LIN | | 1 | \$68.10 | \$68.10 |
| STABILIZER BAR BU | | 1 | \$16.40 | \$16.40 |
| | 711 | 1 | \$252.30 | \$252.30 |
| STG BALL JOINT H | | 1 | \$73.10 | \$73.10 |
| STG TIE END 🥕 o | usongas | 1 | \$125.20 | \$125.20 |
| STG TIE ROD Z de | 1 | \$135.00 | \$135.00 | |
| RACK & PINION ASS | 1 | \$1,820.00 | \$1,820.00 | |
| RONT DRIVE SHAF | 1 | \$2,061.60 | \$2,061.60 | |
| | ORBER MOUNTING (RH) → | 1 | \$217.60 | \$217.60 |
| | ORBER ASSY (RH) Z districtul | 1 | \$217.60 | \$217.60 |
| RONT WHEEL HUB | | 1 | \$153.60 | \$153.60 |
| RONT WHEEL BEAL | 1 | \$301.80 | \$301.80 | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

27/02/2020 e 09/15/ms
NVA ANTWY
L/SUM 7 dq1.

Tyn-) LKK thoto

10477.36 Supp 550.88 11028.24 4|\$ 8800|-

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

| D^{Λ} | Γ⊏⋅ |
|---------------|-----|
| $D \cap$ | |

28-Feb-20

INSURANCE:

MODEL:

HYUNDAI 140

VEHICLE NO.: SHC 8425U (Supplementary)

| DESCRIPTION | QTY | LIST PRICE | AMOUNT |
|-------------------------------|-----|------------|--------|
| FRONT FENDER APRON PANEL (RH) | | \$637.00 | 1 |
| WIPER CONTAINER du (mu) | | \$51.60 | |
| ENGINE CROSS MEMBER | | \$2,094.40 | X |
| 680.60 | | | |
| SUB TOTAL 550.88 | + | \$2,783.00 | |
| LESS 20% | | \$556.60 | |
| DISCOUNTED TOTAL | | \$2,226.40 | |
| | | | |
| | | | |
| | | | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Phone Number: Fax Number:

Customer:

Date: 27/2/2020 éúl - 27/2/2020 10:29 AM

Company:

SHC8425U

VIN

License NO:

Technician:

Odometer:

Order NO:

VEHICLE ALIGNMENT REPORT

HYUNDAI, i40 G 1.6 GDI, 11-11 (Customized)

| Primary Angles | | Initial | Speci | Specifications | | |
|---|--------------|---------|-----------------------|----------------|-----------|--------|
| | | | Property and property | Min. | Max. | Final |
| | Caster | Left | 4°30' | 4°12' | 5°12' | 4°44' |
| | | Right | 4°04' | 4°12' | 5°12' | 4°12' |
| Front | Camber | Left | -1°01' | -1°00' | 0°00' | -0°58' |
| FTOIL | | Right | -1°46' | -1°00' | 0°00' | -1°48' |
| | Toe | Left | 1°01' | 0°00' | 0°12' | -0°10' |
| | | Right | 0°55' | 0°00' | 0°12' | 2°07' |
| | | Total | 1°56' | 0°00' | 0°24' | 1°58' |
| | Camber | Left | 0°19' | -1°30' | -0°30' | 0°22' |
| | | Right | 0°07' | -1°30' | -0°30' | 0°08' |
| Rear | Toe | Left | 0°10' | -0°03' | 0°09' | 0°10' |
| 0.000 (0.0 | 2 | Right | 0°07' | -0°03' | 0°09' | 0°07' |
| | | Total | 0°16' | -0°06' | 0°18' | 0°17' |
| | Thrust Angle | | -0°01' | 99°59' | | -0°01' |
| Second | ary Angles | | Initial | Specif | fications | Final |
| | | | | Min. | Max. | |
| SAI | | Left | 10°23' | 13°18' | 14°18' | 10°23' |
| | | Right | 7°40' | 13°18' | 14°18' | 7°40' |
| Included Angle | | Left | 9°22' | 99°59' | 99°59' | 9°25' |
| | | Right | 5°53' | 99°59' | 99°59' | 5°52' |
| Toe Out On Turns | | Left | | 99°59' | 99°59' | |
| | | Right | | 99°59' | 99°59' | ., |
| Max Turn Inside | | Left | | 99°59' | 99°59' | |
| | | Right | | 99°59' | 99°59' |) |
| Toe Curve Change | | Left | | 0°00' | 199°59' | |
| | | Right | | 0°00' | 199°59' | : |
| Setback | | Front | -0.23" | 99.99" | 99.99" | -0.23" |
| | | Rear | -0.23" | 99.99" | 99.99" | -0.23" |
| Track Width | Diff. | | -0.30" | 1 | | -0.30" |
| Wheel Base | | | -0.00" | | | -0.00" |
| Front Ride Height | | Left | | 99.99" | 99.99" | |
| | | Right | | 99.99" | 99.99" | |
| Rear Ride H | eight | Left | | 99.99" | 99.99" | |
| | | Right | | 99.99" | 99.99" | |
| Frame Angle | 9 | | | | | |