



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM20003238/Apa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN			Date : 27-05-2020	
Code : ASM				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMP 4735Z	Veh. Inspected	GBB 4406C	
Policy No.	CN061445	Coverage (\$)	0.00	
Claim No.	S0M02H06	Excess (\$)	0.00	
Assign From		Assign Date	26/02/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI FUSO	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	FB70BBA10784	Colour	WHITE	
Odometer	255720	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/02/2020	Inspection Date	05/03/2020	
Survey held at	8 Kaki Bukit Ave 4 #08-45 Premier			
Repairer	SPEED AUTO WORKS			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		