Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003239/UBA3Q2

Date: 27/08/2020

REFERENCE

Price:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900107400

Claimant Vehicle No: Insured Vehicle No: SMM1126S

Date of Loss: 24/02/2020 Nature of Claim: TP Claim No: 5355765682SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA3172U

Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B11010173

Reg. Date: 26/02/2016 (Man. Year: 2016) Chassis No: JHMGK3850GX223685

Colour: Red Odometer: 83813 km

Engine Capacity: 1318 cc
Market Value/New Car
N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,869.21	379.50	1,489.71	79.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	620.00	1,020.00	62.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,509.21	999.50	2,509.71	71.52
+ GST 7.00/7.00% (S\$)	245.64	69.97	175.67	71.52
Nett Amount (S\$)	3,754.85	1,069.47	2,685.38	71.52
+ Car Rental (3.0 x S\$	6120.00/day) (S\$)	360.00		
+ Doc	/Search Fee (S\$)	2.00		
N	lett Liability (S\$)	1,431.47		
Global Sum	Settlement (S\$)	1,400.00		

INSPECTION

Date of Assignment: 29/06/2020

Date Inspected: 29/06/2020 Inspected At: Hock Wah Motor Workshop Pte Ltd

(Bedok)

Blk 3011, Bedok Industrial Park E,,

#01-2008/2010/2012 Singapore 489977

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Distorted	517.50 F	*330.00 F	
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	15.70 F	*- F	
3	1		*FRONT BUMPER RETAINER LH	Not Necessary	15.70 F	*- F	
4	1		*HEADLAMP RH	Not Necessary	558.60 F	*- F	
5	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	130.00 F	*- F	
6	6		*FRONT FENDER INNER SHIELD CLIP RH	Not Necessary	23.40 F	*- F	
7	1		*FRONT GRILLE ASSEMBLY	Not Necessary	364.50 F	*- F	
8	1		*FRONT FENDER RH (NPA)	Repair	0.00 FS	*- FS	
9	1		*FRONT DOOR RH (NPA)	Repair	0.00 FS	*- FS	
10	1		*FRONT BUMPER REINFORCEMENT (NPA)	Not Necessary	0.00 FS	*- FS	
F=Franchise part. S=SpcNett. Sub Total (S\$) + Margin on L,N Items 15.00/15.00% (S\$)			1,625.40 243.81	330.00 49.50			
				Total Parts (S\$)	1,869.21	379.50	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	700.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	400.00
3	ANTI RUST COATING	New	100.00	0.00
4	WIRING	New	40.00	20.00
	Gross La	bour Cost (S\$)	1,640.00	620.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.