

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20003240/UPA3N2

**Date:** 20/07/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> CB6478U	<b>Insured Vehicle No :</b>	SHD3135J
Date of Loss: 18/02/2020	Nature of Claim: TP	Claim No: MCT20020382

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB6478U		
Make & Model:	MITSUBISHI ROSA, 4.2 D BE637 (M)	Engine No:	4D33H36845
Reg. Date:	19/06/2000 (Man. Year: 2000)	Chassis No:	BE637JB00332
Colour:	White	Odometer:	872144 km
Engine Capacity:	4214 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5 (D)
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6/6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,976.69	3,106.20	6,870.49	68.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,490.00	1,260.00	45.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,726.69</b>	<b>4,596.20</b>	<b>8,130.49</b>	<b>63.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,650.00</b>		
<b>(S\$)</b>	12,726.69	3,650.00	9,076.69	71.32
<b>+ GST 7.00/7.00% (S\$)</b>	890.87	255.50	635.37	71.32
<b>Nett Amount (S\$)</b>	<b>13,617.56</b>	<b>3,905.50</b>	<b>9,712.06</b>	<b>71.32</b>
<b>+ Loss of Use (3.0 x S\$120.00/day) (S\$)</b>		360.00		
<b>Nett Liability (S\$)</b>		<b>4,265.50</b>		

### INSPECTION

Date of Assignment:	04/03/2020	
Date Inspected:	04/03/2020 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok)
		Blk 3011, Bedok Industrial Park E.,
		#01-2008/2010/2012
		Singapore 489977
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Jun 2020)	
<b>Parts:</b>	N/A	MITSUBISHI ROSA 4.2 D BE637 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for CB6478U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Repair	4,790.46 F	*- FL
2	1		*REAR DOOR RH	Badly Dented	1,689.57 F	*1,689.57 FL
3	1		*REAR SIGNAL LAMP RH	Not Necessary	123.69 F	*- FL
4	1		*REAR BRAKE LAMP RH	Not Necessary	123.69 F	*- FL
5	1		*REAR BUMPER	Distorted	1,652.83 F	*1,652.83 FL
6	2		*REAR BUMPER LAMP RH	Cracked	153.54 F	*153.54 FL
7	1		*REAR EXHAUST PIPE	Bent / Twisted	536.15 F	*536.15 FL
8	2		*REAR NUMBER PLATE LAMP	Not Necessary	124.66 F	*- FL
9	1		*REAR DOOR GLASS RUBBER RH	Not Necessary	284.87 F	*- FL
10	1		*REAR DOOR GLASS RUBBER LH	Not Necessary	284.87 F	*- FL
11	1		*REAR BUMPER BRACKET RH	Bent	76.18 F	*76.18 FL
12	1		*REAR BUMPER BRACKET LH	Not Necessary	76.18 F	*- FL
13	1		*REAR DOOR STICKER -60KM/H	Necessary	30.00 FS	*10.00 FS
14	1		*REAR NUMBER PLATE	Cracked	30.00 FS	*15.00 FS
15	1		*END PANEL (NPA)	Repair	0.00 FS	*- FS
16	1		*REAR DOOR CERNER PANEL PILLAR RH (NPA)	Repair	0.00 FS	*- FS
17	1		*REAR CHASSIS RH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,976.69</b>	<b>4,133.27</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	1,027.07
<b>Total Parts (\$)</b>	<b>9,976.69</b>	<b>3,106.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,200.00	680.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	700.00
3	ANTI-RUST COATING	New	150.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	120.00	60.00
5	WIRING	New	80.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>2,750.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >