

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003243/QDA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900263044
Claimant
Vehicle No : SHB808G **Insured Vehicle No :** SMR4300J
Date of Loss: 22/02/2020 Nature of Claim: TP Claim No: 1964873656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB808G**
Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR6101234
Reg. Date: 07/05/2014 (Man. Year: 2014) Chassis No: JTDKN36UX05742057
Colour: Maroon Odometer: 999999 km
Engine Capacity: 1795 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm
Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,529.44	120.00	6,409.44	98.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,781.00	720.00	2,061.00	74.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,310.44	840.00	8,470.44	90.98
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	9,310.44	800.00	8,510.44	91.41
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$101.65/day) (S\$)		304.95		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,261.95		
Global Sum Settlement (S\$)		1,260.00		

INSPECTION

Date of Assignment: 24/02/2020
Date Inspected: 24/02/2020 Inspected At: SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F	
2	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F	
3	1		*DOOR FRT /RH	Repair	894.40 F	*- F	
4	1		*DOOR RR/RH	Repair	954.50 F	*- F	
5	1		*MOULDING BODY ,RH	Serviceable	673.60 F	*- F	
6	1		*MIRROR ASSY ,RH	Serviceable	1,307.10 F	*- F	
7	1		*MIRROR LAMP RH	Serviceable	65.30 F	*- F	
8	1		*COVER OUTER MIRROR RH	Serviceable	107.40 F	*- F	
9	1		*FENDER RR/RH	Serviceable	766.80 F	*- F	
10	1		*SMRT LOGO	Serviceable	7.80 F	*- F	
11	1		*STICKER DECAL 65558888	Serviceable	21.60 F	*- F	
12	1		*WHEEL DISC	Serviceable	1,484.20 F	*- F	
13	1		*TYRE	Serviceable	126.74 F	*- F	
					Total Parts (\$)	6,529.44	120.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	507.00	300.00
2	SPRAY PAINT	New	1,674.00	400.00
3	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	20.00
7	TO CHECK WIRING WIRING AND SYSTEM FUNCTION	New	80.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			2,781.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >