



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2006586
INV Date 24/09/2020
Reference CC3/CTI20003245/Dea3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHA 8139G
Insured Veh. SJG 9404D
Claim No. SNM20D200830
Policy No. DMPCSNA00002592004
Accident Date 13/02/2020
Inspection Date 20/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20003245/Dea3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 24-09-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 9404D	Veh. Inspected	SHA 8139G
Policy No.	DMPCNA00002592004	Coverage (\$)	0.00
Claim No.	SNM20D200830	Excess (\$)	0.00
Assign From		Assign Date	20/02/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU140735	Colour	YELLOW
Odometer	164192	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/02/2020	Inspection Date	20/02/2020
Survey held at	BIFROST SIN MING		
Repairer	BIFROST AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8139G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	BENT	2,253.80	2,253.80
1	BONNET RUBBER (LH)	NOT NECESSARY	12.40	-
1	BONNET RUBBER (RH)	NOT NECESSARY	12.40	-
1	BONNET HINGE (LH)	NOT NECESSARY	118.70	-
1	BONNET ABSORBER	NOT NECESSARY	35.70	-
1	BONNET SEAL	NOT NECESSARY	38.30	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	8.40	-
1	FRONT BUMPER COVER	DISTORTED / CUT	418.30	418.30
1	FRONT BUMPER GRILLE (LH)	CUT	186.90	186.90
1	FRONT BUMPER MOULDING CENTRE	CUT	108.50	108.50
1	FRONT BUMPER LOWER STIFFNER	NOT NECESSARY	85.10	-
1	FRONT BUMPER BRACKET TOP (LH)	NOT NECESSARY	35.00	-
1	FRONT BUMPER BRACKET (LH)	NOT NECESSARY	28.00	-
1	FRONT BUMPER SIDE BRACKET SUPPORT	NOT NECESSARY	12.00	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER STRIP ASSY	NOT NECESSARY	29.40	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	949.30	949.30
1	HEADLAMP (LH)	CUT	3,987.30	1,198.00
1	DAY LIGHT ,LH	CUT	642.50	642.50
1	DAY LIGHT WIRE ,LH	NOT NECESSARY	585.50	-
1	FRONT FENDER (LH)	DENTED	490.70	490.70
1	FRONT FENDER SHIELD (LH)	NOT NECESSARY	114.70	-
1	FRT DOOR (LH)	DENTED	1,797.20	1,797.20
1	FRONT DOOR HINGE UPPER (LH)	NOT NECESSARY	65.76	-
1	FRONT DOOR HINGE LOWER (LH)	NOT NECESSARY	65.76	-
1	FRONT DOOR CHECK (LH)	NOT NECESSARY	72.98	-
1	FRONT DOOR PROTECTOR (LH)	NOT NECESSARY	116.20	-
1	ROCKER PANEL OUTER GARNISH	NOT NECESSARY	290.00	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	57.30	-
1	FRONT WINDSCREEN PILLAR OUTER (LH)	NOT NECESSARY	3,764.90	-
1	FRONT WHEEL RIM (LH)	DISTORTED	1,124.20	1,124.20

Report Ref No. CC3/CTI20003245/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL HUB CAP (LH)	CUT	346.40	346.40
1	FRONT WHEEL BEARING	DAMAGED	454.00	454.00
1	FRONT SHOCK ABSORBER (ASSY) (LH)	DISTORTED	372.50	372.50
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	206.90	-
1	FRONT SHOCK ABSORBER FORK (LH)	NOT NECESSARY	206.90	-
1	FRONT SUSPENSION UPPER ARM (LH)	NOT NECESSARY	244.30	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	936.70	-
1	RAKC & PINIO ASSY	NOT NECESSARY	887.40	-
1	STG TIE ROD	NOT NECESSARY	125.60	-
1	STG TIE END	NOT NECESSARY	94.70	-
1	STABILIZER BAR	NOT NECESSARY	246.80	-
1	STABILIZER BAR BUSH (LH)	NOT NECESSARY	22.30	-
1	STABILIZER BAR LINK	NOT NECESSARY	92.10	-
1	STABILIZER BRACKET	NOT NECESSARY	10.50	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	296.80	296.80
1	KNUCKLE ARM (LH)	DISTORTED	363.60	363.60
	LESS 20% DISCOUNT		-4,487.34	-2,204.94
			17,949.36	8,819.76
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMFORT LOGO (LH) (SN)	NECESSARY	75.00	75.00
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
1	EMBLEM -BLUE DRIVE (LH) (SN)	NECESSARY	26.60	26.60
1	FRONT DOOR ADVERTISEMENT LOOG (LH) (SN)	NECESSARY	100.00	100.00
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	FRONT ERP STICKER (SN)	NOT NECESSARY	30.00	-
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			593.60	301.60
	<u>LABOUR</u>			
	PANEL BEATING.		1,200.00	800.00
	SPRAY PAINTING CHARGE.		1,000.00	800.00
	WIRING CHARGE.		120.00	50.00
	TUFF KOTE.		150.00	40.00

Report Ref No. CC3/CTI20003245/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	TRANSFER OF DOOR .		120.00	60.00
	4 WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX RADIATOR .	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	RE-SET FRT ABS SYSTEM.		200.00	180.00
			3,610.00	2,140.00
	GRAND TOTAL		22,152.96	11,261.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,000.00

Report Ref No. CC3/CTI20003245/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 8139G

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 8139G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 8139G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

