Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20003246/QGA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005435

Claimant Insured Vehicle No: SLC2614H **GBH4893Y** Vehicle No:

ΤP Date of Loss: 22/02/2020 Nature of Claim: Claim No: 1202000009792

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBH4893Y Reg No:

Make & Model: TOYOTA HIACE, 3.0 D DX (A) Engine No: 1KD2681983 Reg. Date: 18/06/2018 (Man. Year: 2016) Chassis No: KDH2010215305 Colour: Odometer: 83022 km

Silver

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm Front Right Side: Rear Right Side: Bridgestone 5 mm Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,446.36	330.75	1,115.61	77.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	610.00	720.00	54.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,776.36	940.75	1,835.61	66.12
Approved Total (Overridden) (S\$)		750.00		
(S\$)	2,776.36	750.00	2,026.36	72.99
+ GST 7.00/7.00% (S\$)	194.35	52.50	141.85	72.99
Nett Amount (S\$)	2,970.71	802.50	2,168.21	72.99
+ Loss of Use (3.0 x S\$10	300.00			
+ Doc/Se	earch Fee (S\$)	7.45		
Net	t Liability (S\$)	1,109.95		

INSPECTION

Date of Assignment: 25/02/2020

Date Inspected: 25/02/2020 Inspected At: Carz Auto Services Pte Ltd (HQ)

1 KAKI BUKIT AVE 6 #02-35 AUTOBAY @ KAKI BUKIT

Singapore 417883

3.0 days Estimated Period of Repair:

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 May 2020)

Parts: 213 TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH4893Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL HUP CAP LH	Crumpled	201.10 FL	*100.00 FL
2	2		*REAR WHEEL BEARING INNR LH	Broken (1 PCS ONLY)	313.00 FL	*200.00 FL
3	2		*REAR WHEEL BEARING OUTER LH	Broken (1 PCS ONLY)	261.60 FL	*141.00 FL
4	1		*REAR WHEEL AXLE SHAFT LH	Serviceable	599.45 FL	*- FL
5	2		*REAR WHEEL AXLE SHAFT OIL SEAL LH	Serviceable	53.80 FL	*- FL
6	1		*REAR WHEEL SHOCK ABSORBER LH	Serviceable	166.20 FL	*- FL
7	1		*REAR WHEEL TYRE LH	Serviceable	250.00 FS	*-FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	1,845.15	441.00
- List Item Discount on L Items 25.00/25.00% (S\$)					398.79	110.25
				Total Parts (S\$)	1,446.36	330.75
					•	

Report was unsubmitted during this print-out.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 23/6/2020

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND RENEW REAR DAMAGED PARTS REPLACE BEALIGNED ALL AFFECTED PARTS	New	400.00	200.00
2	TO RESPRAY AFFECTED AREAS	New	500.00	250.00
3	TO CMOPUTERISED FOUR WHEEL ALIGNMENT	New	80.00	60.00
4	TO REMOVE AND REPLACE REAR UNDERCARRIAGE	New	350.00	100.00
	Gross Labour Cost (S\$)		1,330.00	610.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.