

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003250/HBS3Q2
Date: 07/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800106921
Claimant		
Vehicle No : SFY4431K	Insured Vehicle No :	SMD9523Z
Date of Loss: 17/02/2020	Nature of Claim: TP	Claim No: 3817227556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFY4431K		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX316507
Reg. Date:	19/09/2005 (Man. Year: 2005)	Chassis No:	MR053HY4204150499
Colour:	Black	Odometer:	449912 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R14	Rear Tyre Size:	185/60 R14
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,026.72	974.70	52.02	5.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,660.00	260.00	13.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,946.72	2,634.70	312.02	10.59
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	2,946.72	2,200.00	746.72	25.34
+ GST 7.00/7.00% (S\$)	206.27	154.00	52.27	25.34
Nett Amount (S\$)	3,152.99	2,354.00	798.99	25.34
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
Nett Liability (S\$)		3,103.00		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment:	26/02/2020	
Date Inspected:	27/02/2020 Inspected At:	Kt Garage Pte Ltd (HQ) BLK 1 KAKI BUKIT AVENUE 6 #01-04, AUTO BAY@KAKI BUKIT ENTRANCE A Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: LEE HOCK ANN

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Bent	208.89 FL	*208.89 FL	
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL	
3	2		*REAR BUMPER SIDE RETAINER	Necessary	30.38 FL	*30.38 FL	
4	1		*REAR BOOT	Bent	313.33 FL	*313.33 FL	
5	1		*REAR BOOT LOCK	Jammed	28.48 FL	*28.48 FL	
6	1		*REAR BOOT WEATHERSTRIP	Serviceable	49.37 FL	*- FL	
7	1		*END PANEL	Cut	417.78 FL	*417.78 FL	
8	1		*END PANEL TOP GARNISH	Crumpled	53.17 FL	*53.17 FL	
9	1		*TAIL LAMP -RH	Cracked	85.45 FL	*85.45 FL	
10	1		*TAIL LAMP -LH	Cracked	85.45 FL	*85.45 FL	
11	1		*REAR NUMBER PLATE	Scratched	50.00 FS	*35.00 FS	
					Sub Total (\$\$)	1,352.30	1,287.93
					- List Item Discount on L Items 25.00/25.00% (\$\$)	325.58	313.23
					Total Parts (\$\$)	1,026.72	974.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND STRAIGHTEN NECESSARY PORTION ,TO REMOVE AND RENEW DAMAGED PANEL .TO ADJUST AND REALIGN THE SAME	New	800.00	800.00
2	TO PUTTY AND SPRAY ALL AFFECTED AREAS	New	800.00	800.00
3	TO RUST PROOF ALL AFFECTED AREAS	New	200.00	30.00
4	TO CHECK WIRING AND ALL LIGHTING	New	120.00	30.00
			Gross Labour Cost (\$)	1,920.00
				1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >