

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2020		27 Feb 2020 11:58 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MOHAMMAD NASIR BIN MOHD NUR HASHIM , ID: S8736787H, Tel: +6585941641, Email: reangirl@hotmail.com									
Vehicle Reg. No.: FBL532U		Date of Loss: 24/02/2020 17:00 - :59 [45 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 2431569854SG		Policy/Cover Note No.: 1900043871 (Comprehensive)							
		Excess: S\$500.00							
Repairer: Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 09/03/2020]									
Driver/Custodian: MOHAMMAD NASIR BIN MOHD NUR HASHIM (32 / Male) , NRIC: S8736787H, Tel: +6585941641 Email: reangirl@hotmail.com									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (13/03/2020): Alert - Adj Mandate Approved (S\$5000.00) - FBL532U - Claim Handler: Chan, Yoke S... - AIG_SG (13/03/2020): Alert - Adj Mandate Approved (S\$5367.00) - FBL532U - Claim Handler: Chan, Yoke S... - AIG_SG (05/03/2020): FBL532U / OD / 24/02/2020 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBL532U (2431569854SG)
OD
Feb 24 2020 5:00PM
[MOHAMMAD NASIR BIN MOHD NUR HASHIM]
Bike Production Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Assessment Reports			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/02/20 17:15	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/02/20 16:36	General View		Load JPG ☒
2	28/02/20 16:36	General View		Load JPG ☒
3	28/02/20 16:36	General View		Load JPG ☒
4	28/02/20 16:36	General View		Load JPG ☒
5	28/02/20 16:36	General View		Load JPG ☒
6	28/02/20 16:36	General View		Load JPG ☒
7	28/02/20 16:36	General View		Load JPG ☒
8	28/02/20 16:36	General View		Load JPG ☒
9	28/02/20 16:36	General View		Load JPG ☒
10	28/02/20 16:36	General View		Load JPG ☒
11	28/02/20 16:36	General View		Load JPG ☒
12	28/02/20 16:36	General View		Load JPG ☒
13	28/02/20 16:36	General View		Load JPG ☒
14	28/02/20 16:36	General View		Load JPG ☒
15	28/02/20 16:36	General View		Load JPG ☒
16	28/02/20 16:36	General View		Load JPG ☒
17	28/02/20 16:36	General View		Load JPG ☒
18	28/02/20 16:36	General View		Load JPG ☒
19	28/02/20 16:36	General View		Load JPG ☒
20	28/02/20 16:36	General View		Load JPG ☒
21	28/02/20 16:36	General View		Load JPG ☒
22	28/02/20 16:36	General View		Load JPG ☒
23	28/02/20 16:36	General View		Load JPG ☒
24	28/02/20 16:36	General View		Load JPG ☒
25	28/02/20 16:36	General View		Load JPG ☒
26	28/02/20 16:36	General View		Load JPG ☒
27	28/02/20 16:36	General View		Load JPG ☒
28	28/02/20 16:36	General View		Load JPG ☒
29	28/02/20 16:36	General View		Load JPG ☒
30	28/02/20 16:36	General View		Load JPG ☒
31	28/02/20 16:36	General View		Load JPG ☒
32	28/02/20 16:36	General View		Load JPG ☒
33	28/02/20 16:36	General View		Load JPG ☒
34	28/02/20 16:36	General View		Load JPG ☒
35	28/02/20 16:36	General View		Load JPG ☒
36	28/02/20 16:36	General View		Load JPG ☒
37	28/02/20 16:36	General View		Load JPG ☒
38	28/02/20 16:36	General View		Load JPG ☒

Assessment Reports				1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
39	28/02/20 16:36	General View		Load JPG	✓
40	28/02/20 16:36	General View		Load JPG	✓
41	23/04/20 17:48	Dismantled Parts		Load JPG	✓
42	23/04/20 17:48	Dismantled Parts		Load JPG	✓
43	23/04/20 17:48	Dismantled Parts		Load JPG	✓
44	23/04/20 17:48	Dismantled Parts		Load JPG	✓
45	23/04/20 17:49	Photo After Spray		Load JPG	✓
46	23/04/20 17:49	Photo After Spray		Load JPG	✓
47	23/04/20 17:49	Photo After Spray		Load JPG	✓
48	23/04/20 17:49	Photo After Spray		Load JPG	✓
49	23/04/20 17:49	Photo After Spray		Load JPG	✓
50	23/04/20 17:49	Photo After Spray		Load JPG	✓
51	23/04/20 17:49	Photo After Spray		Load JPG	✓
52	23/04/20 17:49	Photo After Spray		Load JPG	✓
53	23/04/20 17:49	Photo After Spray		Load JPG	✓
54	23/04/20 17:49	Photo After Spray		Load JPG	✓
55	23/04/20 17:49	Photo After Spray		Load JPG	✓
56	23/04/20 17:49	Photo After Spray		Load JPG	✓
57	23/04/20 17:49	Photo After Spray		Load JPG	✓
58	23/04/20 17:49	Photo After Spray		Load JPG	✓
59	23/04/20 17:49	Photo After Spray		Load JPG	✓
60	23/04/20 17:49	Photo After Spray		Load JPG	✓
61	23/04/20 17:49	Photo After Spray		Load JPG	✓
Documentation				1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/02/20 17:03	Log card (if available)		Load PDF	
2	28/02/20 17:03	USED BIKE ADVERTISEMENT		Load PDF	
3	28/02/20 17:03	ESTIMATE		Load PDF	
4	06/03/20 11:52	Driver's Driving License		Load PDF	
5	06/03/20 11:52	UNDERTAKING LETTER AND INTERVIEW FORM		Load PDF	
6	24/04/20 14:46	SUPPLEMENTARY		Load PDF	
7	24/04/20 14:46	WORKSHOP INVOICE		Load PDF	
8	24/04/20 14:46	DISCHARGE VOUCHER		Load PDF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser ▼
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		1 per page ▼	✓
1	26/02/20 16:02	Accident Statement		Load HTM	
Photos/Images				3 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	26/02/20 15:58	Accident Photo		Load JPG	✓
2	26/02/20 15:58	Accident Photo		Load JPG	✓
3	26/02/20 15:58	Accident Photo		Load JPG	✓
4	26/02/20 15:58	Accident Photo		Load JPG	✓
5	26/02/20 15:58	Accident Photo		Load JPG	✓
6	26/02/20 15:58	Accident Photo		Load JPG	✓
7	26/02/20 15:58	Accident Photo		Load JPG	✓
8	26/02/20 15:58	Accident Photo		Load JPG	✓
9	26/02/20 15:58	Accident Photo		Load JPG	✓
10	26/02/20 15:58	Accident Photo		Load JPG	✓
11	26/02/20 15:58	Accident Photo		Load JPG	✓

Assessment Reports			1 per page ▼	✔
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
Documentation			1 per page ▼	✔
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	26/02/20 15:55	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG20003264/NQD3S2**Date:** 24/04/2020**REFERENCE**

Insured/Claimant: MOHAMMAD NASIR BIN MOHD NUR HASHIM
Date of Loss: 24/02/2020

Policy No: 1900043871

Nature of Claim: OD Claim No: 2431569854SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL532U	Engine No:	NF01E5222438
Make & Model:	HONDA FJS400, 399cc (A)	Chassis No:	JH2NF039X9K000238
Reg. Date:	18/05/2016 (Man. Year: 2015)	Odometer:	38489 km
Colour:	White		
Engine Capacity:	399 cc		
Market Value/New Car Price:	S\$11,500.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/80 R14	Rear Tyre Size:	150/70 R13
Front Left Side:	Pirelli 3 mm	Rear Left Side:	Pirelli 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,922.50	4,284.00	1,638.50	27.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	700.00	1,310.00	65.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,932.50	4,984.00	2,948.50	37.17
Approved Total (Overridden) (\$\$)		4,000.00		
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	7,432.50	3,500.00	3,932.50	52.91
+ GST 7.00/7.00% (\$\$)	520.28	245.00	275.28	52.91
Nett Amount (\$\$)	7,952.78	3,745.00	4,207.78	52.91

INSPECTION

Date of Assignment: 27/02/2020

Date Inspected: 27/02/2020 Inspected At:

Bike Production Pte Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT COVER ASSY	Scratched	650.00 FL	*600.00 FL
2	1		*MOLDING WINDSCREEN	Necessary	115.00 FL	*115.00 FL
3	1		*GARNISH SCREEN	Serviceable	380.00 FL	*- FL
4	1		*FRONT WINDSHIELD HONDA	Necessary	40.00 FL	*20.00 FL
5	1		*FRONT WINDSHIELD	Scratched	550.00 FL	*500.00 FL
6	1		*MIANSTAND	Scratched	395.00 FL	*300.00 FL
7	1		*RIGHT FAIRING ASSY	Serviceable	350.00 FL	*- FL
8	1		*LEFT FAIRING ASSY	Scratched	350.00 FL	*350.00 FL
9	1		*LEFT FLOOR STEP COMP	Scratched	295.00 FL	*295.00 FL
10	1		*INNER FOOTREST BRACKET	Serviceable	335.00 FL	*- FL
11	1		*LEFT FOOT SKIRT	Scratched	395.00 FL	*395.00 FL
12	1		*STEERING HANDLE	Serviceable	250.00 FL	*- FL
13	1		*BRAKE LEVER LEFT	Broken	85.00 FL	*85.00 FL
14	1		*LEFT HAND BALANCER	Scratched	75.00 FL	*75.00 FL
15	1		*LEFT VIEW MIRROR	Cracked	85.00 FL	*85.00 FL
16	1		*COVER SET LEFT BODY	Scratched	580.00 FL	*500.00 FL
17	1		*LEFT REAR FOOTREST	Scratched	145.00 FL	*145.00 FL
18	1		*AMBLEMS	Necessary	75.00 FL	*40.00 FL
19	1		*GEAR BOX ASSEMBLY COVER LOGO	Necessary	40.00 FL	*20.00 FL
20	1		*GEAR BOX ASSEMBLY COVER	Cracked	445.00 FL	*445.00 FL
21	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*15.00 FS
22	1		*REAR TOP BOX	Scratched	480.00 FS	*480.00 FS
23	1		*LEFT FRONT SIGNAL	Scratched	195.00 FL	*120.00 FL
24	1		*RIGHT FRONT SIGNAL	Scratched	195.00 FL	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,525.00	4,705.00
- List Item Discount on L Items 10.00/10.00% (\$)	602.50	421.00
Total Parts (\$)	5,922.50	4,284.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES.	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM.	New	700.00	450.00
3	TO REPLACE AND BALANCE FRONT WHEEL RIM.	New	150.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.	New	380.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.	New	180.00	0.00
6	SPRAY PAINTING.	New	500.00	250.00
Gross Labour Cost (\$\$)			2,010.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >