



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

INV No. AC2003466  
INV Date 27/04/2020  
Reference CS/AGI20003271/T1qd3n2  
Code AGI



### PROFESSIONAL SERVICE FEE

Vehicle No. SKX 4902P  
Insured Veh. SLL 6710P  
Claim No. C10005719  
Policy No.  
Accident Date 25/02/2020  
Inspection Date 27/02/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20003271/T1qd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 27-04-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLL 6710P	<b>Veh. Inspected</b>	SKX 4902P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10005719	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	27/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA WISH	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JTDGG20W00J003498	<b>Colour</b>	BLACK
<b>Odometer</b>	328610	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	25/02/2020	<b>Inspection Date</b>	27/02/2020
<b>Survey held at</b>	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 4902P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	764.75	570.00
2	REAR BUMPER RETAINER	O/S DEFORMED / N/S NOT NECESSARY	139.26	69.63
2	REAR BUMPER BRACKET	O/S DEFORMED / N/S NOT NECESSARY	250.92	125.46
2	REAR BUMPER REFLECTOR	O/S DEFORMED / N/S NOT NECESSARY	225.56	112.78
2	REAR BUMPER DAMPER	O/S DENTED / N/S NOT NECESSARY	281.30	140.65
1	TAILGATE	TO REPAIR SEE LABOUR	1,314.33	-
1	TAILGATE WEATHERSTRIP	CUT	309.10	209.00
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	680.20	-
2	TAILGATE LAMP	NOT NECESSARY	920.69	-
1	TAILGATE EMBLEM-LOGO	NECESSARY	81.90	68.80
1	TAILGATE EMBLEM-VALVE MATIC	NECESSARY	98.00	62.50
1	TAILGATE LOCK	NOT NECESSARY	509.30	-
1	TAILGATE LOCK STRIKER	NOT NECESSARY	54.20	-
1	TAILGATE GLASS MOULDING	NOT NECESSARY	180.00	-
2	TAILGATE HINGE	NOT NECESSARY	131.70	-
1	KEYLESS SENSOR	CRACKED	281.60	144.20
1	KEYLESS SENSOR HOLDER	CRACKED	102.20	102.20
1	END PANEL	BENT	703.87	548.80
1	END PANEL TOP GARNISH	DEFORMED	382.61	281.30
1	FLOOR PANEL	NOT NECESSARY	1,089.20	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	301.45	-
1	EXHAUST SILENCER	BENT	791.34	649.00
2	EXHAUST MOUNTING	DEFORMED	30.00	30.00
2	TAILLAMP	NOT NECESSARY	852.51	-
2	REAR FENDER INNER TRIM (ADDITIONAL)	NOT NECESSARY	841.60	-

Report Ref No. CS/AGI20003271/T1qd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LOWER INNER PANEL (ADDITIONAL)	BENT	311.50	311.50
1	REAR RH MUD FLAP (ADDITIONAL)	DEFORMED	98.69	98.69
	LESS 25% DISCOUNT		-2,931.95	-881.13
			8,795.83	2,643.38
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET END PANEL TOP GARNISH CLIP (SN)	NECESSARY	60.00	20.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE GARNISH (SN)	NOT NECESSARY	80.00	-
1	SET REAR REVERSE SENSOR (SN)	NOT WORKING	800.00	200.00
			1,070.00	250.00
	<b><u>LABOUR</u></b>			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE,REFIT REAR LINING,TRIM AND GARNISH.		200.00	60.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		120.00	30.00
	REMOVE AND RENEW EXHAUST ASSY.		150.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TRANSFER PARTS,ATTACHMENT FOM OLD TAILGATE TO NEW.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF TAILGATE.		1,400.00	700.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,400.00	750.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
			3,770.00	1,660.00
<b>GRAND TOTAL</b>			<b>13,635.83</b>	<b>4,553.38</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,650.00</b>

Report Ref No. CS/AGI20003271/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 4902P

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 4902P

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SKX 4902P**

**RE-INSPECTION**

