



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2006854  
INV Date 06/10/2020  
Reference CC6/CTI20003288/Kba3s2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. GW 9031Y  
Insured Veh. SJT 5064J  
Claim No. SNM20D200349  
Policy No. DMPCSN3027531901  
Accident Date 09/01/2020  
Inspection Date 26/02/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : SNM20D200349

Date: 06<sup>th</sup> October 2020

Our Ref : CC6/CTI20003288/Kba3s2

**M/s China Taiping Insurance (Singapore) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GW 9031Y  
ACCIDENT ON 09/01/2020 INSURED VEHICLE SJT 5064J**

Instruction was received to inspect the vehicle Reg. No. GW 9031Y. The inspection was conducted on 26/02/2020 at the premises of M/s Wei Lee Motor Works, Block 9 Sin Ming Industrial Estate #01-32 Singapore 575644.

The following vehicle information was recorded:

Registration Number	: GW 9031Y
Make/Model	: TOYOTA LITEACE
Year of Registration	: 2003
Body Colour	: White
Chassis Number	: CR425007487
Engine Capacity	: 2184 cc
Speedometer Reading	: 207384 km

The vehicle sustained damages at the rear n/s portion, n/s rear portion and o/s body.  
(Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 15,500.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 11,000.00) (est)
Nett Liability	<u>S\$ 4,500.00 (est)</u> =====

Recommended \$4,500.00 (exclude check item \$452.10) in lieu of cost of repair

Vehicle Inspected By:



KONG SENG CHEONG  
*Licensed Appraiser*



K.K.LAU  
*MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 9031Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	BENT	939.70	939.70
1	TAILGATE - LITEACE STICKER	NECESSARY	35.20	35.20
1	TAILGATE LOCK	JAMMED	127.00	127.00
1	TAILGATE TOYOTA LOGO	NECESSARY	46.50	46.50
1	REAR BUMPER	BENT	375.50	375.50
2	REAR BUMPER REFLECTOR @ \$47.60	N/S CRACKED	95.20	47.60
1	END PANEL	BENT	466.70	466.70
1	SIDE PANEL, RH	BENT	1,284.00	1,284.00
1	SIDE PANEL, LH	BENT	1,147.40	1,147.40
1	SLIDING DOOR, LH	BENT	1,024.50	1,024.50
2	TAILLAMP @\$268.00	O/S CRACKED	536.00	268.00
1	SIDE MIRROR GLASS, RH	BROKEN	76.20	76.20
2	TAILGATE OPEN ABSORBER @ \$301.40	SERVICEABLE	602.80	-
1	EXHAUST TAILPIPE	BENT	625.90	625.90
1	EXHAUST RUBBER MOUNTING @ \$36.00	TORN	72.00	72.00
	LESS 25% DISCOUNT		-1,863.65	-1,634.05
			5,590.95	4,902.15
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	DENTED	220.00	200.00
			220.00	200.00
<b><u>LABOUR</u></b>				
	TO TRANSFER REAR WINDSCREEN GLASS TO NEW DOOR.		180.00	120.00
	TO TRANSFER TAILGATE DOOR BOARD, REAR WIPER MOTOR, WIPER AND ALL ATTACHMENTS TO NEW DOOR.		150.00	60.00
	TO REMOVE DAMAGED PARTS & ATTACHMENTS. CUT AND WELD DAMAGED PANEL. REPAIR / RESHAPE FLOOR PANEL. STRAIGHTEN CHASSIS WHERE NECESSARY. REPLACE / ALIGN ALL PARTS INTO POSITION.		1,500.00	1,400.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT.		1,400.00	1,200.00
			3,230.00	2,780.00
GRAND TOTAL			9,040.95	7,882.15
RECOMMENDED COST OF CASH-IN-LIEU				4,500.00

Report Ref No. CC6/CTI20003288/Kba3s2

MARKET VALUE: \$15,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,000.00 (EST)=NETT VALUE: \$4,500.00(EST)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.