

2200/2001

ASS. REC. BY:

REF: (S) LPI 20001751 / US^{0.57} 3-1

Special Instruction:

SURVIVOR: MARCUS

ASSIGNMENT (Office)

From (Person): ONG Li Li of LPC Date/Time: 31.1.2020 4:55p.m

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SLL 64654 Insured: SLL 4654

at Workshop m/s Huat Automobile Tel: 6461868

of Blk 3007 Ubi Rd 1 #01-404

Policy No: _____ Claim No: 19/20/20/LL00/003436

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15. Jan. 2020
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{mp}

Date/Time: 3.2.2020 10:09a.m Person Contacted: Tommy H.O.D. Enforcement: _____

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 64654 - X
	SLL 4654 - X
<u>4/2/2020</u>	check with Marcus, no estimate

Lily (LPC) instruction to want a ^{US} quote DAR since insured wish to purchase the adjustment repair for the vehicle SLL 64654.

Submit RP \$ 4,539.20 @ 5 days

RECEIVED 27 FEB 2020

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

LPC/


ASSIGNMENT

From: Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLL26465Y
at Workshop m/s West Auburn
of
Insured:
Policy No.
Claims No.
Sum Insured: Excess:
(Client's Record)
Make of Veh:

Veh No: SLL26465Y Yr Regn: 3,17
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA/
Make: Honda Vezel c.c 1496
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 042019 T/Radio: Insured / Std / NI / NA
Eng/No:

C/No: RU11207632
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R:

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 64k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lump Sum: % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 15/1/20 D.O.I. 3/2/20
Survey held at

CA / REV / REP. / 24 HRS L7A 43393
Date: Person Contacted: Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear A/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 1 FEB 2020

Date/Time, File Pass to? 11/02/20
1) Typist
Date/Time, File Return to?

: Preli. Report
 : Final Report

Days Of Repair:
Resurvey No. of Trip: 2

Survey Fee:
Transportation:
\$ - RS \$
) Photos
) Others
TOTAL

Report Format : PRS
Lump Sum / I.B.I.: (\$)

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Shirley Hiew (LKK Auto)

From: Celine Fong (LKKAuto)
Sent: Wednesday, 26 February 2020 6:41 pm
To: LILY KOH; Shirley Hiew (LKK Auto)
Cc: victorfong@toplis.com.sg; NM_Claim_SG
Subject: RE: Yr Ref : CS3/LPC20001751/Usf3s2 Claim No 19/20/20/LL00/003436 Insd : SA Valet Pte Ltd Accident on 15.1.2020 at KK Hospital's carpark [External Confidential]

Dear Lily,

Thank you for the email.

Dear Shirley,

As spoken, please follow up.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LILY KOH <lilykoh@lonpac.com>

Sent: Wednesday, 26 February 2020 6:10 PM

To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Cc: victorfong@toplis.com.sg; NM_Claim_SG <nm_claim@lonpac.com>

Subject: Yr Ref : CS3/LPC20001751/Usf3s2 Claim No 19/20/20/LL00/003436 Insd : SA Valet Pte Ltd Accident on 15.1.2020 at KK Hospital's carpark [External Confidential]

Lonpac External - Confidential

Dear Celine

As spoken, Insured wish to purchase the adjustment report for t/p veh SLL 6465Y.

Kindly arrange and to let us have it soon.

Thank You

Best Regards

Lily Koh

Deputy Claims Manager | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555



Lonpac External - Confidential data is for use by authorised external parties only.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 711Z

Vehicle Details

Vehicle No.: SLL6465Y
Vehicle to be Exported: No
Intended Deregistration Date: 04 Feb 2020
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Red
Manufacturing Year: 2016
Engine No.: L15B4407633
Chassis No.: RU11207632
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$21,563.00
Original Registration Date: 03 Mar 2017
First Registration Date: 03 Mar 2017
Transfer Count: 0
Actual ARF Paid: \$12,189.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 Mar 2027
PARF Rebate Amount: \$9,141.00

Intended COE Rebate Details

COE Expiry Date: 02 Mar 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$48,401.00
COE Rebate Amount: \$34,252.00
Total Rebate Amount: \$43,393.00

The information contained herein is correct as at 04 Feb 2020

OK

SL 64687

Rear bumper	DD	508.50	—
Rear bumper ALS corner	Re	245.00	—
Rear bumper ALS reflector	CRa	157.00	—
Rear bumper ALS side retainer	CRa	65.50	—
Tailgate	DD	1100.90	—
Vehicle emblem	REU	56.50	—
Tailgate ALS reflector	CRa	240.00	—
Rear windscreen moulding	REU	131.80	—
Tail lamp ALS	CRa	441.50	—
Rear Lender ALS outer garnish	groupab	245.80	—
Rear end panel - exist Repair		3186.50	—
		20%	
		2549.20	

S.NET

1 set Rear bumper clips	REU	50	—
1 set Rear bumper reverse sensor	Shold	200	—
Rear windscreen sealant	REU	40	✓
Rear windscreen inner seal	REU	40	—

To check lighting wiring	—	30	
To replacing reverse sensor	—	50	
To remove & refix upholstery	—	80	
To remove & refix rear windscreen	—	120	
labour for panel beating	—	600	
To putty & spray painting	SEANS.	800	

TOTAL
4559.20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC20001751/Usf3s2-1

Date: 27-02-2020



Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	S A Valet PL	Veh. Inspected	SLL 6465Y
Policy No.	Z/19/LL00/015920	Coverage (\$)	0.00
Claim No.	19/20/20/LL00/003436	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	27/02/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11207632	Colour	RED
Odometer	042019 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/01/2020	Inspect Date / Time	03/02/2020 (11:25 AM)
Survey held at	HUAT AUTOMOBILE - BLK 3007 UBI RD 1 #01-404		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SLL 6465Y

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	508.50
1	REAR BUMPER N/S CORNER	DEFORMED	245.00
1	REAR BUMPER N/S REFLECTOR	CRACKED	151.00
1	REAR BUMPER N/S SIDE RETAINER	CRACKED	65.50
1	TAILGATE	DENTED	1,100.90
1	VEZEL EMBLEM	NECESSARY	56.50
1	TAILGATE N/S REFLECTOR	CRACKED	240.00
1	REAR WINDSCREEN MOULDING	NECESSARY	131.80
1	TAILLAMP N/S	CRACKED	441.50
1	REAR FENDER N/S OUTER GARNISH	GRAZED	245.80
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-
	LESS 20% DISCOUNT		-637.30
			2,549.20
SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	40.00
			330.00
LABOUR			
	TO CHECK LIGHTING WIRING.		30.00
	TO REPLACING REVERSE SENSOR.		50.00
	TO REMOVE & REFIX UPHOLSTERY.		80.00
	TO REMOVE & REFIX REAR WINDSCREEN.		120.00
	LABOUR FOR PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00
	TO PUTTY & SPRAY PAINTING.		800.00
			1,680.00
GRAND TOTAL			4,559.20

RECOMMENDED COST OF REPAIRS	4,559.20
------------------------------------	-----------------

Report Ref No. CS3/LPC20001751/Usf3s2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.