

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong

Date: 02 Mar 2020

## **Preliminary Advice**

Insured Vehicle No : XD8583B  
TP Vehicle No : SLJ3295B  
Make : TOYOTA COROLLA  
Date of Inspection : 28/02/2020  
Inspection At : CYS Automobile Services Pte Ltd (Woodlands)  
38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park  
Singapore 757700  
Accident Date : 25/02/2020  
Assignment Date : 27/02/2020  
Est. Duration of Repair : 5 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,824.45
Revised Amount	:S\$	3,075.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,075.20

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.