

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20003292/KGS3Q2**Date:** 02/10/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
**Claimant**  
**Vehicle No :** GBF7673G **Insured Vehicle No :** SHC8482D  
Date of Loss: 26/02/2020 Nature of Claim: TP Claim No: MCT20020504

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF7673G**  
Make & Model: NISSAN NV200, 1.5 (A) Engine No: HR16078240D  
Reg. Date: 27/02/2017 (Man. Year: 2016) Chassis No: VM20101784  
Colour: Metallic Grey Odometer: 72849 km  
Engine Capacity: 1597 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14  
Front Left Side: Firenza 7 mm Rear Left Side: Firenza 7 mm  
Front Right Side: Firenza 7 mm Rear Right Side: Firenza 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,624.40	2,285.91	338.49	12.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	1,000.00	150.00	13.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,774.40</b>	<b>3,285.91</b>	<b>488.49</b>	<b>12.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	264.21	230.01	34.20	12.94
<b>Nett Amount (S\$)</b>	<b>4,038.61</b>	<b>3,515.92</b>	<b>522.69</b>	<b>12.94</b>
<b>+ Car Rental (5.0 x S\$85.00/day + 7.00% GST) (S\$)</b>		454.75		
	<b>Nett Liability (S\$)</b>	<b>3,970.67</b>		
	<b>Global Sum Settlement (S\$)</b>	<b>3,900.00</b>		

INSPECTION

Date of Assignment: 27/02/2020  
Date Inspected: 27/02/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun  
Industrial Park A  
Singapore 768761  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Sep 2020)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF7673G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	655.20 FL	*655.20 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	688.10 FL	*688.10 FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	29.60 FL	*29.60 FL
4	6		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
5	1		*RH HEADLAMP	Mtg Cracked	444.50 FL	*444.50 FL
6	1		*HEADLAMP LOWER GARNISH COVER	Buckled	368.50 FL	*368.50 FL
7	1		*FRONT GRILLE	Repair	356.10 FL	*- FL
8	4		*FRONT GRILLE CLIPS	Repair	20.00 FL	*- FL
9	1		*FRONT BUMPER LOWER COVER	Cracked	324.00 FL	*324.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,916.00</b>	<b>2,539.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	291.60	253.99
<b>Total Parts (S\$)</b>	<b>2,624.40</b>	<b>2,285.91</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS ,TO KNOCK & REPAIR FRT RH FENDER ,HEADLAMP PANEL & REALIGN THE SAME	New	600.00	500.00
2	PUTTY & RESPRAY ON FRT RH FENDER ,HEADLAMP LOWER GARNISH ,GRILLE ,FRT BUMPER ,REINFORCEMENT	New	550.00	500.00
<b>Gross Labour Cost (\$)</b>			<b>1,150.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >