

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20003295/R1PS3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMK9145U	Insured Vehicle No :	SH7942T
Date of Loss: 23/02/2020	Nature of Claim: TP	Claim No: MCT20020528

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9145U		
Make & Model:	BMW 216D, 1.5 D Gran Tourer (A)	Engine No:	33845616B38A15A
Reg. Date:	29/04/2019 (Man. Year: 2019)	Chassis No:	WBA6V12060ED05858
Colour:	Grey	Odometer:	11086 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,694.85	3,458.50	236.35	6.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,971.00	2,342.00	629.00	21.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,665.85	5,800.50	865.35	12.98
+ GST 7.00/7.00% (S\$)	466.61	406.04	60.57	12.98
Nett Amount (S\$)	7,132.46	6,206.54	925.92	12.98
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		6,386.54		

INSPECTION

Date of Assignment:	07/07/2020	
Date Inspected:	07/07/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2020)
Parts:	M1-MPV	BMW 216D 1.5 D Gran Tourer (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK9145U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*RH FINISHER	Scratched	49.90 FS	*49.90 FS
3	1		*IMPACT ABSORBER TOP	Serviceable	49.30 FS	*- FS
4	1		*FRT BUMPER PRIMED PANEL (PMA)	Cracked	897.25 FS	*897.25 FS
5	1		*RH GRID LATERAL (LINES/PDC)	Serviceable	95.05 FS	*- FS
6	2		*GROMMET	Not Necessary	1.60 FS	*- FS
7	1		*PLAQUE 82MM	Necessary	71.60 FS	*71.60 FS
8	1		*RH HEADLIGHT LED TECHNOLOGY	Scratched	2,359.75 FS	*2,359.75 FS
9	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.40 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **3,694.85** **3,458.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING FRONT BUMPER PANEL AND ATTACHMENTS	New	1,275.00	850.00
2	SPRAY FRONT BUMPER	New	1,038.00	934.00
3	TO REPLACE RIGHT HEADLIGHT	New	481.00	408.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			2,971.00	2,342.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >