

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003296/EKA3Q2**Date:** 09/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800008874
Claimant
Vehicle No : SGE1226A **Insured Vehicle No :** SLW2448R
Date of Loss: 16/02/2020 Nature of Claim: TP Claim No: 8879556195SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGE1226A**
Make & Model: BMW 320I, 2.0 (A) Engine No: F6063505B48B20A
Reg. Date: 29/11/2019 (Man. Year: 2019) Chassis No: WBA5F32050FH81341
Colour: Green Odometer: 5506 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40.00	40.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	1,934.00	733.00	27.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,707.00	1,974.00	733.00	27.08
+ GST 7.00/7.00% (S\$)	189.49	138.18	51.31	27.08
Nett Amount (S\$)	2,896.49	2,112.18	784.31	27.08
+ Loss of Use (1.0 x S\$100.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,428.18		

INSPECTION

Date of Assignment: 09/03/2020
Date Inspected: 09/03/2020 Inspected At: Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
					Total Parts (\$)	40.00
						40.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND INSTALL BUMPER FRONT COVER AND ATTACHMENTS	New	1,275.00	850.00
2	TO SPRAY PAINT BUMPER FRONT COVER	New	1,038.00	934.00
3	TO REMOVE OLD PDC ASSEMBLY ,AND RECONNECT INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			2,667.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >