

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003300/AEA3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100353846
Claimant Vehicle No :	SKZ6225L	Insured Vehicle No :	SKK9057P
Date of Loss:	23/02/2020	Nature of Claim:	TP
		Claim No:	2029680550SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ6225L	Engine No:	CVN001544
Make & Model:	AUDI A4, 1.4 (A)	Chassis No:	WAUZZZF44GA012634
Reg. Date:	28/01/2016 (Man. Year: 2016)	Odometer:	19715 km
Colour:	Gold		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,758.00	2,694.00	1,064.00	28.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,260.00	4,296.00	1,964.00	31.37
+ GST 7.00/7.00% (S\$)	438.20	300.72	137.48	31.37

Nett Amount (S\$)	6,698.20	4,596.72	2,101.48	31.37
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,778.72		

INSPECTION

Date of Assignment: 09/03/2020

Date Inspected: 09/03/2020

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,079.00 FS	*1,663.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	69.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	210.00 FS	*168.00 FS
4	1		*REAR BUMPER SPOILER	Deformed	234.00 FS	*187.20 FS
5	1		*REAR LIGHT REFLECTOR -LH REAR	Not Necessary	39.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Bent	845.00 FS	*675.60 FS
7	2		*REAR BUMPER SEAL	Not Necessary	26.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	42.00 FS	*- FS
9	1		*REAR PARKING AID SENSOR -INNER OUTER (NPA)	Not Necessary	0.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
					Total Parts (\$\$)	3,758.00
						2,694.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >