Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003301/GEA3Q2

**Date:** 20/10/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700020192

Claimant
Vehicle No: SJL1424Y

Insured Vehicle No: SLP9529G

Date of Loss: 26/02/2020 Nature of Claim: TP Claim No: 0082214903SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJL1424Y

Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZ117070

Reg. Date: 30/05/2017 (Man. Year: 2017) Chassis No: WAUZZZGAXHA022803

Colour: Black Odometer: 49889 km

Engine Capacity: 999 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,349.00	3,636.16	7,712.84	67.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,602.00	1,602.00	2,000.00	55.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,951.00	5,238.16	9,712.84	64.96
+ GST 7.00/7.00% (S\$)	1,046.57	366.67	679.90	64.96
Nett Amount (S\$)	15,997.57	5,604.83	10,392.74	64.96
+ Loss of Use (3.0 x S\$50.00/day) (S\$) + Doc/Search Fee (S\$)		150.00		
		7.45		
+ (	Other Costs (S\$)	250.00		

**INSPECTION** 

Date of Assignment: 03/03/2020

Date Inspected: 03/03/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)

**Nett Liability (S\$)** 

55 UBI ROAD 1 Singapore 408699

6,012.28

Singapore 408698

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,763.00 FS	*1,299.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	326.00 FS	*-FS
3	1		*FRONT BUMPER GRILLE -CENTRE	Cracked	186.00 FS	*148.40 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Scratched	159.00 FS	*127.20 FS
5	1		*FRONT BUMPER END CAP -RH	Necessary	32.00 FS	*25.44 FS
6	1		*FRONT BUMPER SPOILER	Deformed	282.00 FS	*225.20 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	147.00 FS	*117.20 FS
8	1		*WHEEL SPOILER -RH	Not Necessary	32.00 FS	*-FS
9	1		*FRONT BUMPER ADAPTER -RH	Not Necessary	40.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cut	1,328.00 FS	*1,062.40 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	117.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	646.00 FS	*-FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	73.00 FS	*- FS
14	1		*FRONT BUMPER DISTANCE PIECE	Not Necessary	13.00 FS	*-FS
15	1		*FRONT BUMPER COVER	Broken	95.00 FS	*75.36 FS
16	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	34.00 FS	*-FS
17	1		*SIGNAL HORN -RH HIGH TONE	Not Necessary	178.00 FS	*-FS
18	1		*SPRING SHACKLE -RH LOW TONE	Not Necessary	30.00 FS	*-FS
19	1		*HEADLIGHT MOUNTING	Not Necessary	112.00 FS	*- FS
20	1		*LED HEADLIGHT -RH	Not Necessary	4,627.00 FS	*- FS
21	1		*LIFT CYLINDER -RH	Not Necessary	134.00 FS	*-FS
22	1		*RADIATOR AIR GUIDE -RH	Not Necessary	29.00 FS	*-FS
23	2		*FRONT WHEEL COVER -LH/RH	Necessary	606.00 FS	*484.00 FS
24	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
25	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
26	1		*FRONT NO PLATE	Necessary	40.00 FS	*40.00 FS
27	1		*SUNDRIES	Necessary	300.00 FS	*31.76 FS
F=Fra	anchise	part. S=Spcl	Nett.	Total Parts (S\$)	11,349.00	3,636.16

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	Labour Items								
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00					
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00					
3	TO RESPRAY FRONT BUMPER	New	1,200.00	550.00					
4	TO REAPPLY PAINT COATING (BY OWNER)	New	250.00	0.00					
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00					
	Gross Labour Cost (S\$)		3,602.00	1,602.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >