

REF: CS3/AIG19022119/Hsf3^{ex}-1

Typical Instructions:

L/s: \$ 6000.00

From (Person) Bennie Tan of AIG Date/Time 25/02/2020
Estimated Cost: _____ Bill to: _____

Third Parties

Claimant:

Surveyor: WG Appraisal Services

Workshop: Green star spray painting

ODTP Re-inspection / Evaluation

To Inspect Vehicle No: SGH 6933T Insured: SMM 6-761A
at Workshop n/s: Green Star Spray Painting Tel: 6546 3092
of Blk 3011 Bedok North Avenue 4 #01-2004

Policy No: _____ Claim No: 0293692217SG-003

Sum Insured: _____ Excess: _____

Make of Veh: * D.O.A. 5/12/2019

(Client's Record)

04/03/2020 @ 2pm (waiting)

HOD, Enlistment/Date

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 1-1 Confirmed with Final Fig days (Red \$ / %; Original 7 days)

Date/Time: 05/03/20 Submit Final Fig. \$3,800/45, 5 days (Red \$ 2,200/27 %; Original 7 days)

Date/Time	Action/Instruction
27/2/2020	SGM 6733T - 083/116/19022119/11/302 SMM 6761A - 083/116/19022119/11/302 pending survey report & coloured photographs.

Para(1) : Parts found not replaced	(To highlight <i>R</i> or <i>UB</i> , <i>LR</i> , <i>Etc</i>)
------------------------------------	--

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 00 MAR 2020

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by:	Fee Charged:	Date:
Salvage Value : _____		Basic & Add	200
Nett Value : _____		Transport	
		Photos	
		Others	
		Total	200

1) Date/Time _____ File Pass to _____

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Path _____

2) Date/Time

4) Date/Time

e) Date/Time

File Return to

File Return to

File Return to

Nivitha (LKK Auto)

From: Jerdine <jerdine.wang@alt.sg>
Sent: Thursday, 27 February 2020 4:13 PM
To: 'Nivitha (LKK Auto)'; 'Tan, Bennie-WZ'; 'assignments'
Cc: 'SUR'; jiamin.mak@alt.sg; allister@alt.sg; vincent@alt.sg
Subject: RE: AIG Ref: 0293692217SG-003 || Your Ref: AL.INS.2019.15129(PDPI)JW

Importance: High

WITHOUT PREJUDICE

Dear Navitha,

We refer to your earlier email.

We confirm the physical reinspection on **4 March 2020 at 2.00pm**. Details are as follows:

Date & Time: 4 March 2020 at 2.00pm
Venue: Green Star Spray Painting
Blk 3011 Bedok North Avenue 4
#01-2004 Bedok Industrial Park E
Singapore 489977
Contact person: Jane 6546 3092

Kindly attend punctually.

Thank you.

Best Regards,

Jerdine

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

1 Coleman Street
#05-01 The Adelphi
Singapore 179803
Telephone : 6438 3303
DID: 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

23/03/2011

ASS. REC. BY:

REF: CS/AIG 11022/19/H5 f304 Special Instruction:

SUBJECT:

Hock Ann

ASSIGNMENT (Office)

From (Person): Winnie Fan of AIG Date/Time: 16.12.19 3.49p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH1 6A33T Insured: SMM 6761A

at Workshop m/s Green Star Spray Tel: 65463092

of BIK 3011 Batok North Hwy 4 #01-204

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A 5.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS 17.12.2019

Date/Time: 16.12.19 4.20p.m. Person Contacted: Jan H.O.D. Enforcement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SH1 6A33T ✓
	SMM 6761A - X
17/12/19	- survey taken
18/12/19	- Repairing taken
	- pending workshop milled (able put plate)

INSPECTED BY

PRS

REF: AIG

ASSIGNMENT

From:

Date: 17.12.2019

Estimated Cost:

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGH 6933T

at Workshop m/s Green Star Spray

at BIR 3011 Bolek Mach Ave 4 101-2004

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGH 6933T

Vt Regn:

17/12/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. wish

cc 1797

Colour:

silver

A/C: Insured / Std / NI / NA

Sp. Reading:

245746 km

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2NE100306176

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SiRim / STD A/Rim or

Tyre Size:

F:

R:

215/45/R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

77 mm

Rear

R/Bal:

77 mm

L/Bal:

7 mm

L/Bal:

7 mm

D.O.A:

5/12/19

D.O.I:

18/12/19

Survey held at

Green Star Spray

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roottop or +

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

DAR - 10h

Days → 5

MV - 39000

PV - 29696

NV - 9300

RECEIVED 2019

Date/Time: File Pass 10/

23/12/19
Typist☐ : Prel. Report☐ : Final Report

Date/Time: File Return 10/

11

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp 1\$☐ Interview 1\$☐ Tech. Insps 1\$☐ Weekend 1\$

Survey Fee:

Transportation:

S + RS 50

Phone:

Other:

TOTAL

180

11

191

Form: Form 1

PRS

Date: 23/12/19

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2020-26
 Invoice No: TP/GS/2020-26
 Vehicle No: SGH6933T
 Attn: MOHAMED FADIL BINABDUL RAHMAN
 Company: GREEN STAR SPRAY PAINTING GARAGE
 Address: Blk 3011, Bedok North Ave 4, #01-2004/2006 .
 Bedok Industrial Park E. Singapore 489977

Date 20 January 2020

Invoice

Surveyor Fee:	S\$290
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$44/- (@ \$1 per photo, total 44 photos)
Total:	S\$434

Surveyor:
 Signature:
 Date:

Winsong Service
 20 January 2020



VEHICLE NO : SGH6933T
MODEL : WISH 1.8 A

Our Ref : WG/TP/2020-36

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL		REVISED	
			QUOTATION		QUOTATION	
1 FRONT LH DOOR PANEL ✓ replace	1	DENTED	\$	1,395.00	\$	1,395.00 ✓ 1195.10 ✓
2 FRONT H DOOR TAPE ✓ replace	1	NECESSARY	\$	55.00	\$	55.00 ✓
3 FRONT DOOR TOP MOULDING ✓ replace	1	DEFORMED	\$	75.00	\$	75.00 ✓
4 FRONT LH DOOR LOCK ASSY X SVC	1	NOT NECESSARY	\$	660.00	\$	-
5 FRONT LH REGULATOR MOTOR ASSY X SVC	1	NOT NECESSARY	\$	641.00	\$	-
6 FRONT LH WING MIRROR ASSY ✓ replace	1	DISTORTED	\$	693.00	\$	693.00 ✓ 640.30 ✓
7 FRONT LH DOOR GLASS ✓ replace	1	GRAZED	\$	450.00	\$	450.00 ✓ 410.80 ✓
8 FRONT LH FENDER ✓ replace	1	DENTED	\$	855.00	\$	855.00 ✓ 650.50 ✓
9 FRONT LH FENDER INNER SHIELD X SVC	1	NOT NECESSARY	\$	165.00	\$	-
10 FRONT LH HEADLAMP ✓ replace	1	CRACKED	\$	950.00	\$	950.00 ✓ 681.70 ✓
11 FRONT LH KNUCKLE X SVC	1	BENT	\$	480.00	\$	480.00 ✓
12 FRONT LH KNUCKLE BEARING ✓ replace	1	JAMMED	\$	235.00	\$	235.00 ✓
13 FRONT LH LOWER ARM X SVC	1	BENT	\$	492.00	\$	492.00 ✓
14 FRONT LH SHOCK ABSORBER X SVC	1	BENT	\$	401.00	\$	401.00 ✓
15 FRONT LH TIE ROD END X SVC	1	BENT	\$	115.00	\$	115.00 ✓
16 FRONT BUMPER X repair	1	REPAIR	\$	595.00	\$	-
17 FRONT LH SIGNAL LAMP ✓ replace	1	GRAZED	\$	65.00	\$	65.00 ✓ 48.70 ✓
			\$	8,322.00	\$	6,261.00
		Less 25%	\$	2,080.50	\$	1,565.25
			\$	6,241.50	\$	4,695.75

B) S/NET ITEM

18 FRONT BUMPER CLIP	1 SET	NECESSARY ✓ replace	\$	30.00	\$	20.00 ✓
19 FRONT FENDER INNER TRIM CLIP	1 SET	NECESSARY ✓ replace	\$	20.00	\$	10.00 ✓
20 RIM	1	GRAZED ✓ replace	\$	500.00	\$	400.00 ✓ 380 ✓
21 BRAKE PULD	1 BOT	NECESSARY X SVC	\$	60.00	\$	50.00
			\$	610.00	\$	480.00

Parts Total :

\$ 6,851.50 \$ 5,175.75

C) LABOUR CHARGES & MISC

22 CHECK FRONT WIRING AND LIGHTNING SYSTEM	\$	60.00	\$	50.00 ✓ 30 ✓
23 COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	\$	150.00	\$	120.00 ✓ 60 ✓
24 REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	\$	200.00	\$	180.00 ✓ 80 ✓
25 TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO NEW	\$	200.00	\$	180.00 ✓ 60 ✓
26 PANEL BEATING ON AFFECTED AREAS	\$	800.00	\$	700.00 ✓ 500 ✓
27 SPRAY PAINTING ON AFFECTED AREAS	\$	1,200.00	\$	1,000.00 ✓ 600 ✓
28 APPLY ANTI RUST ON AFFECTED AREAS	\$	120.00	\$	100.00 ✓ 30 ✓
Labour Total :	\$	2,730.00	\$	2,330.00

Total Parts and Labour :

\$ 9,581.50 \$ 7,505.75

FINAL LUMP SUM ADJUSTMENT

\$ 6,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey done by H. ANN (LKK) 4/3/20 3.00pm with L/S 5 day

Parts 3991.70
Parts less 25%
2993.77
spray paint 410
labour 1360
4763.77
4/50 hrs 20%
3811.01
net 1
L/S \$ 3800

POINT OF IMPACT

The impact was confined to the front left portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$6,000.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES

Winston Goh
Automotive Appraiser



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

N/S: MOHAMED FADIL BIN ABDUL RAHMAN
C/O GREEN STAR SPRAY PAINTING GARAGE
Blk 301 I, Bedok North Ave 4, #01-2004/2006
Bedok Industrial Park E, Singapore 489977

Date : 20 January 2020
Our Ref : WG/TP/2020-26

REFERENCE PARTICULARS

Date of Accident : 05 December 2019
Date of Inspection : 08 December 2019

Type of Inspection : Third Party Claim
Date of Re-Inspt : 18 December 2019

VEHICLE PARTICULARS

Registration No : SGH6933T
Make : TOYOTA
Model : WISH 1.8 A
Year : 2006

Engine No : 1ZZ2569668
Chassis No : ZNE100306176
Odometer : 245539km
Colour : Silver

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Hankoo	215/45R17
Front Off Side	Hankoo	215/45R17
Rear Near Side	Hankoo	215/45R17
Rear off Side	Hankoo	215/45R17

Thread Balance
3 mm
3 mm
3 mm
3 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front left portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,900.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Seven (07) working days.

Enclosed Forty-four (44) photographs depicting damage to the vehicle.

Inspection conducted at : GREEN STAR SPRAY PAINTING GARAGE
Blk 301 I, Bedok North Ave 4, #01-2004/2006, Bedok Industrial Park E, Singapore 489977

In accordance to your instruction, we have not authorise repairs and inspection
was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Our Ref: WG/TP/2020-26
Invoice No: TP/GS/2020-26
Vehicle No: SGH6933T
Attn: MOHAMED FADIL BINABDUL RAHMAN
Company: GREEN STAR SPRAY PAINTING GARAGE
Address: Blk 3011, Bedok North Ave 4, #01-2004/2006
Bedok Industrial Park E, Singapore 489977

Date 20 January 2020

Invoice

Surveyor Fee:	S\$290
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$44/- (@ \$1 per photo, total 44 photos)
Total:	S\$434

Surveyor:
Signature:
Date:

Winsongkk

20 January 2020



WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongki@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S: MOHAMED FADIL BIN ABDUL RAHMAN
C/O GREEN STAR SPRAY PAINTING GARAGE
Blk 3011, Bedok North Ave 4, #01-2004/2006
Bedok Industrial Park E, Singapore 489977

Date : 20 January 2020
Our Ref : WG/TP/2020-16

REFERENCE PARTICULARS

Date of Accident : 05 December 2019
Date of Inspection : 09 December 2019

Type of Inspection : Third Party Claim
Date of Re-Inspect : 18 December 2019

VEHICLE PARTICULARS

Registration No : SGH6933T
Make : TOYOTA
Model : WISH 1.8 A
Year : 2008

Engine No : 1ZZ2569668
Chassis No : ZNE100006176
Odometer : 245539km
Colour : Silver

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Hankoo	215/45R17
Front Off Side	Hankoo	215/45R17
Rear Near Side	Hankoo	215/45R17
Rear off Side	Hankoo	215/45R17

Thrust Balance
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front left portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,000.00** net at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Seven (07) working days.

Enclosed Forty-four (44) photographs depicting damage to the vehicle.

Inspection conducted at GREEN STAR SPRAY PAINTING GARAGE
Blk 3011, Bedok North Ave 4, #01-2004/2006, Bedok Industrial Park E, Singapore 489977

In accordance to your instruction, we have not authorise repairs and inspection
was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

VEHICLE NO : SGH6933T
MODEL : WISH 1.8 A

Our Ref : WG/TP/2020-26

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS		QTY	ASSESSED		ORIGINAL	REVISED
		PC/SET	CONDITION		QUOTATION	QUOTATION
1	FRONT LH DOOR PANEL	1	DENTED	\$	1,395.00	\$ 1,395.00
2	FRONT H DOOR TAPE	1	NECESSARY	\$	55.00	\$ 55.00
3	FRONT DOOR TOP MOULDING	1	DEFORMED	\$	75.00	\$ 75.00
4	FRONT LH DOOR LOCK ASSY	1	NOT NECESSARY	\$	660.00	\$ -
5	FRONT LH REGULATOR MOTOR ASSY	1	NOT NECESSARY	\$	641.00	\$ -
6	FRONT LH WING MIRROR ASSY	1	DISTORTED	\$	693.00	\$ 693.00
7	FRONT LH DOOR GLASS	1	GRAZED	\$	450.00	\$ 450.00
8	FRONT LH FENDER	1	DENTED	\$	855.00	\$ 855.00
9	FRONT LH FENDER INNER SHIELD	1	NOT NECESSARY	\$	165.00	\$ -
10	FRONT LH HEADLAMP	1	CRACKED	\$	950.00	\$ 950.00
11	FRONT LH KNUCKLE	1	BENT	\$	480.00	\$ 480.00
12	FRONT LH KNUCKLE BEARING	1	JAMMED	\$	235.00	\$ 235.00
13	FRONT LH LOWER ARM	1	BENT	\$	492.00	\$ 492.00
14	FRONT LH SHOCK ABSORBER	1	BENT	\$	401.00	\$ 401.00
15	FRONT LH TIE ROD END	1	BENT	\$	115.00	\$ 115.00
16	FRONT BUMPER	1	REPAIR	\$	595.00	\$ -
17	FRONT LH SIGNAL LAMP	1	GRAZED	\$	65.00	\$ 65.00
				\$	8,322.00	\$ 6,261.00
				Less 35%	\$ 2,080.50	\$ 1,565.25
				\$	6,241.50	\$ 4,695.75
B) SNETT ITEM						
18	FRONT BUMPER CLIP	1 SET	NECESSARY	\$	30.00	\$ 20.00
19	FRONT FENDER INNER TRIM CLIP	1 SET	NECESSARY	\$	30.00	\$ 10.00
20	RIM	1	GRAZED	\$	500.00	\$ 400.00
21	BRAKE PULD	1 BOT	NECESSARY	\$	60.00	\$ 50.00
				\$	610.00	\$ 480.00
Parts Total :				\$	6,851.50	\$ 5,175.75
C) LABOUR CHARGES & MISC						
22	CHECK FRONT WIRING AND LIGHTNING SYSTEM			\$	60.00	\$ 50.00
23	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT			\$	150.00	\$ 120.00
24	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS			\$	200.00	\$ 180.00
25	TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO NEW			\$	200.00	\$ 180.00
26	PANEL BEATING ON AFFECTED AREAS			\$	800.00	\$ 700.00
27	SPRAY PAINTING ON AFFECTED AREAS			\$	1,200.00	\$ 1,000.00
28	APPLY ANTI RUST ON AFFECTED AREAS			\$	120.00	\$ 100.00
				Labour Total :	\$ 2,730.00	\$ 2,330.00
Total Parts and Labours :				\$	9,581.50	\$ 7,505.75
FINAL LUMP SUM ADJUSTMENT					\$	6,000.00

POINT OF IMPACT

The impact was confined to the front left portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$6,000.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully,
WG APPRAISAL SERVICES

Winston Goh
Automotive Appraiser



COPIES

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

ACCIDENT STATEMENT

Date Of Report 06/12/2019 16:16
Date Of Accident 05/12/2019 21:10
Exact Location Of Accident ALONG GEYLANG LOR 16
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGH6933T
Insured/Policyholder
Name Of Registered Owner MOHAMED FADIL BIN ABDUL RAHMAN
NRIC No S8133049B
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-84681364
Alternative Phone No OFFICE-84681364

Vehicle Particulars

Manufacturer TOYOTA
Model WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company ETIQA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number MA006025
Cover Note Number 10/10/2019-09/10/2020

Driver

Name of Driver MOHAMED FADIL BIN ABDUL RAHMAN
NRIC No S8133049B
Date Of Birth 07/11/1981
Occupation INDOOR
Date Of Driving Pass 22/12/2014
Driving Experience 4 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-84681364
Fax Number
Contact Number OFFICE-84681364
Email Address NOEMAIL

Address BLK 52 LORONG 6 TDA PAYOH #05-54
 Postcode 310052
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME : NOR QASRINA
 GENDER : FEMALE
 Passenger 2
 NAME : NORAINI
 GENDER : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name CHANGI N.P.C
 Police Station Address ROAD: 9 SIMEI STREET 2, POSTCODE: 529914, COUNTRY: SINGAPORE
 Police Station Contact TEL NO - FAX NO
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON THE 05/12/2019 AT AROUND 9PM, I WAS DRIVING ALONG THE SAID ROAD. THE OTHER VEHICLE WAS ABOUT TO DROP THE PASSENGER AND WAS ON THE LEFT SIDE OF THE ROAD. THE ROAD IS A ONE LANE ONE WAY ROAD WHICH IS WIDE. I MANAGED TO OVERTAKE THE VEHICLE AND WHILE I WAS OVERTAKING, THE PASSENGER OF THE OTHER VEHICLE OPEN THE REAR RIGHT DOOR AND HIT ONTO MY LEFT SIDE AND CAUSE DAMAGES TO MY LEFT SIDE MIRROR, FENDER AND DOOR. DURING THE ACCIDENT, MY 6 YEAR OLD DAUGHTER GOT HURT DUE TO THE E BRAKE I HAD TO APPLY. I WAS ALSO INJURED. I WAS WILL BE GOING TO THE DOCTOR AND HAVE A MEDICAL CHECK UP WITH MY DAUGHTER AS WELL.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMM6751A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

93686128

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMED FADIL BIN ABUL RAHMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGH6933T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

NOR QASRINA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGH6933T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

VH # 3-11-29-50

Collision 12:30 PM

12:30 PM 12:30 PM



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA report

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.

Reporting Only
Claim OD
Claim TP
☒ Claim OD/TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:





Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/12/2019 17:29	Vide Report No.: G/20191205/0176	Station Diary No.: 46
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: MOHAMED FADIL BIN ABDUL RAHMAN			Address: APT BLK 52 LORONG 6 TOA PAYOH #05-54 SINGAPORE 310052		
ID Type / ID No.: NRIC NO / S8133049B			Contact No.: Home/Office: Mobile: 84681364		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 07/11/1981	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/12/2019 21:00	Type of Location: Straight Road
Location: Along Road 1 LORONG 16 GEYLANG				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGH6933T	Car	TOYOTA	WISH 1.8 A	Silver	Seriously Damaged	3
SMM6761A	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGH6933T	ETIQA INSURANCE BERHAD	MA006025	10/10/2019	09/10/2020



Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOHAMED FADIL BIN ABDUL RAHMAN	ID No.	S8133049B
Related Vehicle	SGH6933T (Car)	Contact No.	84681364
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Nor Qasrina Amirah	ID No.	NIL
Related Vehicle	SGH6933T (Car)	Contact No.	84681364
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On the 05/12/2019 at around 9pm, I was driving along the said road. The other vehicle was about to drop the passenger and was on the left side of the road. The road is a one lane one way road which is wide. I managed to overtake the vehicle and while I was overtaking, the passenger of the other vehicle open the rear right door and hit onto my left side and cause damages to my left side mirror, fender and door. During the accident, my 6 year old daughter got hurt due to the e brake I had to apply. I was also injured. I will be going to the doctor and have a medical check up with my daughter as well.



Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

3 of 3

Report No. T/20191206/2145

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sr Staff Sgt DZULHILMI BIN OMAR
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No 65475436

Authentication Stamp
NP168

Signature Of Informant: 
Date/Time: 06/12/2019 17:29
Classification Of Case:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG19022119/Hsf3e2-1	
78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120		Date : 06-03-2020	
ATTN : BENNIE TAN		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SMM 6761A	Veh. Inspected	SGH 6933T
Policy No.		Coverage (\$)	0.00
Claim No.	0293692217SG-003	Excess (\$)	0.00
Assign From	BENNIE TAN	Assign Date	25/02/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100306176	Colour	SILVER
Odometer	252908	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	HANKOOK	7 mm
L/H Front Tyre	215/45 R17	HANKOOK	7 mm
R/H Rear Tyre	215/45 R17	HANKOOK	7 mm
L/H Rear Tyre	215/45 R17	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	05/12/2019	Inspection Date	04/03/2020
Survey held at	GREEN STAR SPRAY PAINTING BLK 3011 BEDOK NORTH AVE 4 #01-2004 BEDOK INDUSTRIAL PARK E SINGAPORE 489977		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR.		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 6933T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LH DOOR	REPLACED	1,395.00	1,195.10
1	FRONT H DOOR TAPE	REPLACED	55.00	55.00
1	FRONT DOOR TOP MOULDING	REPLACED	75.00	75.00
1	FRONT LH DOOR LOCK ASSY	SERVICEABLE	660.00	-
1	FRONT LH REGULATOR MOTOR ASSY	SERVICEABLE	641.00	-
1	FRONT LH WING MIRROR ASSY	REPLACED	693.00	640.30
1	FRONT LH DOOR GLASS	REPLACED	450.00	410.80
1	FRONT LH FENDER	REPLACED	855.00	650.50
1	FRONT LH FENDER INNER SHIELD	SERVICEABLE	165.00	-
1	FRONT LH HEADLAMP	REPLACED	950.00	681.70
1	FRONT LH KNUCKLE	SERVICEABLE	480.00	-
1	FRONT LH KNUCKLE BEARING	REPLACED	235.00	235.00
1	FRONT LH LOWER ARM	SERVICEABLE	492.00	-
1	FRONT LH SHOCK ABSORBER	SERVICEABLE	401.00	-
1	FRONT LH TIE ROD END	SERVICEABLE	115.00	-
1	FRONT BUMPER	REPAIRED SEE LABOUR	595.00	-
1	FRONT LH SIGNAL LAMP	REPLACED	65.00	48.30
	LESS 25% DISCOUNT		-2,080.50	-997.93
			6,241.50	2,993.77
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN)	REPLACED	30.00	20.00
1	SET FRONT FENDER INNER TRIM CLIP (SN)	REPLACED	20.00	10.00
1	RIM (SN)	REPLACED	500.00	380.00
1	BOT BRAKE FLUID (SN)	SERVICEABLE	60.00	-
			610.00	410.00
LABOUR				
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		60.00	30.00
	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT.		150.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.		200.00	80.00
	TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		800.00	500.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
			2,730.00	1,360.00
	GRAND TOTAL		9,581.50	4,763.77
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS3/AIG19022119/Hsf3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.