

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003309/HVF3E2

Date: 22/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30251019011

Claimant Vehicle
No : SLK5939JInsured Vehicle
No : GW3843K

Date of Loss: 26/02/2020

Nature of Claim: TP

Claim
No: SNM20D201048C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK5939J

Make & Model: MERCEDES-BENZ E220D SE, 2.0 (A)

Engine No: 65492080036881

Reg. Date: 20/01/2017 (Man. Year: 2016)

Chassis No: WDD2130042A078009

Colour: Green

Odometer: 78982 km

Engine Capacity: 1950 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,880.50	5,069.70	2,810.80	35.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,460.00	760.00	34.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,100.50	6,529.70	3,570.80	35.35
+ GST 7.00/7.00% (S\$)	707.04	457.08	249.96	35.35
Nett Amount (S\$)	10,807.54	6,986.78	3,820.76	35.35

INSPECTION

Date of Assignment: 27/02/2020

Date Inspected: 28/02/2020 Inspected At:

48 Toh Guan Road East #05-155

Repairer : VAG SINGAPORE PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2020)
Parts:	143	MERCEDES-BENZ E220D SE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5939J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Crumpled	1,800.00 F	*1,450.20 FL
2	1		*LH HEADLAMP ASSEMBLY	Cracked	2,210.00 F	*1,850.50 FL
3	1		*LH HEADLAMP GASKET	Serviceable	70.00 F	*- FL
4	1		*LH FRONT FENDER	Repair	740.00 F	*- FL
5	1		*LH BUMPER RETAINER	Crumpled	8.50 F	*8.50 FL
6	1		*BASIC CARRIER FOR FRONT BUMPER (LEFT)	Serviceable	75.00 F	*- FL
7	1		*BASIC CARRIER FOR FRONT BUMPER (CENTRE)	Serviceable	105.00 F	*- FL
8	1		*LH FRONT WHEELHOUSE COVER	Serviceable	105.00 F	*- FL
9	10		*BLIND RIVETS (NECESSARY)	Necessary	50.00 F	*30.00 FL
10	1		*LH FOGLAMP COVER	Serviceable	95.00 F	*- FL
11	1		*INTERMEDIATE LAYER BETWEEN LH FENDER AND BUMPER	Serviceable	16.00 F	*- FL
12	1		*HOOD	Bent	1,830.00 F	*1,680.30 FL
13	1		*FOAM INSERT	Cracked	166.00 F	*166.00 FL
14	1		*FRONT REINFORCEMENT BEAM	Bent	580.00 F	*447.50 FL
15	1		*SUNDRIES	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,880.50	5,633.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	563.30
Total Parts (\$\$)	7,880.50	5,069.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVAL, REFITTING AND PANEL BEATING OF FRONT BUMPER, BONNET, LEFT FENDER	New	900.00	600.00
2	SURFACE PREPARATION, PUTTY, SPRAY PAINT AND DETAILING OF AFFECTED PANELS	New	900.00	700.00
3	HEADLAMP CALIBRATION, LEVELLING AND ALIGNMENT	New	150.00	40.00
4	DIAGNOSTICS AND CLEARING OF FAULT CODES AFTER REPAIR	New	150.00	120.00
5	WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			2,220.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >