

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20003312/EKS3Q2

**Date:** 26/06/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100367124-06

**Claimant**  
**Vehicle No :** SLZ5235C **Insured Vehicle No :** SKM5443Z

Date of Loss: 16/02/2020 Nature of Claim: TP Claim No: 5676081062SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLZ5235C</b>		
Make & Model:	BMW 540I, 3.0 SR LED NAV HUD RCP MSPORT (A)	Engine No:	19205266B58B30A
Reg. Date:	08/05/2018 (Man. Year: 2018)	Chassis No:	WBAJB32090G460050
Colour:	Blue	Odometer:	26222 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	245/35 R20
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,126.10	6,706.30	3,419.80	33.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,574.00	3,261.00	3,313.00	50.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,700.10</b>	<b>9,967.30</b>	<b>6,732.80</b>	<b>40.32</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,169.01</b>	<b>697.71</b>	<b>471.30</b>	<b>40.32</b>
<b>Nett Amount (S\$)</b>	<b>17,869.11</b>	<b>10,665.01</b>	<b>7,204.10</b>	<b>40.32</b>
<b>+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		385.20		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>11,052.21</b>		

#### INSPECTION

Date of Assignment: 24/03/2020

Date Inspected: 24/03/2020 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 4.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH SIDE PANEL ALUMINIUM	Repair	933.30 FS	*- FS
2	1		*VERTICAL CONNECTION RH	Not Necessary	19.90 FS	*- FS
3	1		*FRT BUMPER CARRIER	Not Necessary	726.70 FS	*- FS
4	1		*FRT BUMPER BOTTOM CARRIER	Not Necessary	399.70 FS	*- FS
5	1		*DAMPER KERB DESCENT	Not Necessary	5.45 FS	*- FS
6	1		*FRT BUMPER TOP IMPACT ABSORBER (M)	Not Necessary	63.00 FS	*- FS
7	1		*RH GRILLE AIR INLET OPEN	Not Necessary	83.15 FS	*- FS
8	1		*RH FOG LAMP SUPPORT (M)	Not Necessary	65.00 FS	*- FS
9	1		*RH FINISHER	Cut	76.25 FS	*76.25 FS
10	1		*FRT BUMPER BOTTOM IMPACT ABSORBER	Not Necessary	63.00 FS	*- FS
11	1		*FRT BUMPER PANEL PRIMED (M)	Broken	1,653.55 FS	*1,653.55 FS
12	1		*SET MOUNTING PDC/PMA SENSOR FRT	Not Necessary	69.35 FS	*- FS
13	1		*TRIM GRILLE FRT (I CAM)	Not Necessary	29.20 FS	*- FS
14	1		*COVERING CROSS MEMBER (ECE)	Not Necessary	33.65 FS	*- FS
15	1		*RH HEADLIGHT LED AHL HIGH(ICON LIG)	Broken	4,879.55 FS	*4,879.55 FS
16	1		*RH FOG LIGHT LED	Not Necessary	471.40 FS	*- FS
17	1		*ULTRASONIC SENSOR BLUESTONE WC2Y	Not Necessary	381.90 FS	*- FS
18	1		*DECOUPLING RING PDC TORQUE CONVERTER	Not Necessary	5.10 FS	*- FS
19	1		*RH BUMPER GUIDE	Broken	16.95 FS	*16.95 FS
20	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 10,126.10 6,706.30**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRONT BUMPER INCLUDING ATTACHMENT FRONT RIGHT FENDER AND DEFORMATION	New	3,825.00	850.00
2	PAINTING FRONT BUMPER AND FRONT RIGHT FENDER	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REPLACE RIGHT HEADLIGHT	New	531.00	531.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>6,574.00</b>	<b>3,261.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >