

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 7937J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER RH	DENTED	810.50	810.50
1	REAR DOOR RH	DENTED	898.40	898.40
1	REAR DOOR TRIM BOARD RH	CRACKED	746.50	746.50
1	REAR DOOR LOCK	JAMMED	530.70	401.90
1	REAR DOOR GLASS	SERVICEABLE	510.60	-
1	REAR DOOR GLAS REGULATOR	BENT	230.80	230.80
1	REAR POWER WINDOW MOTOR RH	SERVICEABLE	510.90	-
1	REAR POWER WINDOW SWITCH RH	SHORTED	140.60	140.60
1	REAR DOOR OUTER HANDLE RH LONG	TO REPAIR SEE LABOUR	108.30	-
1	REAR DOOR OUTER HANDLE RH SMALL	SERVICEABLE	60.70	-
1	CENTRE PILLAR RH	SERVICEABLE	550.60	-
1	REAR WINDOW GUIDE RH	SERVICEABLE	209.40	-
1	REAR WINDOW GUIDE GARNISH	BENT	170.50	170.50
1	REAR DOOR STICKER	MISSING	67.10	40.00
1	REAR DOOR RUBBER RH	CUT	240.30	240.30
1	SILL PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,446.48	-919.88
			4,339.42	2,759.62
<u>SPECIAL NETT ITEMS</u>				
1	SET RIMS COVER (SN)	SCRATCHED	300.00	110.00
1	SET TYRE (SN)	SERVICEABLE	80.00	-
			380.00	110.00
<u>LABOUR</u>				
	TO CHECK REAR ELECTRICAL WIRING.		50.00	30.00
	TO REMOVE AND REFIT REVERSE SENSOR.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT WINDSCREEN MOULDING.		120.00	60.00
	TO RESPRAY UNDERCOATING. }		100.00	50.00
	APPLY ANTI RUST ON AFFECTED AREAS. }		120.00	-
	SPRAY PAINTING ON AFFECTED AREAS.		1,500.00	800.00

Report Ref No. CS/LPC20003320/Qyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR DOOR OUTER HANDLE RH LONG AND SILL PANEL.		1,500.00	600.00
			3,470.00	1,540.00
GRAND TOTAL			8,189.42	4,409.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/LPC20003320/Qyd3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.