

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG20003327/KES3Q2

Date:

09/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070005504

Claimant Vehicle No : SLP2681U**Insured Vehicle No :**

SFE8991P

Date of Loss: 25/01/2020

Nature of Claim:

TP

Claim No:

9030031543SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP2681U**

Make & Model: TOYOTA AQUA HYBRID, 1.5 E S CVT (A)

Engine No: 1NZ8175910

Reg. Date: 30/05/2017 (Man. Year: 2017)

Chassis No: NHP106595204

Colour: Metallic Pearl White

Odometer: 183563 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R14

Rear Tyre Size:

175/65 R14

Front Left Side: SUNWIDE 6 mm

Rear Left Side:

KAPSEN 6 mm

Front Right Side: SUNWIDE 6 mm

Rear Right Side:

KAPSEN 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,184.25	1,125.52	58.73	4.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	420.00	200.00	32.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,804.25	1,545.52	258.73	14.34
Approved Total (Overridden) (S\$)		1,200.00		

(S\$)	1,804.25	1,200.00	604.25	33.49
+ GST 7.00/7.00% (S\$)	126.30	84.00	42.30	33.49
Nett Amount (S\$)	1,930.55	1,284.00	646.55	33.49
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
(S\$)		1,584.00		
Liable Amount (50.00%) (S\$)		792.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		794.00		

INSPECTION

Date of Assignment: 30/01/2020

Date Inspected: 30/01/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Optima Werkz Pte Ltd (HQ)
 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. L=ListItemDisc.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=920367&extid=332810&CFID=90181935&CFTOKEN=4dd9b8e91dbdfb17-0CC546B5-FF64-B82E-C73D8A7... 3/4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR & READJUST FRONT BUMPER & ETC	New	350.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER & ETC	New	220.00	200.00
3	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM	New	50.00	20.00
Gross Labour Cost (\$\$)			620.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >